## MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only:	Postmark (mai	l only)	Date Re	ceived -1名-2分	Al Number		
I. Type of Notification (O=Original R=Revised							
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R							
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):							
Bldg. Name: Storage Choice Pearl, LLC							
Address: 3528 US Highway 80							
<sub>City:</sub> Pearl	earl Sta			Zip: 39208			
Site Location: Rankin Square Shopping	Center		Tel: 228-617		-5956		
Building Size: 20,000 ft2		# of Floors: One		Age in Years:			
Present Use: Vacant		Prior Use: Retai	ail		()		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)							
OWNER NAME: Storage Choice Pearl, LLC							
Address: 3528 US Highway 80				,			
<sub>City:</sub> Pearl		State: MS		Zip: 39208			
Contact: Al Brumfield				Tel: 228-617-5956			
ASBESTOS REMOVAL CONTRACTOR: Alle	n Engineerir	ng and Science					
Address: 6360 I-55 North Suite 330							
<sub>City:</sub> Jackson	State: MS			<sub>Zip:</sub> 39211			
Contact: Richard Vick				Tel: 228-218-9866			
Certification Number: ABC-00010100			Expiration Date: 02/14/2023				
OTHER OPERATOR: N/A							
Address:							
City:	State:		Zip:		W		
Contact:		Tel:					
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes							
WAS ASBESTOS PRESENT? (Yes/No): Yes	Inspecti	tion Date: 09/23/2022					
Inspector: Christopher Harland Certification Number: ABI-00010676 Expiration Date: 02/15/2023  VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:							
12" x 12" Floor Tile - determined to be non-ACM - EPA 600/R-93/116 Polarized Light Microscopy Black Tile mastic - ACM - EPA 600/R-93 116 using Polarized Light Microscopy							
VII. QUANTITY OF RACM TO BE REMOVED:							
Pipes (LN FT):	Surface Area (S	<sub>SQ FT):</sub> 18,300 ft	2	Volume of Facility Co	mponents (CU FT):		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: N/A							
Category I: Category II:							
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 12/05/2022 Complete: 12/27/2022							
x. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 12/05/2022 Complete: 12/27/2022							

#### XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Non-ACM floor tiles will be removed then a mastic remover applied to the surface. Mastic remover and ACM will be collected, bagged and disposed at certified landfill.

# XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Work area has existing restricted access. Ingress and egress will be shrouded with plastic. During non-ACM floor tile removal, non-friable mastic will be wetted once exposed. Mastic remover manufacturer's specifications will be followed during

mastic will be wetted once exposed. Mastic remover manu	nacturer 3 specifica	LIONS WIII DE	i lollowed during	
XIII. WASTE TRANSPORTER #1			ii	
Name: Republic Services				
Address: 1716 N County Line Road				
<sub>City:</sub> Ridgeland	State: MS	Z	<sub>2ip:</sub> 39157	
Contact Person: Scott Johnson		1	el: 601-906-460	6
WASTE TRANSPORTER #2				
Name:				
Address:				
City:	State:	Z	ip:	
Contact Person:	8		el:	
XIV. WASTE DISPOSAL SITE	0.			
Name: Republic Services Little Dixie Landfill				
Address: 1716 N County Line Road				
City: Ridgeland	State: MS		Zip: 39157	
Contact Person: Scott Johnson		1	el: 601-906-460	6
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENC	CY. PLEASE IDENTI	IFY THE AG	ENCY BELOW:	
Name: N/A	,	Title:	10	
Authority:				
Date of Order (MM/DD/YY):	Date (	Ordered to Bo	egin (MM/DD/YY):	
XVI. FOR EMERGENCY RENOVATIONS:				
Date and Hour of Emergency (MM/DD/YY): N/A				
Description of the sudden unexpected event:	<u> </u>			
Explanation of how the event caused unsafe conditions or would	d cause equipment da	amage or an	unreasonable financ	cial burden:
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED I				FOUND OR PREVIOUSLY
NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLE Although none should be disturbed, if any is found or made				sor will assess the hazard and
determine, after consultation, what action is necessary before				
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PR	OVISIONS OF THIS	REGULATIO	ON (40 CFR PART 6	1. SUBPART M) WILL BE
ONSITE DURING THE DEMOLITION OR RENOVATION, AND THIS PERSON WILL BE AVAILABLE FOR INSPECTION DUR	<b>EVIDENCE THAT T</b>	HE REQUIR	ED TRAINING HAS	BEEN ACCOMPLISHED BY
Richard Sumrall Ri	chard Sumrall	Digitally signed by Date: 2022.11.16		11/16/2022
Type or Print Name	(Signature of Owner/O	perator)	35	(Date)
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRE		Disitally	· Dishard Cumpa"	
Richard Sumrall Ri	Richard Sumrall Digitally signed by Richard Sumrall Date: 2022.11.16 16:14:40 -06'00'			11/16/2022
Type or Print Name	(Signature of Owner/Operator)			(Date)



#### **EMSL** Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989

http://www.EMSL.com / batonrougelab@emsl.com

Attention: John Bourgeois

Allen Engineering and Science 6360 I-55 North Suite 330 Jackson, MS 39211

EMSL Order: 252204768 Customer ID: ECOS55 Customer PO: 22135.03

Project ID:

Phone: (601) 326-2821

Fax: (601) 936-4463


Received Date: 09/26/2022 10:10 AM

**Analysis Date:** 09/26/2022 Collected Date: 09/23/2022

Project: 22135.03/Storage Choice Pearl, LLC

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized **Light Microscopy**

			Non-As	<u>Asbestos</u>	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
SC-01-Floor Tile 252204768-0001	12x12 tan floor tile with yellow glue painted green	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
SC-01-Adhesive/Leveler	12x12 tan floor tile with yellow glue painted green	Gray/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
SC-02-Floor Tile 252204768-0002	12x12 tan floor tile with yellow glue painted purple	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
SC-02-Adhesive 252204768-0002A	12x12 tan floor tile with yellow glue painted purple	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
SC-03-Floor Tile 252204768-0003	12x12 tan floor tile with yellow glue	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
SC-03-Adhesive	12x12 tan floor tile with yellow glue		-		Insufficient Material
SC-04-Floor Tile 252204768-0004	12x12 tan floor tile with yellow glue	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
SC-04-Adhesive/Mastic	12x12 tan floor tile with yellow glue	Black/Yellow Non-Fibrous Homogeneous		97% Non-fibrous (Other)	3% Chrysotile
SC-05-Floor Tile	12x12 tan floor tile with yellow glue painted gray	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
SC-05-Adhesive/Mastic	12x12 tan floor tile with yellow glue painted gray				Positive Stop (Not Analyzed)
SC-06-Floor Tile	12x12 tan floor tile with yellow glue painted green	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
SC-06-Adhesive/Mastic	12x12 tan floor tile with yellow glue painted green				Positive Stop (Not Analyzed)



EMSL Order: 252204768
Customer ID: ECOS55
Customer PO: 22135.03

Project ID:

Analyst(s)

Victoria Atkins (9)

Jamie Laginess, Laboratory Operations Manager or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Baton Rouge, LA NVLAP Lab Code 200375-0, LELAP 01950, TX 300238

Initial report from: 09/30/2022 15:24:40



#### **EMSL** Analytical, Inc.

18369 Petroleum Drive Baton Rouge, LA 70809

Tel/Fax: (225) 755-1920 / (225) 755-1989 http://www.EMSL.com / batonrougelab@emsl.com **Customer PO:** 

Project ID:

Attention: John Bourgeois

Allen Engineering and Science 6360 I-55 North Suite 330 Jackson, MS 39211

Phone: (601) 326-2821

(601) 936-4463 Fax:

Received Date: 10/10/2022 10:15 AM

10/10/2022 Analysis Date: 10/06/2022 Collected Date:

EMSL Order: 252205117

Customer ID: ECOS55

Project: Storage Choice Pearl, LLC 22135.03

#### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized **Light Microscopy**

Sample Description			<u>Asbestos</u>			
	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
SC-07-Floor Tile 252205117-0001	12x12 tan floor tile w/black glue	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected	
SC-07-Mastic 252205117-0001A	12x12 tan floor tile w/black glue	Black Non-Fibrous Homogeneous		94% Non-fibrous (Other)	6% Chrysotile	
SC-08-Floor Tile	12x12 tan floor tile w/black glue painted green	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected	
SC-08-Mastic 252205117-0002A	12x12 tan floor tile w/black glue painted green	Black Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile	
SC-09-Floor Tile 252205117-0003	12x12 tan floor tile w/black glue painted green	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected	
SC-09-Mastic 252205117-0003A	12x12 tan floor tile w/black glue painted green	Black Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile	
Sc-10-Floor Tile 252205117-0004	12x12 tan floor tile w/black glue	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected	
Sc-10-Mastic 252205117-0004A	12x12 tan floor tile w/black glue	Tan/Black Non-Fibrous Heterogeneous		94% Non-fibrous (Other)	6% Chrysotile	

Analyst(s)

Jamie Laginess (8)

Jamie Laginess, Laboratory Operations Manager or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request

Samples analyzed by EMSL Analytical, Inc. Baton Rouge, LA NVLAP Lab Code 200375-0, LELAP 01950, TX 300238

Initial report from: 10/10/2022 14:19:48

