Emerg.

## MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: Postmark (n		te Reçeived Al Number			
XEmail ☐Mail ☐Hand Delivery		te Received Al Number			
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):					
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):					
III. FACILITY DESCRIPTION (Include building name, number	r and floor or room number)	PORTON CONTRACTOR AND			
Bldg. Name: Cooper Tire & Rubber Company		(min staff (c2) link must			
Address: 1804 S. Green Street					
<sub>City:</sub> Tupelo	State: MS	Zip: 38804			
te Location: Site Wide		Tel: 662.841.7520			
Building Size: 300,000 SF	# of Floors: 1	Age in Years: 59			
Present Use: Tire Manufacturing	Prior Use: Tire Manufacturing				
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)					
OWNER NAME: Cooper Tire & Rubber Cor	mpany	AM de			
Address: 1804 S. Green Street					
		zip: 38804			
Contact: Craig Busenbark  ASBESTOS REMOVAL CONTRACTOR: Snyder Environmental & Construction, LLC					
Address: 7705 Northshore Place	Timental & Constructi	011, LLC			
	ΛP	72110			
City: North Little Rock	State: AR	Zip: 72118			
Contact: Andrew Ables		Tel: 601-559-2185			
Certification Number: 23265-SG- ABC - 0000	9502 Ex	piration Date: May 29, 2023 09 30 2023			
OTHER OPERATOR: NA	Profession Co.	2 2 3 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Address: NA		A CONTRACTOR OF THE PROPERTY O			
City: NA	State: NA	zip: NA			
Contact: NA Tel: NA					
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF					
WAS ASBESTOS PRESENT? (Yes/No): Yes		pection Date: 4/6/2023			
Inspector: Thomas Ahern Certification Number: ABI00008685 Expiration Date: 03/2024					
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Transite Panels and Built-Up Roofing Materials  PINA					
Transite Panels and Built-Up Roofing Materials					
VII. QUANTITY OF RACM TO BE REMOVED:	10.000 00.000 07	75 15 11 11 11 11 11 11 11 11 11 11 11 11			
Арргох.		of Damaged Built-Up roofing Materials			
Pipes (LN FT): NA Surface Area	es (LN FT): NA Surface Area (SQ FT): 10,000 - 20,000 Volume of Facility Components (CU FT): NA				
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMO					
Category I: 150,000 SF of built-up roofing materials  Category II: Approx. 2,000 SF Transite Panels					
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/	YY) Start: 04/15/23	Complete: 05/13/23			
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY		Complete: N/A			

Decontamination of building interior & equipment, clean-up of damaged built-up roofing, Abatement of built-up roofing and transite panels.						
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:						
Materials will be wetted before, during and after abatement, properly packaged, labeled and transported to a class 1 landfill for disposal.  Interior Clean-up and decontamination to be done in NPE, built-up roofing and transite panel abatement to be done in Regulated Work area.						
XIII. WASTE TRANSPORTER #1						
Name: RMI (Roy Moffit Inc.)						
Address: 17302 House & Hahl Road #211						
City: Cypress	State: TX		Zip: 77433			
Contact Person: Peyton Hughes	s		Tel: 281.205.7577 - 832.392.8442			
WASTE TRANSPORTER #2 NA						
Name: NA						
Address: NA						
City: NA	State:		Zip:			
Contact Person: NA			Tel:			
XIV. WASTE DISPOSAL SITE						
Name: Waste Management Prarrie Bluff Security Landfill						
Address: 1649 Highway 15						
City: Houston	State: MS		Zip: 38851			
Contact Person: Anna Alford			Tel: 662.456.9560			
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:						
Name: NA Title: NA						
Authority: NA						
Date of Order (MM/DD/YY): NA						
XVI. FOR EMERGENCY RENOVATIONS:						
Date and Hour of Emergency (MM/DD/YY): 04/10/23 @ 2:00pm						
Description of the sudden unexpected event:						
Tornado						
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:  Substantial damage to asbestos built-up roofing materials, ripped holes in roof deck exposing the building interior and contaminating areas with damaged roofing debris.						
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:						
Wet the unexpected, make area safe and notify DEQ						
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.						
Justin Dixon - President	Justin Dixe		o4/17/23			
Type or Print Name (Signature of Owner/Operator) (Date)						
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:						
Justin Dixon - President	(Signature of Owner/Operator)		04/17/23 (Date)			
Type or Print Name (Signature of Owner/Operator) (Date)						