MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: ⊠Email □Mail	☐ Hand Delivery	Postmark (mail o	only)	Date Re	eceived 07-13-2023	Al Number 81569				
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): O										
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R										
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): COLONIAL PIPELINE COMPANY										
Bldg. Name: CPC ROW NEAR MILE MARKER 328.3 ON LINE 2										
Address: CPC ROW CROSSING OF HWY 98										
City: MCCOMB			State: MS		zip: 39648					
Site Location: N/A					Tel: N/A					
Building Size: N/A		# of Floors: N/A			Age in Years: N/A					
Present Use: N/A	Present Use: N/A		Prior Use: N/A		Alaj gamek					
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)										
OWNER NAME: COLONIAL PIPELINE COMPANY										
Address: PO BOX 1298										
City: COLLINS			State: MS		Zip: 39428					
Contact: PHILIP HUX					Tel: 601-765-9180					
ASBESTOS REMOVAL CONTRACTOR: DDS										
Address: 87 PICKERING ROAD										
City: COLLINS			State: MS		_{Zip:} 39428					
Contact: WARREN KING					Tel: 601-433-4087					
Certification Number:				Expirati	piration Date:					
OTHER OPERATOR: N/A										
Address: N/A		Autor III	14 - AT			The second secon				
City: N/A					z _{ip:} N/A					
Contact: N/A					Tel: N/A					
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): NO										
WAS ASBESTOS PRES	ENT? (Yes/No): ASS	Inspecti	pection Date: N/A							
Inspector: N/A Certification Number: N/A					Expiration Date: N/A					
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:										
ASSUMED COATING										
विकास करण हो। स्टेस्टर अन्यक्षण कारणव्या । १९७९ १ । वार्ताच्या स्टेस्टर अन्य विकास वर्षण विकास होता है। 										
VII. QUANTITY OF RACM TO BE REMOVED:										
- 423	STORY RANGERS			Rent C						
Pipes (LN FT): 423 Surface Area (SQ FT): -					Volume of Facility Components (CU FT): -					
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: Category I: N/A Category II: N/A										
	10/30/2023									
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 08/01/2023 X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: Complete: 10/30/2023										
x. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: Complete:										

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:										
Adequately wet, wrap in shrink wrap, hit to disbond, place in wet labled double bag, twist and seal										
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:										
Strip and Removal, Containment, Wet Method, Double Bagging										
XIII. WASTE TRANSPORTER #1										
Name: KENT ENERGY										
Address: 1555 BEAULIEU LANE										
City: PORT ALLEN	State: LA		_{Zip:} 70767							
Contact Person: JERRY HORNER			Tel: 225-718-0993							
WASTE TRANSPORTER #2										
Name: N/A										
Address: N/A										
City: N/A	State: N/A		zip: N/A							
Contact Person: N/A			Tel: N/A	'A						
XIV. WASTE DISPOSAL SITE										
Name: WASTE MANAGEMENT WOODSIDE										
Address: 29340 WOODSIDE DRIVE										
City: WALKER	State: LA		z _{ip:} 70785							
Contact Person: N/A			Tel: N/A							
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:										
Name: N/A Title: N/A										
Authority: N/A										
Date of Order (MM/DD/YY): N/A Date Ordered to Begin (MM/DD/YY): N/A										
XVI. FOR EMERGENCY RENOVATIONS: N/A										
Date and Hour of Emergency (MM/DD/YY): N/A										
Description of the sudden unexpected event:										
N/A										
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:										
N/A										
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:										
Stop work and reevaluate pipe coating removal method to alleviate making friable coating nonfriable.										
			_	-						
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.										
PHILIP HUX	Philip Hux			7/13/2023						
Type or Print Name	(Signature of Owner/Operator)			(Date)						
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT: PHILIP HUX Philip Hux Digitally signed by Philip Hux Date: 2023 07.13 13:27:35-0500' 7/13/2023										
Type or Print Name				(Date)						
13pe or Fink Name	(Giginature of C	omiciroperatur)		(Date)						