

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 07-09-2024	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): O				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: Down Town Old Vacant Store				
Address: 502 Main St 502 S Main St				
City: Mount Olive		State: MS		Zip: 39119
Site Location: entire store space except for two smaller rooms				Tel: 601.382.0837
Building Size: 2100 sq ft		# of Floors: 1		Age in Years: 60 +
Present Use: Vacant		Prior Use: Store		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Melissa Ducksworth				
Address: 407 Sheppard St.				
City: Mount Olive		State: MS		Zip: 39119
Contact: Owner				Tel: 601.382.0837
ASBESTOS REMOVAL CONTRACTOR: John Lee				
Address: 1728 Mount Zion Rd.				
City: Magee		State: MS		Zip: 39111
Contact: Contractor				Tel: 601.519.8281
Certification Number: ABC-00003364			Expiration Date: 05/07/2025	
OTHER OPERATOR: NA				
Address:				
City:		State:		Zip:
Contact:				Tel:
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): No- Assumed				
WAS ASBESTOS PRESENT? (Yes/No):			Inspection Date:	
Inspector:		Certification Number:		Expiration Date:
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Floor tile and floor tile adhesive is assumed to be ACM due to buildings age.				
VII. QUANTITY OF RACM TO BE REMOVED:				
Pipes (LN FT):		Surface Area (SQ FT):		Volume of Facility Components (CU FT):
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I: 2100 sq ft			Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 07/23/2024 Complete: 07/29/2024				
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 08/04/2024 Complete: 08/28/2024				

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Use wet methods such as misting with water to suppress dust before any disturbance of ACMs. Minimize breakage of ACMs during removal to prevent the release of asbestos fibers into the air. Carefully lift and remove asbestos-containing floor tiles intact, if possible, to minimize the release of fibers.

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Establish clearly marked exclusion zones around the renovation area to limit access to authorized personnel only. Use physical barriers such as plastic sheeting and warning signs to prevent unauthorized entry. Utilize wet methods to suppress dust during all phases of work involving ACMs. Mist ACMs with water before disturbance to minimize the release of asbestos fibers into the air.

XIII. WASTE TRANSPORTER #1

Name: John Lee III

Address: 1728 Mount Zion Rd

City: Magee

State: MS

Zip: 39111

Contact Person: Supervisor

Tel: 601.808.9266

WASTE TRANSPORTER #2

Name: Xavier Keller

Address: 101 Eula Mae Dr.

City: Magee

State: MS

Zip: 39111

Contact Person: Supervisor

Tel: 601.398.5296

XIV. WASTE DISPOSAL SITE

Name: WM Clear View Landfill

Address: 2253 Mudline Rd

City: Lake

State: MS

Zip: 39092

Contact Person: Representative

Tel: 866.909.4458

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:

Stop all work in the affected area as soon as unexpected asbestos is discovered or nonfriable asbestos becomes crumbled, pulverized, or reduced to powder. Establish an exclusion zone around the affected area using physical barriers (e.g., plastic sheeting) and warning signs to prevent access. Document the incident thoroughly, including photographs, written records of actions taken, and notifications made. Notify MDEQ

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

John Lee

Type or Print Name

John Lee
(Signature of Owner/Operator)

07/09/2024

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

John Lee

Type or Print Name

John Lee
(Signature of Owner/Operator)

07/09/2024

(Date)