208941

Mississippi Office of Pollution Control Lead-Based Paint Abatement/Renovation Notification



MDEQ U Email		Postmark (mail only)	Date Received 4/29/2025	AI Number	
Please ch	eck all applicable boxes for	Renovation Date of the type of Notification:	Original Revision [n: 1969 Cancellation	
I.	PROJECT/SITE INFORMATION Target Housing: Child-Occupied Facility: 303 Greenbrier Drive				
	Physical Address Project Site: 202 Greenbriar Drive City: Vicksburg State: MS Zip Code: 39180 County: Warren				
	-	ed/Renovated in the Building		(y:	
II.	BUILDING OWNER IN Mr./Mrs.: Kretonia Jones				
	Address of Owner: 202 Green Telephone Number: (601)		Vicksburg S	tate: MS ZIP: 39180	
III.	I. ABATEMENT/RENOVATION CONTRACTOR INFORMATION Name of Certified Lead Abatement/Renovator Firm: Brian Wraight Firm Certification Number: NBF-00000927 Telephone Number: (601) 850-7154 Exp. Date: 08/31/202 Address of Certified Firm: 121 David Henderson Rd				
		State: MS	S Z	ip Code: 39145	
IV.	INSPECTION INFORMATION Name of Renovator/Inspector/Risk Assessor Conducting Inspection: Brian Wraight Certification Number: PBR-00011222 Exp. Date: 07/21/2025 Date Inspection Conducted: Test Method Used & Manufacturer of Testing Equipment:				
	For Paint Chip Analysis, Name of Laboratory: Certification Number:				
v.	GENERAL CONTRACTOR (Other) Name of Firm: Windows USA Firm Mailing Address: PO Box 222 Royal, AR 71968				
	Contact Person: Christine		Telephone Number:	(501) 760-0292	
VI.	PROJECT DATES Lead Project Start: 05	<u>/14 /2025</u> L	ead Project Stop: 05	/14 /2025	
	Abatement/Renovation t	o be done during what time	? ■ Day (5 a.m. – 5 p.r ■Night (8 p.m. – 5 a		
VII.		OCEDURES TO BE USE	` <u> </u>		
	 Wet Sanding Containment Other – Explain	Component Removal Strip and Removal	☐ Heat Gun ☐ Negative Air	Encapsulation Enclosure	

VIII. DESCRIPTION OF RENOVATION ACTIVITIES TO BE COMPLETED (INCLUDING COMPONENTS TO BE AFFECTED)

Retro Fit Pocket Replacement of Existing Windows with New Vinyl Windows

Name: Brian Wraight Full Mailing Address: 121 David Henderson Rd City: Pelahatchie Contact: Brian Wraight Telephone Number: (801) 850-7154 X. WASTE LEAD DISPOSAL SITE Site Name: Mt. Helm Landrill Physical Address: 495 Mt Helm Rd Full Mailing Address: 495 Mt Helm Rd City: Brandon State: MS Zip Code: 39047 XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name: Physical Address: City: State: Zip Code: Contact Person: Telephone Number: (20) NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landrill. XII. ABATEMENT A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours. XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature State: MS Zip Code: 39047 Zip Cod	IX.	WASTE TRANSPORTER						
City: Pelahatchie State: MS Zip Code: 39145 Contact: Brian Wraight Telephone Number: (601) 850-7154 X. WASTE LEAD DISPOSAL SITE Site Name: Mt. Helm Landrill Physical Address: 495 Mt Helm Rd Full Mailing Address: 495 Mt Helm Rd City: Brandon State: MS Zip Code: 39047 XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name: Physical Address: Full Mailing Address: City: State: Zip Code: Contact Person: Telephone Number: Display State: State		Name: Brian Wraight						
Contact: Brian Wraight Telephone Number: (601) 850-7154 X. WASTE LEAD DISPOSAL SITE Site Name: Mt. Helm Landrill Physical Address: 495 Mt Helm Rd Full Mailing Address: 495 Mt Helm Rd City: Brandon State: MS Zip Code: 39047 XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name: Physical Address: Full Mailing Address: State: Zip Code: Contact Person: Telephone Number: () NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill. XII. ABATEMENT A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours. XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature State: MS Zip Code: 39145 Contact information for return mall or questions concerning the information on this Notice Mailing Address: 121 David Henderson Rd City: Pelahatchie State: MS Zip Code: 39145 Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com		Full Mailing Address: 121 David Henderson Rd						
X. WASTE LEAD DISPOSAL SITE Site Name: Mt. Helm Landrill Physical Address: 495 Mt Helm Rd Full Mailing Address: 495 Mt Helm Rd City: Brandon State: MS Zip Code: 39047 XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name: Physical Address: Full Mailing Address: City: State: Zip Code: Contact Person: Telephone Number: Display to an authorized Rubbish Site, or to a permitted sanitary landfill. XII. ABATEMENT A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours. XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature Signature State: MS Zip Code: 39145 Contact information for return mail or questions concerning the information on this Notice Mailing Address: 121 David Henderson Rd City: Pelahatchie Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification.		City: Pelahatchie	State: MS	Zip Code: 39145				
XI. WASTE LEAD DISPOSAL SITE Site Name: Mt. Helm Landrill Physical Address: 495 Mt Helm Rd Full Mailing Address: 495 Mt Helm Rd City: Brandon State: MS Zip Code: 39047 XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name: Physical Address:		Contact: Brian Wraight	Telephone Number	: (601) 850-7154				
Physical Address: 495 Mt Helm Rd Full Mailing Address: 495 Mt Helm Rd City: Brandon State: MS Zip Code: 39047 XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name: Physical Address: State: State: Zip Code: Code: Code: State: St	X.							
Full Mailing Address: 495 Mt Helm Rd City: Brandon State: MS Zip Code: 39047 XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name:		Site Name: Mt. Helm Landrill						
XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name: Physical Address: Full Mailing Address: City: State: Contact Person: NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill. XII. ABATEMENT A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours. XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com		Physical Address: 495 Mt Helm Rd	, , , , , , , , , , , , , , , , , , , ,					
XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name: Physical Address: Full Mailing Address: City: State: Contact Person: NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill. XII. ABATEMENT A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours. XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com		Full Mailing Address: 495 Mt Helm Rd	1)					
Site Name: Physical Address: Full Mailing Address: City: Contact Person: NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill. XII. ABATEMENT A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours. XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality			State: MS	Zip Code: 39047				
Site Name: Physical Address: Full Mailing Address: City: State: Zip Code: Contact Person: NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill. XII. ABATEMENT A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours. XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature Signature Signature Signature State: MS Zip Code: 39145 Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality	XI.							
Physical Address: Full Mailing Address: City:								
Full Mailing Address: City: State: Zip Code: Contact Person: NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill. XII. ABATEMENT A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours. XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature Signature Signature Signature State: MS Zip Code: 39145 Contact information for return mail or questions concerning the information on this Notice Mailing Address: 121 David Henderson Rd City: Pelahatchie State: MS Zip Code: 39145 Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com		Physical Address:						
City:		Full Mailing Address:						
Contact Person: NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill. XII. ABATEMENT A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours. XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature Signature State: MS Zip Code: 39145 Contact: Brian Wraight Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality		City:	State:	Zip Code:				
A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours. XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature Signature Signature State: MS Zip Code: 39145 Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality		Contact Person:	Telephone Number	r: ()				
A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours. XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature Signature Signature State: MS Zip Code: 39145 Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality		NOTE: All debris (other than lead) should	go to an authorized Rubbis	sh Site, or to a permitted sanitary landfill.				
during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours. XIII. RENOVATION A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature Signature Signature State: MS Zip Code: 39145 Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality	XII.							
A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature Signature Signature Contact information for return mail or questions concerning the information on this Notice Mailing Address: 121 David Henderson Rd City: Pelahatchie State: MS Zip Code: 39145 Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality		during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and						
are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted. XIV. CERTIFICATION OF ACCURACY I certify that all of the above information is correct. Print Brian Wraight Signature Contact information for return mail or questions concerning the information on this Notice Mailing Address: 121 David Henderson Rd City: Pelahatchie State: MS Zip Code: 39145 Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality	XIII	RENOVATION						
I certify that all of the above information is correct. Print Brian Wraight Signature Mailing Address: 121 David Henderson Rd City: Pelahatchie State: State: State: Signature Signature Mississippi Department of Environmental Quality		performed. The certified renovator must reg	tainment is being establishe ularly direct work being pe	d, and while required work area cleaning is				
Print Brian Wraight Signature S	XIV.	CERTIFICATION OF ACCURACY						
Contact information for return mail or questions concerning the information on this Notice Mailing Address: 121 David Henderson Rd City: Pelahatchie State: MS Zip Code: 39145 Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality		I certify that all of the above information is correct						
Mailing Address: 121 David Henderson Rd City: Pelahatchie State: MS Zip Code: 39145 Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality		Print_Brian Wraight	Signature DUM	Wraight Date 4.29.25				
City: Pelahatchie State: MS Zip Code: 39145 Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality		Contact information for return mail or questions concerning the information on this Notice						
Contact: Brian Wraight Telephone Number: (601) 850-7154 Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality								
Email: brian.wraight@windowsusa.com Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality			State: M	S Zip Code: 39145				
Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification. MAIL TO: Mississippi Department of Environmental Quality			Telephone N	umber: (601) 850-7154				
MAIL TO: Mississippi Department of Environmental Quality		Email: brian.wraight@windowsusa.com						
MAIL TO: Mississippi Department of Environmental Quality	Refer	to fee schedule to calculate required notif	fication fee. Notification	fee must be submitted with notification.				
Load Notifications								

P.O. Box 2261, Jackson, MS 39225