

PI

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: ☒ Email ☐ Mail ☐ Hand Delivery		Postmark (mail only)		Date Received: 6/15/2025		Alt Number	
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):				O = ORIGINAL			
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):				R = RENOVATIONS			
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):							
Bldg. Name: ANGELA KINGET BARBER SHOP							
Address: 420 N. DAVIS STREET							
City: CLEVELAND		State: MS		Zip: 38732			
Site Location: 420 N. DAVIS ST., CLEVELAND, MS 38732				Tel: 662-846-1924			
Building Size: 1,700 sq.		# of Floors: 1		Age in Years: 60 + -			
Present Use: VACANT		Prior Use: BARBER SHOP					
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)							
OWNER NAME: SUTEP & ROSALG KINGET							
Address: 35 HORSESHOE DR.							
City: MERIGOLD		State: MS		Zip: 38759			
Contact: ANGELA KINGET				Tel: 662-313-0592			
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC.							
Address: P.O. BOX 133							
City: DELTA CITY		State: MS		Zip: 39061			
Contact: JIMMY BELL				Tel: 662-820-2124			
Certification Number: ABC-60001282				Expiration Date: 12/15/25			
OTHER OPERATOR: BLOCKETT CONSTRUCTION, LLC							
Address: P.O. BOX 4020							
City: CLEVELAND		State: MS		Zip: 38732			
Contact: CYNTHIA BLOCKETT				Tel: 662-846-1924			
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES							
WAS ASBESTOS PRESENT? (Yes/No): YES				Inspection Date: 12/15/23			
Inspector: CYNTHIA BLOCKETT		Certification Number: ABI-60001391		Expiration Date: 9/19/24			
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: SAMPLES WERE TAKEN FROM: LINOLEUM FLOORING, MASTIC, WINDOW CAULKING, WHITE PAINT, SHEETROCK WALLS, CEILING TILE, ATTIC INSULATION, DRYWALL, DRYWALL-JOINT COMPOUND, RED PAINT. THE SAMPLES WERE COLLECTED AND SHIPPED TO EHS LAB SERVICES LLC AND ANALYZED USING THE PLM METHOD. ASBESTOS WERE FOUND IN THE LINOLEUM FLOORING/BLACK-TAN VINYL TILE UNDERNEATH LINOLEUM FLOORING.							
VII. QUANTITY OF RACM TO BE REMOVED: 600 sq. of linoleum flooring Top Layer and Tan/Black Vinyl flooring UNDERNEATH.							
Pipes (LN FT): 0		Surface Area (SQ FT): 600 sq.		Volume of Facility Components (CU FT): 0			
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 0							
Category I: ✓				Category II:			
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 6/27/25				Complete: 7/2/25			
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 7/5/25				Complete: 8/25/25			

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:
 Wet Method, NEQ-Air, Containment, Air Monitoring

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: PREP SITE: 6 mil poly over doors/windows, Air Condition - units. Wet and Remove Linoleum Top Layer, Bag, Wet and Remove Vinyl Flooring Bottom Layer, Bag, Remove Mastic, Double Bag, Cleanup, Await Air Clearance

XIII. WASTE TRANSPORTER #1

Name: BELL ENVIRONMENTAL SERVICES, LLC

Address: P.O. BOX 133

City: DELTA City

State: MS

Zip: 39061

Contact Person: Jimmy Bell

Tel: 662-820-2124

WASTE TRANSPORTER #2 N/A

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: Big River Landfill (Republic Services)

Address: 52 LANDFILL RD.

City: LELAND

State: MS

Zip: 38756

Contact Person: WILLIE CHRISTEN

Tel: 662-332-7927

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: N/A

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

Stop work, Remain under containment, Contact owner and MDEQ of -
 Change, Follow MDEQ Direction

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell

Type or Print Name

(Signature of Owner/Operator)

6/23/25

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Jimmy Bell

Type or Print Name

(Signature of Owner/Operator)

6/23/25

(Date)