

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: ☑Email □Mail □Hand Delivery	Postmark (mail only)	Date R	eceived 3-23	Al Number				
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): Original								
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation								
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Northside Plaza - 1 Floor Janitor Closet, Restrooms and Breakroom								
Bldg. Name: Regions Bank - Northside Plaza								
Address: 113 Northside Plaza								
City: Newton	State: MS	Jagger	Zip: 39345	medical needs				
Site Location: 113 Northside Plaza			Tel: 205-223-8450					
Building Size: 1,200	# of Floors	# of Floors: 1		Age in Years: 46				
Present Use: Bank Branch Prior Use: Bank Branch			scal/ instance of the					
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)								
OWNER NAME: Regions Financial Corporation								
Address: 250 Riverchase Parkway								
City: Birmingham State: AL			zip: 35224					
Contact: Doug Stephen			Tel: 205-223-8450					
ASBESTOS REMOVAL CONTRACTOR: Lakeshore Environmental Contractors LLC								
Address: 5513 Eastcliff Industrial Loop								
City: Birmingham State: AL			zip: 35210					
Contact: Aaron Murphree			Tel: 205-288-7049					
Certification Number: ABC-00001844			Expiration Date: 04/24/2023					
OTHER OPERATOR:								
Address:								
City: State:			Zip:					
Contact:			Tel:					
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes								
			tion Date: 09/23/2010					
Inspector: Maxwell T. Anderson	Certification Number: A	BI-00001455	Expiration	Expiration Date: 05/27/2011				
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:								
PLM								
VIL QUANTITY OF RACM TO BE REMOVED:								
VII. QUANTITY OF RACM TO BE REMOVED: Resilient Sheet Flooring								
Pipes (LN FT):	Surface Area (SQ FT): 275 Volume of Facility Components (CU FT):							
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:								
Category II: Category II: 03/14/2022 74/7/2								
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 03/14/2023 3/17 23 Complete: 03/14/2023 3/17/23								
x. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 03/14/2023 317/23 Complete: 03/14/2023 317/23								

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:								
Regulated Area, Decon, 6 Mil Poly, Disposal Coveralls, Respirators, HEPA Vaccum, Amended Water Applied During Removal.								
XII, DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:								
Regulated Area, Deconm 6 Mil Ploy, Disposal Coveralls, Respirators, HEPA Vaccum, Amended Water Applied During Removal.								
XIII. WASTE TRANSPORTER #1								
Name: Lakeshore Environmental Contractors, LLC								
Address: 5513 Eastcliff Industrial Loop								
_{City:} Birmingham	State: AL		_{Zip:} 35210					
Contact Person: Aaron Murphree	Tel: 205-288-7			9				
WASTE TRANSPORTER #2								
Name: Independent Waste								
Address: 112 24th Street N								
City: Birmingham	State: AL		Zip: 35203					
Contact Person: Jack Louis			Tel: 205-902-9804	4				
XIV. WASTE DISPOSAL SITE								
Name: Big Sky Environmental								
Address: 5100 Flat Top Road								
City: Adamsville	State: AL		Zip: 35005	Zip: 35005				
Contact Person:			Tel: 205-743-008	·el: 205-743-0080				
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:								
Name:	Title:							
Authority:								
Date of Order (MM/DD/YY): Date Ordered to Begin (MM/DD/YY):								
XVI. FOR EMERGENCY RENOVATIONS:								
Date and Hour of Emergency (MM/DD/YY):								
Description of the sudden unexpected event:								
Stop Work, Contain Area, Notify Mississippi MDEQ & Revise Notification								
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:								
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:								
Northable as 153103 maierial becomes crumbled, pulserized, or reduced 10 powder.								
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE CNSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.								
H	aron Murphi		ned by Aeron Marphree 00.01 13:08:17 -0500	03/01/2023				
Type or Print Name	(Signature of C	Owner/Operator)		(Date)				
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORR Agron Murphree	ECT: aron Murph	il Tee Digitally sig Date: 2021.	sned by Assan Murphree L03.01 13:08:30 -06'00'	03/01/2023				
Type or Print Name	(Signature of Owner/Operator)			(Dats)				

}