job-193478

Mississippi Office of Pollution Control Lead-Based Paint Abatement/Renovation Notification



MDEQ U	se Only: Mail Hand Delivery	Postmark (mail only)	Date Received	AI Number
Please ch	Type: Abatement eck all applicable boxes for the	he type of Notification: 🛚	Original Revision	on: 1961 Cancellation Emergency
I.	PROJECT/SITE INFORM Target Housing: Child-Occupied Facility: Physical Address Project Sit City: Jackson Number of Units to be Abated	State: MS Zi		nty: Hinds
II.	Mr./Mrs.: Wax Tay vi. Address of Owner: 1308 Telephone Number: (1662) 7	ous Hullan Winterview D City	: Jackson	State: NS ZIP: 3921
ш	Address of Certified Firm:	batement/Renovator F PBR-00010175 Telepho	irm: Gary Ogle one Number:(⁶⁰¹) 862-	8033 Exp. Date: 07/06/2022 Zip Code: 39047
IV.	INSPECTION INFORMA Name of Renovator/Inspectification Number: Test Method Used & Manu For Paint Chip Analysis, N	ctor/Risk Assessor Con Exp. Date:_ facturer of Testing Equip	Date Insp	ection Conducted:
v.	GENERAL CONTRACT Name of Firm: Windows US Firm Mailing Address: PO Contact Person: Mia Walsh	SA	8 Telephone Number	r:(501)760-0309
VI.	PROJECT DATES Lead Project Start: 09 / Abatement/Renovation to			
VII.	DESCRIPTION OF PRO Wet Sanding Containment Other - Explain	CEDURES TO BE US Component Removal Strip and Removal	ED (CHECK ALL TI Heat Gun Negative Air	HAT APPLY) Encapsulation Enclosure

VIII. DESCRIPTION OF RENOVATION ACTIVITIES TO BE COMPLETED (INCLUDING COMPONENTS TO BE AFFECTED)

Retro Fit Pocket Replacement of Existing Windows with New Vinyl Windows

Full Mailing Address: 126 Cape	Charles		
City: Brandon	State: MS	Zip C	ode: 39047
Contact: Gary Ogle	Telephone Number	r: (601) 862	2-8033
WASTE LEAD DISPOSAL SI Site Name:			
Physical Address:	AC MANY		作品の (miles) (miles) (k) (miles) (
Full Mailing Address:			
City:	State:	Zip C	ode:
DISPOSAL SITE FOR DEBRI		1640 HE 147 HE	
Physical Address:			
Full Mailing Address:			
City:	State:	Zip C	ode:
City:	State:	Zip C	ode:
City: Contact Person: NOTE: All debris (other than lead) ABATEMENT	State: Telephone Number should go to an authorized Rubb	Zip C er: () sish Site, or t	o a permitted sanitary landfil
City: Contact Person: NOTE: All debris (other than lead)	State: Telephone Number should go to an authorized Rubbreach abatement project and shall nd clearance of work areas. At all isor shall be onsite or available by	Zip Corrections Zip Correction	to a permitted sanitary landfill ring all work site preparation when abatement activities are
City: Contact Person: NOTE: All debris (other than lead) ABATEMENT A certified supervisor is required for during the post-abatement cleanup a being conducted, the certified superv	State: Telephone Number should go to an authorized Rubbreach abatement project and shall nd clearance of work areas. At all isor shall be onsite or available by	Zip Corrections Zip Correction	to a permitted sanitary landfill ring all work site preparation when abatement activities are
City: Contact Person: NOTE: All debris (other than lead) ABATEMENT A certified supervisor is required for during the post-abatement cleanup a being conducted, the certified supervable to be present at the work site in RENOVATION A certified renovator is required for are posted, while the required work a performed. The certified renovator is available either onsite or by telephone	State: Telephone Number should go to an authorized Rubber each abatement project and shall not clearance of work areas. At all isor shall be onsite or available by no more than 2 hours. each renovation project and shall area containment is being establishmust regularly direct work being pare at all times renovations are being	Zip Construction Zip Co	o a permitted sanitary landfill ring all work site preparation when abatement activities are lager, or answering service, and present when the required signs required work area cleaning to other individuals and must be
City: Contact Person: NOTE: All debris (other than lead) ABATEMENT A certified supervisor is required for during the post-abatement cleanup a being conducted, the certified supervable to be present at the work site in RENOVATION A certified renovator is required for are posted, while the required work a performed. The certified renovator is available either onsite or by telephon. CERTIFICATION OF ACCUS	State: Telephone Number should go to an authorized Rubbre each abatement project and shall not clearance of work areas. At all isor shall be onsite or available by no more than 2 hours. each renovation project and shall area containment is being establishmust regularly direct work being part at all times renovations are being RACY	Zip Construction Zip Co	o a permitted sanitary landfill ring all work site preparation when abatement activities are lager, or answering service, and present when the required signs required work area cleaning to other individuals and must be
City: Contact Person: NOTE: All debris (other than lead) ABATEMENT A certified supervisor is required for during the post-abatement cleanup a being conducted, the certified supervable to be present at the work site in RENOVATION A certified renovator is required for are posted, while the required work a performed. The certified renovator is available either onsite or by telephon. CERTIFICATION OF ACCULT.	State: Telephone Number should go to an authorized Rubbre each abatement project and shall nd clearance of work areas. At all isor shall be onsite or available by no more than 2 hours. each renovation project and shall area containment is being establishmust regularly direct work being part at all times renovations are being RACY	Zip Consiste dural other times telephone, pube physically ned, and while performed by g conducted.	ring all work site preparation when abatement activities are tager, or answering service, and present when the required signs required work area cleaning to other individuals and must be
City: Contact Person: NOTE: All debris (other than lead) ABATEMENT A certified supervisor is required for during the post-abatement cleanup a being conducted, the certified supervable to be present at the work site in RENOVATION A certified renovator is required for are posted, while the required work a performed. The certified renovator is available either onsite or by telephon. CERTIFICATION OF ACCUIT CERTIFICATION	State: Telephone Number should go to an authorized Rubbreach abatement project and shall not clearance of work areas. At all isor shall be onsite or available by no more than 2 hours. each renovation project and shall area containment is being establishmust regularly direct work being pare at all times renovations are being RACY atton is correct. Signature Gary C	Zip Consiste Consists Site, or to be onsite during the consiste during the consistency of	ring all work site preparation when abatement activities are tager, or answering service, and present when the required signs other individuals and must be a serviced by other individuals and must be a serviced work area cleaning to the serviced work area.
City: Contact Person: NOTE: All debris (other than lead) ABATEMENT A certified supervisor is required for during the post-abatement cleanup a being conducted, the certified supervable to be present at the work site in RENOVATION A certified renovator is required for are posted, while the required work a performed. The certified renovator is available either onsite or by telephon. CERTIFICATION OF ACCUIT CERTIFICATION	State: Telephone Number should go to an authorized Rubber each abatement project and shall not clearance of work areas. At all isor shall be onsite or available by no more than 2 hours. each renovation project and shall area containment is being establish must regularly direct work being ple at all times renovations are being RACY atton is correct. Signature Gary Corquestions concerning the information of the should be	Zip Consiste Consists Site, or to be onsite during the consiste during the consistency of	ring all work site preparation when abatement activities are tager, or answering service, and present when the required signs other individuals and must be a serviced by other individuals and must be a serviced work area cleaning to the serviced work area.
City: Contact Person: NOTE: All debris (other than lead) ABATEMENT A certified supervisor is required for during the post-abatement cleanup a being conducted, the certified supervable to be present at the work site in RENOVATION A certified renovator is required for are posted, while the required work a performed. The certified renovator is available either onsite or by telephon. CERTIFICATION OF ACCUIT CERTIFICATION CE	State: Telephone Number should go to an authorized Rubber each abatement project and shall not clearance of work areas. At all isor shall be onsite or available by no more than 2 hours. each renovation project and shall area containment is being establishmust regularly direct work being part at all times renovations are being RACY atton is correct. Signature Gary Corquestions concerning the informatics	Zip Control Zip Co	ring all work site preparation when abatement activities are tager, or answering service, and present when the required signs required work area cleaning to other individuals and must be a service. Date 09/09/2022
City: Contact Person: NOTE: All debris (other than lead) ABATEMENT A certified supervisor is required for during the post-abatement cleanup a being conducted, the certified supervable to be present at the work site in RENOVATION A certified renovator is required for are posted, while the required work a performed. The certified renovator is available either onsite or by telephon. CERTIFICATION OF ACCUIT CERTIFICATION	State: Telephone Number should go to an authorized Rubbre each abatement project and shall nd clearance of work areas. At all isor shall be onsite or available by no more than 2 hours. each renovation project and shall area containment is being establishmust regularly direct work being put at all times renovations are being RACY ation is correct. Signature Gary Corrects or questions concerning the informatics State:	Zip Coer: () pish Site, or to be onsite due to other times telephone, p be physically ned, and while performed by g conducted.	ring all work site preparation when abatement activities are tager, or answering service, and present when the required signs other individuals and must be a serviced by other individuals and must be a serviced work area cleaning to the serviced work area.

P.O. Box 2261, Jackson, MS 39225