Job - 193816

Mississippi Office of Pollution Control Lead-Based Paint Abatement/Renovation Notification



MDEQ U Email		☐Hand Delivery	Postmark (mail only)	Date Received 9.20.22	AI Number			
Please ch	eck all ap	plicable boxes for			tion: 1971 Cancellation Emergency			
I.	Target He Child-Oc Physical	cupied Facility: Address Project S	ilte: 15 Abide Dr	39704	Washington			
		enville	State: MS ed/Renovated in the Build		unty: Washington			
II.	BUILDI Mr./Mrs.:	NG OWNER IN Larry or Carrie Gu	FORMATION ster	ity: Greenville	State: MS ZIP: 38701			
		e Number: (662) 3		ity:	State. Zir.			
III.	ABATEMENT/RENOVATION CONTRACTOR INFORMATION Name of Certified Lead Abatement/Renovator Firm: Brad Jones Firm Certification Number: PBR-00011234 Telephone Number: (870) 575-3548 Exp. Date: 01/25/2023 Address of Certified Firm: 350 Pine Tree Rd							
	City: Rise		State:	AR	Zip Code: 71665			
IV.	INSPECTION INFORMATION Name of Renovator/Inspector/Risk Assessor Conducting Inspection: Certification Number: Exp. Date: Date Inspection Conducted:							
				uipment:Certificati				
v.	GENER Name of	AL CONTRAC	ΓOR (Other) SA					
	Firm Mailing Address: PO Box 222 Royal, AR 71968							
	Contact 1	Person: Mia Walsh		Telephone Number	r:(<u>501)/50-0309</u>			
VI.	Lead Pro	J	121 /2022	Lead Project Stop: 09				
	Abateme	ent/Renovation to	be done during what ti	me? ■Day (5 a.m. – 5 p Night (8 p.m. – 5	o.m.) Evening (5 p.m. – 8 p.s i a.m.) Weekend			
VII.	DESCR	IPTION OF PRO	OCEDURES TO BE U	SED (CHECK ALL T				
	Conta	Sanding [ainment [ar - Explain	Component Removal Strip and Removal	☐ Heat Gun ☐ Negative Air	Encapsulation Enclosure			

VIII.DESCRIPTION OF RENOVATION ACTIVITIES TO BE COMPLETED (INCLUDING COMPONENTS TO BE AFFECTED)

Retro Fit Pocket Replacement of Existing Windows with New Vinyl Windows

(Full Mailing Address: 350 Pine Tree							
(
(City: Rison	State: AR	Zip	Code: 71665				
	Contact: Brad Jones	Telephone Numl	er: (870)	575-3548				
x. '	WASTE LEAD DISPOSAL SITE							
5	Site Name:							
	Physical Address:							
	Full Mailing Address:							
	City:			Code:				
XI. I	DISPOSAL SITE FOR DEBRIS O	THER THAN LEAD						
5	Site Name:							
	Physical Address:							
	Full Mailing Address:							
(City:	State:	Zip	Code:				
	Contact Person:							
XII. A	NOTE: All debris (other than lead) shounds ABATEMENT A certified supervisor is required for each luring the post-abatement cleanup and cleaning conducted, the certified supervisor s	abatement project and sha earance of work areas. At a hall be onsite or available l	obish Site, of the site of the	during all work site	unitary landfill. preparation and t activities are			
XII. A d b a XIII. F	ABATEMENT A certified supervisor is required for each furing the post-abatement cleanup and cleaning conducted, the certified supervisor suble to be present at the work site in no make the certified renovator is required for each in the posted, while the required work area conformed. The certified renovator must be present.	abatement project and shatement project and shatement project and shatemance of work areas. At a hall be onsite or available lore than 2 hours. The project and shatemance of the stable and the project and shatemance and the project and shatemance are shall be a stable and the project and shatemance are shall be a stable and the project and shatemance are shall be a stable and the project and shatemance are shall be a stable and the project and shatemance are shall be a stable and the project and shall be a stable as a stable and the project and shall be a stable and the project and shall be a stable as a stable and the project and shall be a stable as a stable and the project and shall be a stable as a stable as a stable and the project and shall be a stable as a stabl	ll be onsite all other time by telephone the physical shed, and we performed	during all work site nes when abatement e, pager, or answeri ally present when the hile required work by other individua	e preparation and t activities are ing service, and ne required signs area cleaning is			
XII. A d b a XIII. F	ABATEMENT A certified supervisor is required for each luring the post-abatement cleanup and cleaning conducted, the certified supervisor suble to be present at the work site in no make the certified renovator is required for each the posted, while the required work area controls.	abatement project and shatement project and shatement project and shatemance of work areas. At a hall be onsite or available lore than 2 hours. The project and shatemance of the stable and the project and shatemance and the project and shatemance are shall be a stable and the project and shatemance are shall be a stable and the project and shatemance are shall be a stable and the project and shatemance are shall be a stable and the project and shatemance are shall be a stable and the project and shall be a stable as a stable and the project and shall be a stable and the project and shall be a stable as a stable and the project and shall be a stable as a stable and the project and shall be a stable as a stable as a stable and the project and shall be a stable as a stabl	ll be onsite all other time by telephone the physical shed, and we performed	during all work site nes when abatement e, pager, or answeri ally present when the hile required work by other individua	e preparation and t activities are ing service, and ne required signs area cleaning is			
XII. A dd bb ax XIII. F A a p a	ABATEMENT A certified supervisor is required for each during the post-abatement cleanup and cleanup conducted, the certified supervisor suble to be present at the work site in no more RENOVATION A certified renovator is required for each are posted, while the required work area coerformed. The certified renovator must available either onsite or by telephone at a CERTIFICATION OF ACCURACE	abatement project and shatement project and shatement project and shatemance of work areas. At a hall be onsite or available lore than 2 hours. The containment is being establication and shatement is being establication and shatement is being establication. The containment is being establication are being litimes renovations are being the containment is seen as a second containment is being establication.	ll be onsite all other time by telephone the physical shed, and we performed	during all work site nes when abatement e, pager, or answeri ally present when the hile required work by other individua	e preparation and t activities are ing service, and ne required signs area cleaning is			
XII. A dd b a XIII. F A a p a XIV. C	ABATEMENT A certified supervisor is required for each furing the post-abatement cleanup and cleaning conducted, the certified supervisor is able to be present at the work site in no more RENOVATION A certified renovator is required for each in the posted, while the required work area controlled. The certified renovator must be available either onsite or by telephone at a certify that all of the above information is	abatement project and shatement project and shatement of work areas. At a hall be onsite or available love than 2 hours. The renovation project and shatement is being establing a half of the stabling and the stabling are being times renovations are being the stabling are stabling as a correct.	ll be onsite all other tim by telephone the physica shed, and w performed ng conducte	during all work site ness when abatemente, pager, or answering ally present when the hile required work by other individuated.	e preparation and t activities are ing service, and the required signs the required signs that area cleaning is			
XII. A dd ba xIII. F A a p a XIV. C	ABATEMENT A certified supervisor is required for each furing the post-abatement cleanup and cleaning conducted, the certified supervisor is able to be present at the work site in no more RENOVATION A certified renovator is required for each in the posted, while the required work area controlled. The certified renovator must be available either onsite or by telephone at a certify that all of the above information is	abatement project and shatement project and shatement project and shatemance of work areas. At a hall be onsite or available lore than 2 hours. The containment is being establication and shatement is being establication and shatement is being establication. The containment is being establication are being litimes renovations are being the containment is seen as a second containment is being establication.	ll be onsite all other tim by telephone the physica shed, and w performed ng conducte	during all work site ness when abatemente, pager, or answering ally present when the hile required work by other individuated.	e preparation and t activities are ing service, and ne required signs area cleaning is			
XII. A d d b a XIII. F A A A A A A A A A A A A A A A A A A A	ABATEMENT A certified supervisor is required for each luring the post-abatement cleanup and cleaning conducted, the certified supervisor is able to be present at the work site in no more RENOVATION A certified renovator is required for each in the posted, while the required work area controlled. The certified renovator must be available either onsite or by telephone at a certify that all of the above information in the print Brad Jones Contact information for return mail or questions.	abatement project and shatement project and shatement project and shatemance of work areas. At thall be onsite or available love than 2 hours. The conversion project and shatement is being establing establing and all times renovations are being litimes renovations are being storrect. Signature	Il be onsite all other time by telephone Il be physical be physical shed, and we performed and conductors.	during all work sittles when abatements, pager, or answers ally present when the hile required work by other individuals. Date	e preparation and t activities are ing service, and the required signs the required signs that area cleaning is			
XII. A d d b a XIII. F A a p p A C C N	ABATEMENT A certified supervisor is required for each furing the post-abatement cleanup and cleaning conducted, the certified supervisor is able to be present at the work site in no more removed. The certified renovator is required for each are posted, while the required work area conformed. The certified renovator must be realised either onsite or by telephone at a certify that all of the above information in the print Brad Jones Contact information for return mail or questioning Address: 350 Pine Tree Rd	abatement project and shatement project and shatement project and shatemance of work areas. At a hall be onsite or available love than 2 hours. The conversion project and shatemance of the shateman sh	Il be onsite all other time by telephone Il be physical be physical shed, and we performed and conducted to the shed of the sh	during all work site ies when abatements, pager, or answer ally present when the shift required work by other individuated. Date this Notice	e preparation and tactivities are ing service, and he required signs area cleaning is its and must be			
XII. A d d b a XIII. F A A A A A A A A A A A A A A A A A A A	ABATEMENT A certified supervisor is required for each luring the post-abatement cleanup and cleaning conducted, the certified supervisor is able to be present at the work site in no more reposted, while the required for each in posted, while the required work area controlled. The certified renovator must be available either onsite or by telephone at a certify that all of the above information is required by the posted of the short information in the posted of the short information in the print Brad Jones Contact information for return mail or questions and address: 350 Pine Tree Rd City: Rison	abatement project and shatement project and shatement of work areas. At thall be onsite or available love than 2 hours. The enovation project and shatement is being establic regularly direct work being li times renovations are being times renovations are being establic times renovations are being lift times renovations are being lift times renovations are being establic times renovations are being lift times renovations.	Il be onsite all other time by telephone the physics shed, and we performed and conductors.	during all work site ies when abatements, pager, or answer ally present when the hile required work by other individuated. Date this Notice	e preparation and tactivities are ing service, and he required signs area cleaning is als and must be			
XII. A d d b a XIII. F A A A A A A A A A A A A A A A A A A A	ABATEMENT A certified supervisor is required for each furing the post-abatement cleanup and cleaning conducted, the certified supervisor is able to be present at the work site in no more removed. The certified renovator is required for each are posted, while the required work area conformed. The certified renovator must be realised either onsite or by telephone at a certify that all of the above information in the print Brad Jones Contact information for return mail or questioning Address: 350 Pine Tree Rd	abatement project and shatement project and shatement of work areas. At thall be onsite or available love than 2 hours. Trenovation project and shatement is being establic regularly direct work being litimes renovations are being state. Signature 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	Il be onsite all other time by telephone the physics shed, and we performed and conductors.	during all work site ies when abatements, pager, or answer ally present when the shift required work by other individuated. Date this Notice	e preparation and tactivities are ing service, and he required signs area cleaning is als and must be			
XII. A dd bb ax XIII. F A a p a	ABATEMENT A certified supervisor is required for each during the post-abatement cleanup and cleanup conducted, the certified supervisor suble to be present at the work site in no more RENOVATION A certified renovator is required for each are posted, while the required work area coerformed. The certified renovator must available either onsite or by telephone at a CERTIFICATION OF ACCURACE	abatement project and shatement project and shatement project and shatemance of work areas. At a hall be onsite or available lore than 2 hours. The containment is being establication and shatement is being establication and shatement is being establication. The containment is being establication are being litimes renovations are being the containment is seen as a second containment is being establication.	ll be onsite all other time by telephone the physical shed, and we performed	during all work site test when abatements, pager, or answering ally present when the by other individuals.	e preparatio t activities a ing service, s ne required :			
XII. A d d b a XIII. F A A A A A A A A A A A A A A A A A A A	ABATEMENT A certified supervisor is required for each luring the post-abatement cleanup and cleaning conducted, the certified supervisor is able to be present at the work site in no more reposted, while the required for each in posted, while the required work area controlled. The certified renovator must be available either onsite or by telephone at a certify that all of the above information is required by the posted of the short information in the posted of the short information in the print Brad Jones Contact information for return mail or questions and address: 350 Pine Tree Rd City: Rison	abatement project and shatement project and shatement of work areas. At thall be onsite or available love than 2 hours. The enovation project and shatement is being establic regularly direct work being li times renovations are being times renovations are being establic times renovations are being lift times renovations are being lift times renovations are being establic times renovations are being lift times renovations.	Il be onsite all other time by telephone the physics shed, and we performed and conductors.	during all work site ies when abatements, pager, or answer ally present when the hile required work by other individuated. Date this Notice	e preparation and activities are ing service, and are required signs area cleaning is als and must be			