## Mississippi Office of Pollution Control Lead-Based Paint Abatement/Renovation Notification



-		Profession (mail only)	Date Receiv	ed A	I Number		
MDEQ U		Postmark (mail only)		1-23			
Please ch	Type: Abatement Leck all applicable boxes for heck if asbestos notificati	the type of Notificati	on: Original _	Kevision LC	1970 ancellation Emergency		
I.	PROJECT/SITE INFORT				PROPERTY AND		
	City: Prentiss  Number of Units to be Abat	State: NIS	Zip Code: 3947 nilding: 1	74 County:	Jefferson Davis		
11.	BUILDING OWNER IN Mr./Mrs.: Jocelyn Oatis Address of Owner: 276 Air	port Rd	City: Prentiss	State	MS ZIP: 39474		
ш.	Telephone Number: (601)	92-8629 ATION CONTRAC	CTOR INFORM	ATION			
	Name of Certified Lead Firm Certification Number Address of Certified Firm City: New Orleans	PBR-00009925 T	elephone Number	(504)382-45	78 Exp. Date: 01/27/23  Code: 70123		
IV.	INSPECTION INFORMATION Name of Renovator/Inspector/Risk Assessor Conducting Inspection:						
	Certification Number: Exp. Date: Date Inspection Conducted: Test Method Used & Manufacturer of Testing Equipment: Assumed  For Paint Chip Analysis, Name of Laboratory: Certification Number:						
V.	GENERAL CONTRACTOR (Other)  Name of Firm: THE HOME DEPOT  Firm Mailing Address: 2455 Paces Ferry Rd C-11  Contact Person Director of Services Compliance Telephone Number: (770) 384-4422						
VI.	PROJECT DATES Lead Project Start: 02 Abatement/Renovation t	/08 /2023	Lead Project at time? Day (5	a.m. – 5 p.m.			
VII.	DESCRIPTION OF PR Wet Sanding Containment Other – Explain	OCEDURES TO B Component Remo Strip and Remova	E USED (CHEC		n.)		

## VIII. DESCRIPTION OF RENOVATION ACTIVITIES TO BE COMPLETED (INCLUDING COMPONENTS TO BE AFFECTED)

Retrofitting and component removal for 16 windows

Name							
0.		State:	Zip Code				
Conta	act	Telephone Number: (_	)				
WAS	TE LEAD DISPOSAL SITE		1				
Physi	cal Address:						
Full N	Mailing Address:						
City:	Mailing Address:	State:	_ Zip Code				
DISP	Site Name: —see onsite personnel—						
Physi	cal Address:						
	C 11: A 11						
City		State:	_ Zip Code				
		Talanhane Number					
ABA A certiful during	TEMENT ified supervisor is required for each aba the post-abatement cleanup and cleara and ucted, the certified supervisor shall be present at the work site in no more	go to an authorized Rubbish atement project and shall be once of work areas. At all oth	onsite during	all work site preparation an			
ABA' A certifuring being cable to  I. RENC	E. All debris (other than lead) should go FEMENT  ified supervisor is required for each abage the post-abatement cleanup and cleara conducted, the certified supervisor shall to be present at the work site in no more solvential to be present at the conducted of the conducted of the conducted of the conducted of the conducted work area content of the conducted work area content.	atement project and shall be once of work areas. At all oth the onsite or available by telesthan 2 hours.	onsite during oner times whe ephone, pager ohysically pre and while re	all work site preparation an a abatement activities are c, or answering service, and sent when the required sign quired work area cleaning is			
A certiful during being cable to I. RENC	E All debris (other than lead) should go FEMENT  ified supervisor is required for each abage the post-abatement cleanup and clearate conducted, the certified supervisor shall be present at the work site in no more over the conduction.	go to an authorized Rubbish  atement project and shall be once of work areas. At all oth the consite or available by tele than 2 hours.  ovation project and shall be p ainment is being established, ularly direct work being perf	onsite during over times whe ephone, pager ohysically pre and while re-	all work site preparation an n abatement activities are c, or answering service, and sent when the required sign			
A Certifuring being cable to A certifure por performavailal	E. All debris (other than lead) should go FEMENT  ified supervisor is required for each abage the post-abatement cleanup and cleara conducted, the certified supervisor shall to be present at the work site in no more solvent.  OVATION  ified renovator is required for each renovator, while the required work area continued. The certified renovator must required.	go to an authorized Rubbish  atement project and shall be once of work areas. At all oth the consite or available by tele than 2 hours.  ovation project and shall be p ainment is being established, ularly direct work being perf	onsite during over times whe ephone, pager ohysically pre and while re-	all work site preparation an n abatement activities are c, or answering service, and sent when the required sign			
A Certiful during being of able to A certifure por performavailal	E All debris (other than lead) should go FEMENT ified supervisor is required for each abage the post-abatement cleanup and clearage and other than the certified supervisor shall be present at the work site in no more solvential.  OVATION ified renovator is required for each renovated, while the required work area contimed. The certified renovator must regulate either onsite or by telephone at all to FIFICATION OF ACCURACY	atement project and shall be once of work areas. At all oth the onsite or available by telethan 2 hours.  Divation project and shall be painment is being established, ularly direct work being perfemes renovations are being co	onsite during ner times whe cphone, pager ohysically pre and while re formed by oth inducted.	all work site preparation an n abatement activities are c, or answering service, and sent when the required sign			
A Certiful during being cable to A certifare por perforavailal V. CERT Contac Mailin	E All debris (other than lead) should go FEMENT  ified supervisor is required for each abage the post-abatement cleanup and clearage and conducted, the certified supervisor shall be present at the work site in no more solvential. The certified renovator must regulated, while the required work area continued. The certified renovator must regulate either onsite or by telephone at all time.  FIFICATION OF ACCURACY by that all of the above information is continued the shutley/The Home Depot.  Set information for return mail or questing Address: 2455 Paces Ferry Ro	atement project and shall be conce of work areas. At all oth the consite or available by telesthan 2 hours.  The project and shall be painment is being established, alarly direct work being performes renovations are being concerning the informations concerning the informations.	onsite during the times whe comment of the times when the times wh	all work site preparation an abatement activities are ror answering service, and sent when the required signiquired work area cleaning is er individuals and must be  Date 1/19/23			
A Certiful during being cable to A certifare por perforavailal V. CERT Contac Mailin	E All debris (other than lead) should go FEMENT  ified supervisor is required for each abage the post-abatement cleanup and clearage and conducted, the certified supervisor shall be present at the work site in no more solvential. The certified renovator must regulated, while the required work area continued. The certified renovator must regulate either onsite or by telephone at all time.  FIFICATION OF ACCURACY by that all of the above information is continued the shutley/The Home Depot.  Set information for return mail or questing Address: 2455 Paces Ferry Ro	atement project and shall be conce of work areas. At all oth the onsite or available by telethan 2 hours.  The project and shall be painment is being established, ularly direct work being performes renovations are being concerning the informational C12  State: GA	onsite during the times whe ephone, pager on this record by oth inducted.	all work site preparation an abatement activities are room or answering service, and sent when the required signification work area cleaning is er individuals and must be			
A Certifuring being of able to  I. RENG A certifure por performavailal  V. CERT Contact Mailin City Contact	E. All debris (other than lead) should go FEMENT  ified supervisor is required for each abage the post-abatement cleanup and cleara conducted, the certified supervisor shall to be present at the work site in no more steed, while the required work area continued. The certified renovator must regulate either onsite or by telephone at all to FIFICATION OF ACCURACY by that all of the above information is continued. The certified renovator must regulate either Shutley/The Home Depot  Set information for return mail or questing Address: 2455 Paces Ferry Roadlanta  Let Heather Shutley  Heather Shutley  Heather Shutley  Heather Shutley	atement project and shall be conce of work areas. At all oth libe onsite or available by telethan 2 hours.  To vation project and shall be painment is being established, alarly direct work being performes renovations are being concerning the informational C12  State: GA  Telephone Nu	onsite during the times whe ephone, pager on this record by oth inducted.	all work site preparation an abatement activities are room or answering service, and sent when the required signification work area cleaning is er individuals and must be			
A Certifuring being of able to  I. RENG A certifure por performavailal  V. CERT Contact Mailin City Contact	E. All debris (other than lead) should got FEMENT  ified supervisor is required for each abage the post-abatement cleanup and cleara conducted, the certified supervisor shall a be present at the work site in no more solvation  OVATION  ified renovator is required for each renovator while the required work area continued. The certified renovator must regulate either onsite or by telephone at all to a supervisor of the should be supervisor in the should be supervisor. Set information for return mail or questing Address: 2455 Paces Ferry Roallanta	atement project and shall be conce of work areas. At all oth libe onsite or available by telethan 2 hours.  To vation project and shall be painment is being established, alarly direct work being performes renovations are being concerning the informational C12  State: GA  Telephone Nu	onsite during the times whe ephone, pager on this record by oth inducted.	all work site preparation an abatement activities are root answering service, and sent when the required sign quired work area cleaning is er individuals and must be  Date 1/19/23			
A Certifuring being of able to  I. RENO A certifure por performavailal  V. CERT Contact Mailing City Contact Contact Email	E. All debris (other than lead) should go FEMENT  ified supervisor is required for each abage the post-abatement cleanup and cleara conducted, the certified supervisor shall to be present at the work site in no more steed, while the required work area continued. The certified renovator must regulate either onsite or by telephone at all to FIFICATION OF ACCURACY by that all of the above information is continued. The certified renovator must regulate either Shutley/The Home Depot  Set information for return mail or questing Address: 2455 Paces Ferry Roadlanta  Let Heather Shutley  Heather Shutley  Heather Shutley  Heather Shutley	atement project and shall be conce of work areas. At all oth the consite or available by telesthan 2 hours.  To vation project and shall be painment is being established, alarly direct work being performes renovations are being concerning the informational C12  State: GA  Telephone Nuest@homedepot.com	onsite during per times whe ephone, pager ohysically pre and while reformed by other ducted.	all work site preparation an abatement activities are cor answering service, and sent when the required signification work area cleaning is er individuals and must be Date 1/19/23 stice			