



**VIII. DESCRIPTION OF RENOVATION ACTIVITIES TO BE COMPLETED (INCLUDING COMPONENTS TO BE AFFECTED)**

Retro Fit Pocket Replacement of Existing Windows with New Vinyl Windows

**IX. WASTE TRANSPORTER**

Name: Chandler Moody  
Full Mailing Address: 1691 CR 171  
City: Blue Springs State: MS Zip Code: 38828  
Contact: Chandler Moody Telephone Number: (662) 507-5154

**X. WASTE LEAD DISPOSAL SITE**

Site Name: Republic Services Little Dixie Landfill  
Physical Address: 1716 N County Line Road  
Full Mailing Address: \_\_\_\_\_  
City: Ridgeland State: MS Zip Code: 39157

**XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD**

Site Name: \_\_\_\_\_  
Physical Address: \_\_\_\_\_  
Full Mailing Address: \_\_\_\_\_  
City: \_\_\_\_\_ State: \_\_\_\_\_ Zip Code: \_\_\_\_\_  
Contact Person: \_\_\_\_\_ Telephone Number: (\_\_\_\_) \_\_\_\_\_

NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.

**XII. ABATEMENT**

A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.

**XIII. RENOVATION**

A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.

**XIV. CERTIFICATION OF ACCURACY**

I certify that all of the above information is correct.

Print Chandler Moody Signature Chandler Moody Date 7/31/23

Contact information for return mail or questions concerning the information on this Notice

Mailing Address: 1691 CR 171  
City: Blue Springs State: MS Zip Code: 38828  
Contact: Chandler Moody Telephone Number: (662) 507-5154  
Email: chandler.moody@windowsusa.com

Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification.

MAIL TO: Mississippi Department of Environmental Quality  
Lead Notifications  
P.O. Box 2261, Jackson, MS 39225