## REV

## Mississippi Office of Pollution Control Lead-Based Paint Abatement/Renovation Notification

200272



MDEQ	Use Only:		Postmark (mall only)	Date 1	Received	AI Number			
⊠Email	I ☐Mail	Hand Delivery		08	3-21-2023	CO DICTION OF THE			
Project	Type:	Abatement	Renovation	Date of Build	ing Constru	etion: 1970 Cancellation Emerg	•		
			on was also submi				ency		
I,	Target Ho	CT/SITE INFO	E						
	Physical	Address Project S	Site: 203 Nest St	0	<u> </u>	t de la companya de l			
	City: Can	ton	State: MS	Zip Code:		ounty: Madison			
	Number o	f Units to be Abat	ed/Renovated in the I	Building: Replac	ing 8 Window	5			
II.	BUILDI	NG OWNER IN	FORMATION			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
	Mr./Mrs.:	Clarence Meeks							
	Address	f Owner: 203 Nes	tSt	City: Cantor	1	State: MS ZIP: 39046	2-1		
	Telephon	Number: (601) 8	342-2330						
m.	ARATE	MENT/RENOV	ATION CONTRA	CTOR INFO	RMATION				
111,			Abatement/Renov		122 Y				
			r: PBR-00010175			2-8033 Exp. Date: 03/28	1/2024		
			126 Cape Charles	Ciophono Ivan	1001.()	Dap. Date			
	City: Bra		S	ata MS		Zip Code: 39047	-		
				arc.		Zip Code.	_		
IV.		TION INFORM	IATION ector/Risk Assesso	v Canduatina	Ingrestions				
						spection Conducted:	-		
						-	<u> </u>		
	For Paint	Chip Analysis, I	Name of Laboratory	•	Certificat	ion Number:	41		
V.		AL CONTRAC							
	Name of Firm: Windows USA								
	Firm Mailing Address; PO Box 222, Royal, AR 71988								
	Contact Person; Christine Walker Telephone Number: (501) 760-0292								
VI.	PROJEC	T DATES	/26 /2023	Lead Proj	ect Stop: 08	/27 /2023			
		nt/Renovation to	be done during wh	at time? Da	y (5 a.m. – 5				
	Abateme	ib removation to		□Ni	ght (8 p.m. –	5 a.m.) Weekend	ı, – a p,ııı		
VII.			OCEDURES TO B		The said		i, — 8 p,iii		

## VIII.DESCRIPTION OF RENOVATION ACTIVITIES TO BE COMPLETED (INCLUDING COMPONENTS TO BE AFFECTED)

Retro Fit Pocket Replacement of Existing Windows with New Vinyl Windows

Full Mailing Address: 126	Cape Charles							
City: Brandon		State: MS	Zin Co	de- 39047	Mark Lines			
Contact: Gary Ogle					E-Faith			
WASTE LEAD DISPOS. Site Name: Canton Sanitary	AL SITE y Landfill		vortage	SANTETENTOT Selection				
Physical Address: 303 Solo	diers Colony Road			Jackettales S. F. J.				
Full Mailing Address:		at III	Land.	Total E	Territor.			
City: Canton	anema (Byen elma)	State: MS	Zip Co	de: 39046				
	DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD Site Name:							
Physical Address:					est A			
Full Mailing Address:				I III Cacataly and	6-54-67			
City:	Version a	State:	Zip Co	de:				
Ctt D	Т	lephone Numbe	er: ( )		Bernal'i			
Contact Person:	lead) should go to an	authorized Rubbi	ish Site, or to	a permitted sanitary	landfill.			
I. ABATEMENT								
	red for each abatement p nup and clearance of w supervisor shall be onsit	project and shall ork areas. At all te or available by	be onsite duri other times w	ng all work site prepa hen abatement activit	ration and			
I. ABATEMENT  A certified supervisor is required uring the post-abatement clease being conducted, the certified able to be present at the work in	red for each abatement p nup and clearance of w supervisor shall be onsit	project and shall ork areas. At all te or available by	be onsite duri other times w	ng all work site prepa hen abatement activit	ration and			
I. ABATEMENT  A certified supervisor is required during the post-abatement clear being conducted, the certified statement conducted.	red for each abatement panup and clearance of we supervisor shall be onsit site in no more than 2 hed for each renovation payork area containment vator must regularly dis	project and shall book areas. At all te or available by ours.  project and shall to be being establish rect work being project and shall to be being establish rect work being p	be onsite duri other times w telephone, pa be physically p ed, and while erformed by o	ng all work site prepa then abatement activit ger, or answering serv present when the requ required work area c	ration and ies are vice, and ired signs leaning is			
I. ABATEMENT  A certified supervisor is required during the post-abatement clear being conducted, the certified suble to be present at the work of the supervisor is required are posted, while the required performed. The certified reno	red for each abatement panup and clearance of we supervisor shall be onsit site in no more than 2 heed for each renovation pawork area containment vator must regularly distended.	project and shall book areas. At all te or available by ours.  project and shall to be being establish rect work being project and shall to be being establish rect work being p	be onsite duri other times w telephone, pa be physically p ed, and while erformed by o	ng all work site prepa then abatement activit ger, or answering serv present when the requ required work area c	ration and ies are vice, and ired signs leaning is			
I. ABATEMENT  A certified supervisor is required uring the post-abatement cleaseing conducted, the certified stable to be present at the work of the service	red for each abatement panup and clearance of we supervisor shall be onsit site in no more than 2 he defor each renovation payork area containment vator must regularly disleptione at all times renovation is correct.	project and shall ork areas. At all te or available by ours.  project and shall to is being establish rect work being povations are being	be onsite duri other times we telephone, par be physically p ed, and while erformed by or conducted.	ng all work site prepartien abatement activiting ger, or answering servers and the required work area continuity and the requirement which are the requirement and the requirement activities and the requirement activities are the requirement activities and the requirement activities and the requirement activities are the requirement activities and the requirement activities are the requ	ration and ies are vice, and ired signs leaning is must be			
I. ABATEMENT  A certified supervisor is required uring the post-abatement cleaseing conducted, the certified stable to be present at the work of the service	red for each abatement panup and clearance of we supervisor shall be onsit site in no more than 2 he defor each renovation payork area containment vator must regularly disleptione at all times renovation is correct.	project and shall ork areas. At all te or available by ours.  project and shall to is being establish rect work being povations are being	be onsite duri other times we telephone, par be physically p ed, and while erformed by or conducted.	ng all work site prepa then abatement activit ger, or answering serv present when the requ required work area c	ration and ies are vice, and ired signs leaning is must be			
A certified supervisor is required uring the post-abatement cleated being conducted, the certified stable to be present at the work of the certified renovator is required are posted, while the required performed. The certified renovailable either onsite or by tell to certify that all of the above in Print Gary Ogle.  Contact information for return	red for each abatement panup and clearance of we supervisor shall be onsit site in no more than 2 he ded for each renovation payork area containment vator must regularly distended at all times renovation at all times renovation is correct.  Signatura mail or questions concerning and signaturations are signaturated as a signaturation and signaturated as a signa	project and shall bork areas. At all te or available by ours.  project and shall this being establish rect work being povations are being	be onsite duri other times w telephone, pa  telephone pa	ng all work site preparties abatement activity ger, or answering servers are servers when the required work area contact individuals and a servers are servers are servers as a server are servers as a server are servers as a server area of their individuals and a servers area of their individuals and a servers area.	ration and ies are vice, and ired signs leaning is must be			
A certified supervisor is required uring the post-abatement cleated being conducted, the certified stable to be present at the work of the certified renovator is required are posted, while the required performed. The certified renovailable either onsite or by tell to certify that all of the above in Print Gary Ogle.  Contact information for return	red for each abatement panup and clearance of we supervisor shall be onsit site in no more than 2 he ded for each renovation payork area containment vator must regularly distended at all times renovation at all times renovation is correct.  Signatura mail or questions concerning and signaturations are signaturated as a signaturation and signaturated as a signa	project and shall bork areas. At all te or available by ours.  project and shall this being establish rect work being povations are being	be onsite duri other times w telephone, pa  telephone pa	ng all work site preparties abatement activity ger, or answering servers are servers when the required work area contact individuals and a servers are servers are servers as a server are servers as a server are servers as a server area of their individuals and a servers area of their individuals and a servers area.	ration and ies are vice, and ired signs leaning is must be			
A certified supervisor is required uring the post-abatement clear being conducted, the certified able to be present at the work of the supervisor.  II. RENOVATION  A certified renovator is required are posted, while the required performed. The certified renovatilable either onsite or by tell.  V. CERTIFICATION OF A I certify that all of the above in Print Gary Ogle  Contact information for return Mailing Address: 126 Cape	red for each abatement panup and clearance of we supervisor shall be onsit site in no more than 2 he ded for each renovation payork area containment vator must regularly distended at all times renovation at all times renovation is correct.  Signatura mail or questions concerning and signaturations are signaturated as a signaturation and signaturated as a signa	project and shall bork areas. At all te or available by ours.  project and shall this being establish rect work being povations are being	be onsite duri other times w telephone, pa  oe physically p ed, and while erformed by o conducted.	ng all work site preparties abatement activity ger, or answering servers are servers when the required work area contact individuals and a servers are servers are servers as a server are servers as a server are servers as a server area of their individuals and a servers area of their individuals and a servers area.	ration and ies are vice, and ired signs leaning is must be			
A certified supervisor is required uring the post-abatement cleated being conducted, the certified stable to be present at the work of the certified renovator is required are posted, while the required performed. The certified renovailable either onsite or by tell to certify that all of the above in Print Gary Ogle.  Contact information for return	red for each abatement panup and clearance of we supervisor shall be onsit site in no more than 2 he ded for each renovation payork area containment vator must regularly distended at all times renovation at all times renovation is correct.  Signatura mail or questions concerning and signaturations are signaturated as a signaturation and signaturated as a signa	project and shall fork areas. At all te or available by ours.  project and shall this being establish rect work being povations are being erning the information of the state;  State:	be onsite duri other times w telephone, pa  be physically p ed, and while erformed by c c conducted.	ng all work site prepartien abatement activiting ger, or answering serversesent when the required work area contact individuals and a Date 08/18/	ration and ies are vice, and ired signs leaning is must be			
A certified supervisor is required uring the post-abatement cleated being conducted, the certified stable to be present at the work of the certified renovator is required are posted, while the required performed. The certified renovailable either onsite or by tell and the required performed of the certified renovailable of the above in Print Gary Ogle  Contact information for return Mailing Address: 126 Cape City: Brandon	red for each abatement panup and clearance of we supervisor shall be onsite in no more than 2 he ded for each renovation payork area containment vator must regularly disceptione at all times renovation is correct.  Signature mail or questions concest Charles	project and shall fork areas. At all te or available by ours.  project and shall this being establish rect work being povations are being erning the information of the state;  State:	be onsite duri other times w telephone, pa  be physically p ed, and while erformed by c c conducted.	ng all work site prepartien abatement activiting ger, or answering server answering server are sent when the required work area counter individuals and answering better individuals and activities.  Date 08/18/	ration and ies are vice, and ired signs leaning is must be			