

## Mississippi Office of Pollution Control Lead-Based Paint Abatement/Renovation Notification



MDEQ U	se Only:		Postmark (mail only)	Date Received	AI Number
Email	Mail	Hand Delivery		3/13/2025	88285
Please ch	eck all ap	plicable boxes for	Renovation Date of the type of Notification: on was also submitted for	Original KRevision L	on: 1910 Cancellation Emergency
				<u> </u>	
I.	Target He Child-Oc Physical City: CO	cupied Facility:  Address Project S LUMBUS	-	ip Code: 39705 Cou	nty:LOWDNES
II.	Mr./Mrs.	ING OWNER IN : CHRISTY HUE of Owner: 106 SLE ne Number: (225)2	EY PPY HOLLOW DRIVE $_{ m Cit}$	y:COLUMBUS	State: MS ZIP: 39705
ш.	ABATE	MENT/RENOV	ATION CONTRACTO	R INFORMATION	
	Firm Ce	rtification Number of Certified Firm	Abatement/Renovator I cr: PBR-00012689 Teleph d: 4979 CLIFF GOOKIN BLV	none Number:( <u><sup>662</sup>) <sup>842-5</sup></u> /D	Exp. Date: 12/10/2025
IV.	Name of Certific Test Me	ation Number: ethod Used & Mar	oector/Risk Assessor Co	Date Insp ipment:_LEAD CHECK S\	ection Conducted:
V.	GENEI Name o	RAL CONTRAC	TOR (Other) WORLD TUPELO/COLUMB 079 CLIFF GOOKIN BLVD, 1	us	
VI.	PROJI Lead P	ECT DATES roject Start: ろ	/ 20/2025	ne? 🔳 Day (5 a.m. – 5 p	
VII	☐ We ■ Cor	RIPTION OF PR t Sanding ntainment ner – Explain	ROCEDURES TO BE USE Component Removal Strip and Removal	SED (CHECK ALL T  Heat Gun  Negative Air	Encapsulation

## VIII. DESCRIPTION OF RENOVATION ACTIVITIES TO BE COMPLETED (INCLUDING **COMPONENTS TO BE AFFECTED)**

REMOVING 3 WINDOWS CONTAIN LEAD PAINT INSTALLATION OF 3 VINYL WINDOWS

	WASTE TRANSPORTER	Δ						
-		Δ						
	Name: WESLEY DA SILVA BRAGA							
]	Full Mailing Address: 4979 CLIFF GO							
(	City: TUPELO	State: MS	Zip Code: 38801					
(	Contact: CHRIS COLLINS	Telephone Number	r: ( <u><sup>662</sup>)</u> 842-5201					
<b>X.</b> '	WASTE LEAD DISPOSAL SITE							
	Site Name: WINDOW WORLD OF TUPELO/COLUMBUS							
	Physical Address: 4979 CLIFF GOOKIN BLVD , TUPELO, MS 38801							
į	Full Mailing Address: 4979 CLIFF GO	OOKIN BLVD						
	City: TUPELO	State: MS	Zip Code: 38801					
	DISPOSAL SITE FOR DEBRIS O	THER THAN LEAD						
	Site Name. WINDOW WORLD OF TUPELO/COLUMBUS							
	Physical Address: 4979 CLIFF GOOKIN BLVD, TUPELO, MS 38801							
	End Mailing Address, 4979 CLIFF GC	OOKIN BLVD						
	City. TUPELO	State: MS	Zip Code: 38801					
	CHRIS COLLINS		662 842-5201					
	Contact Person. Of It to OCEEII to	Telephone Numb	er: ( 002 ) 042-3201					
	NOTE: All debris (other than lead) shou	Telephone Numb uld go to an authorized Rubb	pish Site, or to a permitted sanitary landfill.					
	NOTE: All debris (other than lead) shou	Telephone Numbuld go to an authorized Rubb	Zip Code: 38801  er: (662) 842-5201  pish Site, or to a permitted sanitary landfill.					
XII.	ABATEMENT  A certified supervisor is required for each	n abatement project and shall learance of work areas. At al shall be onsite or available by	bish Site, or to a permitted sanitary landfill.  The be onsite during all work site preparation and lother times when abatement activities are y telephone, pager, or answering service, and					
XII.	ABATEMENT  A certified supervisor is required for each during the post-abatement cleanup and cleanup conducted, the certified supervisor is	n abatement project and shall learance of work areas. At al shall be onsite or available by	be onsite during all work site preparation and lother times when abatement activities are					
XII.	ABATEMENT  A certified supervisor is required for each during the post-abatement cleanup and cl being conducted, the certified supervisor able to be present at the work site in no memory of the property of the required for each proceed, while the required work area.	n abatement project and shall learance of work areas. At al shall be onsite or available by nore than 2 hours.  Trenovation project and shall containment is being establis	be onsite during all work site preparation and other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs hed, and while required work area cleaning is performed by other individuals and must be					
XII. XIII.	ABATEMENT  A certified supervisor is required for each during the post-abatement cleanup and cl being conducted, the certified supervisor able to be present at the work site in no memory.  RENOVATION  A certified renovator is required for each are posted, while the required work area performed. The certified renovator must	n abatement project and shall learance of work areas. At al shall be onsite or available by nore than 2 hours. Trenovation project and shall containment is being establis tregularly direct work being all times renovations are being	be onsite during all work site preparation and other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs hed, and while required work area cleaning is performed by other individuals and must be					
XII. XIII.	ABATEMENT  A certified supervisor is required for each during the post-abatement cleanup and cleaning conducted, the certified supervisor able to be present at the work site in no material RENOVATION  A certified renovator is required for each are posted, while the required work area performed. The certified renovator must available either onsite or by telephone at a certify that all of the above information	n abatement project and shall learance of work areas. At al shall be onsite or available by nore than 2 hours.  Trenovation project and shall containment is being establist regularly direct work being all times renovations are being correct.	be onsite during all work site preparation and other times when abatement activities are y telephone, pager, or answering service, and be physically present when the required signs hed, and while required work area cleaning is performed by other individuals and must be ng conducted.					
XII. XIII.	ABATEMENT A certified supervisor is required for each during the post-abatement cleanup and cl being conducted, the certified supervisor able to be present at the work site in no memory.  RENOVATION A certified renovator is required for each are posted, while the required work area performed. The certified renovator must available either onsite or by telephone at a certify that all of the above information Print	n abatement project and shall learance of work areas. At al shall be onsite or available by nore than 2 hours.  Trenovation project and shall containment is being establist regularly direct work being all times renovations are being correct.  Signature	be onsite during all work site preparation and all other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs hed, and while required work area cleaning is performed by other individuals and must be ag conducted.  Date 3 15 26					
XII. XIII.	ABATEMENT A certified supervisor is required for each during the post-abatement cleanup and cleaning conducted, the certified supervisor stable to be present at the work site in no memory.  RENOVATION A certified renovator is required for each are posted, while the required work area performed. The certified renovator must available either onsite or by telephone at a certify that all of the above information Print Chris Collins  Contact information for return mail or questions.	n abatement project and shall learance of work areas. At al shall be onsite or available by nore than 2 hours.  Trenovation project and shall containment is being establist regularly direct work being all times renovations are being correct.  Signature	be onsite during all work site preparation and all other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs hed, and while required work area cleaning is performed by other individuals and must be ag conducted.  Date 3 15 26					
XII. XIII.	ABATEMENT A certified supervisor is required for each during the post-abatement cleanup and cleaning conducted, the certified supervisor stable to be present at the work site in no memory.  RENOVATION A certified renovator is required for each are posted, while the required work area performed. The certified renovator must available either onsite or by telephone at a certify that all of the above information Print Chris Collins  Contact information for return mail or qualiting Address: 4979 CLIFF GOO	a abatement project and shall learance of work areas. At al shall be onsite or available by nore than 2 hours.  Trenovation project and shall containment is being establist regularly direct work being all times renovations are being correct.  Signature  OKIN BLVD	be onsite during all work site preparation and all other times when abatement activities are y telephone, pager, or answering service, and be physically present when the required signs hed, and while required work area cleaning is performed by other individuals and must be an conducted.  Date 3 15 26					
XII. XIII.	ABATEMENT A certified supervisor is required for each during the post-abatement cleanup and cleaning conducted, the certified supervisor able to be present at the work site in no memory.  RENOVATION A certified renovator is required for each are posted, while the required work area performed. The certified renovator must available either onsite or by telephone at a certify that all of the above information print Chris Collins  Contact information for return mail or qualling Address: 4979 CLIFF GOO City: TUPELO	a abatement project and shall learance of work areas. At al shall be onsite or available by nore than 2 hours.  Trenovation project and shall containment is being establist regularly direct work being all times renovations are being correct.  Signature  OKIN BLVD	be onsite during all work site preparation and all other times when abatement activities are y telephone, pager, or answering service, and be physically present when the required signs hed, and while required work area cleaning is performed by other individuals and must be an conducted.  Date 3 15 26					
XII. XIII.	ABATEMENT A certified supervisor is required for each during the post-abatement cleanup and cleaning conducted, the certified supervisor stable to be present at the work site in no memory.  RENOVATION A certified renovator is required for each are posted, while the required work area performed. The certified renovator must available either onsite or by telephone at a certify that all of the above information Print Chris Collins  Contact information for return mail or qualiting Address: 4979 CLIFF GOO	a abatement project and shall learance of work areas. At al shall be onsite or available by nore than 2 hours.  Trenovation project and shall containment is being establist regularly direct work being all times renovations are being correct.  Signature	be onsite during all work site preparation and all other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs hed, and while required work area cleaning is performed by other individuals and must be ag conducted.  Date 3 15 26					

**Lead Notifications** 

P.O. Box 2261, Jackson, MS 39225

Page 2

EMAIL TO: notifications@mdeq.ms.gov