209394

## Mississippi Office of Pollution Control Lead-Based Paint Abatement/Renovation Notification



MDEQ Us Email		Hand Delivery	Postmark (mail or	ily)	Date Received 4/04/2025	AI Nui	nber	
lease ch	eck all ap	Abatement plicable boxes for bestos notification	the type of Notif	ication: 🔳	Original Revis	ion [ Cancel	4 llation Emergency	
	Target Ho Child-Occ	cupied Facility:	]	sta Avo				
		Address Project S			39648	o Pike		
		f Units to be Abate						
				ie building.				
		NG OWNER IN	FORMATION					
		Everette Clark	nesota Ave	a. I	AcComb	a MS	30649	
		f Owner: 720 Minr Number: ( <sup>601</sup> ) 7		City: <u>"</u>	WOODIIID	State:	Zlb: 29049	
	•		•,					
		MENT/RENOV				Ŋ		
	Name of Certified Lead Abatement/Renovator Firm: John Tew							
	Firm Certification Number: PBR-00010112 Telephone Number: (334) 378-9231 Exp. Date: 06/04/2025							
	Address	of Certified Firm	•					
	City: Lau	rel		_State: MS		Zip Code	:: <u>39443</u>	
IV.	INSPEC	TION INFORM	IATION					
	Name of	Renovator/Insp	ector/Risk Asse	ssor Cond	acting Inspection	n:		
	Certificat	tion Number:	Ex	p. Date:	Date	Inspection C	onducted:	
	Test Method Used & Manufacturer of Testing Equipment:							
	For Paint	Chip Analysis, I	Name of Laborat	ory:	Certific	cation Numb	er:	
V.	GENER	AL CONTRAC	FOR (Other)					
	Name of Firm: Windows USA							
		iling Address: PC		al, AR 71968	3			
		Person: Christine \	<u>`</u>	<u>:</u>	Telephone Nur	nher (501) 7	60-0292	
					_ rerepriorie rvai			
		CT DATES ject Start: 04	/16 /2025	Lea	d Project Stop: _	04 / 16	/2025	
	Abateme	nt/Renovation to	be done during	what time?	■Day (5 a.m. – Night (8 p.m.	<del>-</del>	]Evening (5 p.m. – 8 p.: ]Weekend	
VII.	DESCRI	PTION OF PRO	OCEDURES TO	D BE USEI	(CHECK ALI	L THAT AP	PLY)	
	Wet S	Sanding inment Explain	Component Re	emoval	Heat Gun Negative		Encapsulation Enclosure	

## VIII.DESCRIPTION OF RENOVATION ACTIVITIES TO BE COMPLETED (INCLUDING COMPONENTS TO BE AFFECTED)

Retro Fit Pocket Replacement of Existing Windows with New Vinyl Windows

IX.	WASTE TRANSPORTER							
	Name: John Tew							
	Full Mailing Address: 30 Triangle Dr							
	City: Laurel	State: MS	Zip Code: 39443					
	Contact: John Tew	Telephone Number	: ( <u>334</u> ) <u>378-9231</u>					
Х.	WASTE LEAD DISPOSAL SITE							
	Site Name: Republic Services Little Dixie Landfill							
	Physical Address: 1716 N County Line	Rd						
	Full Mailing Address:City: Ridgeland	State: MS	Zip Code: 39157					
XI.	DISPOSAL SITE FOR DEBRIS OT							
	Site Name:							
	Physical Address:							
	Full Mailing Address:							
			Zip Code:					
	y - <u></u>							
	Contact Person:	Telephone Numbe	ST. ()					
	Contact Person:  NOTE: All debris (other than lead) should	Telephone Number go to an authorized Rubbi	sh Site, or to a permitted sanitary landfill.					
XII.	Contact Person:  NOTE: All debris (other than lead) should  ABATEMENT	Telephone Number go to an authorized Rubbi	sh Site, or to a permitted sanitary landfill.					
XII.	Contact Person:  NOTE: All debris (other than lead) should ABATEMENT	batement project and shall rance of work areas. At all all be onsite or available by	be onsite during all work site preparation and other times when abatement activities are					
	Contact Person:  NOTE: All debris (other than lead) should ABATEMENT  A certified supervisor is required for each a during the post-abatement cleanup and clea being conducted, the certified supervisor shall be a conducted.	batement project and shall rance of work areas. At all all be onsite or available by	be onsite during all work site preparation and other times when abatement activities are					
	Contact Person:  NOTE: All debris (other than lead) should ABATEMENT  A certified supervisor is required for each a during the post-abatement cleanup and clea being conducted, the certified supervisor she able to be present at the work site in no more. RENOVATION  A certified renovator is required for each results.	batement project and shall be rance of work areas. At all all be onsite or available by than 2 hours.  Showation project and shall be not a being established all all the gularly direct work being p	be onsite during all work site preparation and other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs ed, and while required work area cleaning is erformed by other individuals and must be					
XIII	Contact Person:  NOTE: All debris (other than lead) should ABATEMENT  A certified supervisor is required for each a during the post-abatement cleanup and clea being conducted, the certified supervisor shable to be present at the work site in no more. RENOVATION  A certified renovator is required for each reare posted, while the required work area conperformed. The certified renovator must re-	batement project and shall be rance of work areas. At all all be onsite or available by than 2 hours.  Showation project and shall be nationment is being establishing times renovations are being times renovations are being	be onsite during all work site preparation and other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs ed, and while required work area cleaning is erformed by other individuals and must be					
XIII	Contact Person:  NOTE: All debris (other than lead) should ABATEMENT  A certified supervisor is required for each a during the post-abatement cleanup and clea being conducted, the certified supervisor shable to be present at the work site in no more. RENOVATION  A certified renovator is required for each reare posted, while the required work area comperformed. The certified renovator must reavailable either onsite or by telephone at all. CERTIFICATION OF ACCURACY I certify that all of the above information is	batement project and shall a rance of work areas. At all all be onsite or available by re than 2 hours. enovation project and shall be ntainment is being establish regularly direct work being p times renovations are being	be onsite during all work site preparation and other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs ed, and while required work area cleaning is erformed by other individuals and must be conducted.					
XIII	Contact Person:  NOTE: All debris (other than lead) should ABATEMENT  A certified supervisor is required for each a during the post-abatement cleanup and clea being conducted, the certified supervisor shable to be present at the work site in no more. RENOVATION  A certified renovator is required for each reare posted, while the required work area comperformed. The certified renovator must reavailable either onsite or by telephone at all.  CERTIFICATION OF ACCURACY	batement project and shall a rance of work areas. At all all be onsite or available by re than 2 hours. enovation project and shall be ntainment is being establish regularly direct work being p times renovations are being	be onsite during all work site preparation and other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs ed, and while required work area cleaning is erformed by other individuals and must be					
XIII	Contact Person:  NOTE: All debris (other than lead) should ABATEMENT  A certified supervisor is required for each a during the post-abatement cleanup and clea being conducted, the certified supervisor shable to be present at the work site in no more. RENOVATION  A certified renovator is required for each reare posted, while the required work area comperformed. The certified renovator must reavailable either onsite or by telephone at all CERTIFICATION OF ACCURACY I certify that all of the above information is Print John Tew  Contact information for return mail or questions.	batement project and shall brance of work areas. At all all be onsite or available by the than 2 hours.  enovation project and shall brainment is being establish egularly direct work being p times renovations are being to correct.	be onsite during all work site preparation and other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs ed, and while required work area cleaning is erformed by other individuals and must be conducted.  Date 4.4.25					
XIII	Contact Person:  NOTE: All debris (other than lead) should ABATEMENT  A certified supervisor is required for each a during the post-abatement cleanup and clea being conducted, the certified supervisor she able to be present at the work site in no more. RENOVATION  A certified renovator is required for each reare posted, while the required work area comperformed. The certified renovator must reavailable either onsite or by telephone at all. CERTIFICATION OF ACCURACY I certify that all of the above information is Print John Tew  Contact information for return mail or quest Mailing Address: 30 Triangle Dr	batement project and shall be rance of work areas. At all all be onsite or available by the than 2 hours.  enovation project and shall be nationment is being establish egularly direct work being p times renovations are being times renovations are being to correct.  Signature	be onsite during all work site preparation and other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs ed, and while required work area cleaning is erformed by other individuals and must be conducted.  Date 4.25					
XIII	Contact Person:  NOTE: All debris (other than lead) should ABATEMENT  A certified supervisor is required for each a during the post-abatement cleanup and clea being conducted, the certified supervisor she able to be present at the work site in no more. RENOVATION  A certified renovator is required for each reare posted, while the required work area comperformed. The certified renovator must reavailable either onsite or by telephone at all. CERTIFICATION OF ACCURACY I certify that all of the above information is Print John Tew  Contact information for return mail or quest Mailing Address: 30 Triangle Dr  City: Laurel	batement project and shall be rance of work areas. At all all be onsite or available by than 2 hours.  The covation project and shall be notainment is being establish regularly direct work being p times renovations are being correct.  Signature  State:	be onsite during all work site preparation and other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs ed, and while required work area cleaning is erformed by other individuals and must be conducted.  Date 4.25  Tation on this Notice					
XIII	Contact Person:  NOTE: All debris (other than lead) should ABATEMENT  A certified supervisor is required for each a during the post-abatement cleanup and clea being conducted, the certified supervisor she able to be present at the work site in no more. RENOVATION  A certified renovator is required for each reare posted, while the required work area comperformed. The certified renovator must reavailable either onsite or by telephone at all. CERTIFICATION OF ACCURACY I certify that all of the above information is Print John Tew  Contact information for return mail or quest Mailing Address: 30 Triangle Dr	batement project and shall be rance of work areas. At all all be onsite or available by than 2 hours.  The covation project and shall be notainment is being establish regularly direct work being p times renovations are being correct.  Signature  State:	be onsite during all work site preparation and other times when abatement activities are telephone, pager, or answering service, and be physically present when the required signs ed, and while required work area cleaning is erformed by other individuals and must be conducted.  Date 4.25					

P.O. Box 2261, Jackson, MS 39225