



**VIII. DESCRIPTION OF RENOVATION ACTIVITIES TO BE COMPLETED (INCLUDING COMPONENTS TO BE AFFECTED)**

Retro Fit Pocket Replacement of Existing Windows with New Vinyl Windows

**IX. WASTE TRANSPORTER**

Name: Gary Ogle

Full Mailing Address: 126 Cape Charles

City: Brandon State: MS Zip Code: 39047

Contact: Gary Ogle Telephone Number: (601) 862-8033

**X. WASTE LEAD DISPOSAL SITE**

Site Name: Canton Sanitary Landfill

Physical Address: 303 Soldiers Colony Road

Full Mailing Address: \_\_\_\_\_

City: Canton State: MS Zip Code: 39046

**XI. DISPOSAL SITE FOR DEBRIS OTHER THAN LEAD**

Site Name: \_\_\_\_\_

Physical Address: \_\_\_\_\_

Full Mailing Address: \_\_\_\_\_

City: \_\_\_\_\_ State: \_\_\_\_\_ Zip Code: \_\_\_\_\_

Contact Person: \_\_\_\_\_ Telephone Number: (\_\_\_\_) \_\_\_\_\_

NOTE: All debris (other than lead) should go to an authorized Rubbish Site, or to a permitted sanitary landfill.

**XII. ABATEMENT**

A certified supervisor is required for each abatement project and shall be onsite during all work site preparation and during the post-abatement cleanup and clearance of work areas. At all other times when abatement activities are being conducted, the certified supervisor shall be onsite or available by telephone, pager, or answering service, and able to be present at the work site in no more than 2 hours.

**XIII. RENOVATION**

A certified renovator is required for each renovation project and shall be physically present when the required signs are posted, while the required work area containment is being established, and while required work area cleaning is performed. The certified renovator must regularly direct work being performed by other individuals and must be available either onsite or by telephone at all times renovations are being conducted.

**XIV. CERTIFICATION OF ACCURACY**

I certify that all of the above information is correct.

Print Gary Ogle Signature Gary Ogle Date 5/23/2025

Contact information for return mail or questions concerning the information on this Notice

Mailing Address: 126 Cape Charles

City: Brandon State: MS Zip Code: 39047

Contact: Gary Ogle Telephone Number: (601) 862-8033

Email: gary.ogle@windowsusa.com

Refer to fee schedule to calculate required notification fee. Notification fee must be submitted with notification.

EMAIL TO: notifications@mdeq.ms.gov

MAIL COPY TO: **Mississippi Department of Environmental Quality  
Lead Notifications  
P.O. Box 2261, Jackson, MS 39225**