MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: ☑Email □Mail □Hand Delivery	Postmark (ma	il only)	Date Re	ceived 2/21/2025	Al Number	
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): Original						
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation						
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): University MS SOC Bldg						
Bldg. Name: SOC Building						
Address: 2301 S Lamar Blvd						
_{City:} Oxford		State: MS		Zip: 38655		
Site Location: ELEC Site, South Wing		Ţ-		Tel: 662-915-6767		
Building Size: 22,000 sqft		# of Floors: 1		Age in Years: 30 +/-		
Present Use: Vacant		Prior Use: Early Learning Evaluation Center				
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)						
OWNER NAME: University of MS						
Address: 164 Jeanette Phillips Drive						
City: University		State: MS		_{Zip:} 38677		
Contact: Heather Applewhite				_{Tel:} 662-915-6767		
ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.						
Address: P.O. Box 343012						
City: Memphis		State: TN		Zip: 38184-3012	3	
Contact: Dwight Grayson				_{Tel:} 901-507-1203		
Certification Number: ABC00001660 William H Stamps		Expiration I		Date: 02/23/2025 02/7/2026		
OTHER OPERATOR: n/a						
Address:						
City:		State:		Zip:		
Contact:				Tel:		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes						
WAS ASBESTOS PRESENT? (Yes/No): Yes Inspection Date: 06/25/2024				4		
Inspecto: Brewer L Gilliland Certification Number: ABI-00011818 Expiration Date: 09/12/2025						
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Bulk Sampling, PLM Methods; Floor Tile & Mastic, cove base, duct joint glue, fire caulk, sink soundproofing, sheet vinyl, ceramic tile grout, cove base mastic, exterior window/door caulk, brick mortar, silver roof coating, roll roofing, pipe mastic, CMI mortar, pipe joints, hot water tank insulation, plaster, vent pipe						
VII. QUANTITY OF RACM TO BE REMOVED: 20,000sqft VAT/20,000sqft Mastic/100sf hot water tank insulation						
Pipes (LN FT): n/a Surface Area (SQ FT): 1,200/1,200/400 Volume of Facility Components (CU FT): n/a						
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 30 LF transite vent pipe						
Category I: n/a	Category I: n/a Category II: 30 LF					
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 03/10/2025 Complete: 03/28/2025						
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 03/10/2025 Complete: 03/28/2025						

Removal of ACM using hand tools and wet	methods	(S) TO BE USED:				
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING DEMOLITION OR RENOVATION SITE: Containment as required, negative pressure						
XIII. WASTE TRANSPORTER #1 SASI						
Name: SASI Memphis						
Address: 4009 Broadway Rd		00.00				
_{City:} Bartlett	State: TN	Zip: 38135				
Contact Person: Dwight Grayson						
WASTE TRANSPORTER #2 L&T Services LLC		-				
Name: L&T Services LLC ·						
Address: 2170 Highway 51						
City: Hernando	State: MS	Zip: 38632				
Contact Person: Carlton Gibson		Tel: 662-429-7335				
XIV. WASTE DISPOSAL SITE WM The Tunica Landfill						
Name: WM The Tunica Landfill						
Address: 6035 Bowdre Rd						
City: Robinsonville	State: MS	Zip:				
Contact Person: Carlton Gibson		Tel: 901-331-7187				
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:						
Name: n/a	, Title:					
Authority: n/a						
Date of Order (MM/DD/YY): n/a	Date Ordered	to Begin (MM/DD/YY):				
XVI. FOR EMERGENCY RENOVATIONS: n/a						
Date and Hour of Emergency (MM/DD/YY): n/a						
Date and Hour of Emergency (MM/DD/YY): 11/4						
Description of the sudden unexpected event:						
Description of the sudden unexpected event: n/a						
Description of the sudden unexpected event:	d cause equipment damage o	r an unreasonable financial burden:				
Description of the sudden unexpected event: n/a Explanation of how the event caused unsafe conditions or woul n/a XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLI All work will cease, workers will be remove	IN THE EVENT THAT UNEX ED, PULVERIZED, OR REDU ed from site, MDEQ	PECTED ASBESTOS IS FOUND OR PREVIOUSLY ICED TO POWDER: will be called for an inspection				
Description of the sudden unexpected event: n/a Explanation of how the event caused unsafe conditions or woul n/a XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED NONERIABLE ASTESTOS MATERIAL BECOMES CRUMBLI	IN THE EVENT THAT UNEX ED, PULVERIZED, OR REDU ed from site, MDEQ ROVISIONS OF THIS REGUL DEVIDENCE THAFTHE REG	PECTED ASBESTOS IS FOUND OR PREVIOUSLY ICED TO POWDER: will be called for an inspection 7 ATION (40 CFR PART 61, SUBPART M) WILL BE QUIRED TRAINING HAS BEEN ACCOMPLISHED BY				
Description of the sudden unexpected event: n/a Explanation of how the event caused unsafe conditions or would n/a XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLI All WORK WIll Cease, Workers will be removed the purple of the DEMOLITION OF RENOVATION. AND AND THE DEMOLITION OF RENOVATION. AND THE DEMOLITION OF RENOVATION.	IN THE EVENT THAT UNEX ED, PULVERIZED, OR REDU ed from site, MDEQ ROVISIONS OF THIS REGUL DEVIDENCE THAT THE REC RING NORMAL BUSINESS I	PECTED ASBESTOS IS FOUND OR PREVIOUSLY ICED TO POWDER: will be called for an inspection ? ATION (40 CFR PART 61, SUBPART M) WILL BE QUIRED TRAINING HAS BEEN ACCOMPLISHED BY HOURS.				
Description of the sudden unexpected event: n/a Explanation of how the event caused unsafe conditions or woul n/a XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLI All Work will cease, workers will be remove XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PRONSITE DURING THE DEMOLITION OR RENOVATION, ANI THIS PERSON WILL BE AVAILABLE FOR INSPECTION DU William Stamps Type or Print Name	IN THE EVENT THAT UNEX ED, PULVERIZED, OR REDU ed from site, MDEQ ROVISIONS OF THIS REGUL D EVIDENCE THAT THE REC RING NORMAL BUSINESS I	PECTED ASBESTOS IS FOUND OR PREVIOUSLY ICED TO POWDER: Will be called for an inspection ? ATION (40 CFR PART 61, SUBPART M) WILL BE QUIRED TRAINING HAS BEEN ACCOMPLISHED BY HOURS.				
Description of the sudden unexpected event: n/a Explanation of how the event caused unsafe conditions or would n/a XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLI All WORK WIll Cease, Workers will be removed the condition of the person will be removed this person will be available for inspection du William Stamps	IN THE EVENT THAT UNEX ED, PULVERIZED, OR REDU ed from site, MDEQ ROVISIONS OF THIS REGUL D EVIDENCE THAT THE REC RING NORMAL BUSINESS I	PECTED ASBESTOS IS FOUND OR PREVIOUSLY ICED TO POWDER: will be called for an inspection ? ATION (40 CFR PART 61, SUBPART M) WILL BE QUIRED TRAINING HAS BEEN ACCOMPLISHED BY HOURS.				