

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

| | | | |
|---|---|--|-----------|
| MDEQ Use Only: <input type="checkbox"/> Email <input checked="" type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery | Postmark (mail only) 5/2/22 | Date Received 5/4/22 | AI Number |
| I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): O= ORIGINAL | | | |
| II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R= RENOVATION | | | |
| III. FACILITY DESCRIPTION (Include building name, number and floor or room number): | | | |
| Bldg. Name: South Gate Subdivision | | | |
| Address: 105 AQUARIUS | | | |
| City: INDIANOLA | State: MS | Zip: 38751 | |
| Site Location: 304 PORTER DRIVE INDIANOLA, MS | | Tel: 662-843-5060 | |
| Building Size: 1/32 SF | # of Floors: 1 | Age in Years: 25+- | |
| Present Use: VACANT | Prior Use: SINGLE FAMILY DWELLING | | |
| IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator) | | | |
| OWNER NAME: South Gate Subdivision | | | |
| Address: 105 AQUARIUS | | | |
| City: INDIANOLA | State: MS | Zip: 38751 | |
| Contact: Chris Collins | | Tel: 662-843-5060 | |
| ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC | | | |
| Address: P.O. BOX 133 | | | |
| City: DELTA CITY | State: MS | Zip: 39061 | |
| Contact: Jimmy Bell | | Tel: 662-820-2124 | |
| Certification Number: ABC-00001282 | Expiration Date: 1/5/2023 | | |
| OTHER OPERATOR: Roy Collins Construction, INC. | | | |
| Address: P.O. BOX 1008 / 406 3rd street | | | |
| City: CLEVELAND | State: MS | Zip: 38732 | |
| Contact: Chris Collins | | Tel: 662-843-5060 | |
| V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES | | | |
| WAS ASBESTOS PRESENT? (Yes/No): YES (Floor tile/mastic) | | Inspection Date: 8/16-18/2021 | |
| Inspector: MARK R. WALTERS | Certification Number: ABI-00006317 | Expiration Date: 7/28/2022 | |
| VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: FLOOR TILE, CEILING, WALLS, ROOF, LEAD PAINT. THE SAMPLES WERE SUBMITTED TO EMSL ANALYTICAL, INC. BATON ROUGE, LA. USING THE PLM METHOD | | | |
| VII. QUANTITY OF RACM TO BE REMOVED: | | | |
| Pipes (LN FT): 0 | Surface Area (SQ FT): Floor tile/mastic | Volume of Facility Components (CU FT): 0 | |
| VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: | | | |
| Category I: <input checked="" type="checkbox"/> | | Category II: | |
| IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 6/15/2022 | | Complete: 8/18/2022 | |
| X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 2/18/2022 | | Complete: 12/20/2023 | |

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Wet method, Containment, Neg-Air, Double Bag, Drop Tags
Independent Air Clearance.

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

PLACE SIGNS AT ALL ENTRANCES PLACE POLY OVER ALL WINDOWS AND DOORS. WET, REMOVE, DOUBLE BAG, DROP TAG, TAPE CLOSE, PLACE IN TO LINED DUMPSTOR

XIII. WASTE TRANSPORTER #1

Name: HORTON WASTE SERVICES

Address: 601 SUNFLOWER Rd.

City: CLEVELAND

State: MS

Zip: 38732

Contact Person: STEVE HORTON

Tel: 662-588-5092

WASTE TRANSPORTER #2 N/A

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: LEXCORE COUNTY LANDFILL

Address: 15200 HWY 49E SOUTH

City: SIDON

State: MS

Zip:

Contact Person: MABEL BROWN

Tel: 662-455-6477

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: N/A

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLER, PULVERIZED, OR REDUCED TO POWDER:

REMAIN UNDER CONTAINMENT / NEG-AIR PRESSURE, STOP WORK, CONTACT OWNER / MDEQ OF CHANGE FOLLOW MDEQ DIRECTIONS.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell

Type or Print Name

Jimmy Bell
(Signature of Owner/Operator)

5/2/2022

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Jimmy Bell

Type or Print Name

Jimmy Bell
(Signature of Owner/Operator)

5/2/2022

(Date)