

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 5.13.2022	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):		R = REVISED		
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):		RENOVATIONS		
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: THE FORMER GOODY'S STORE				
Address: 1229 SUNSET DRIVE (SPACE C)				
City: GRENADA	State: MS	Zip: 38901		
Site Location: 1229 SUNSET DRIVE, (SPACE C) GRENADA, MS		Tel: 601 953-3432		
Building Size: 11,000 SF	# of Floors: 1	Age in Years: 20+		
Present Use: VACANT	Prior Use: CLOTHING STORE			
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: ACTION PROPERTIES				
Address: 110 JERRY CLOWER BLVD., N # W				
City: YAZOO CITY	State: MS	Zip: 39194		
Contact: STEVE PHILLIPS	Tel: 601 953-3432			
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC				
Address: P.O. BOX 133				
City: DELTA CITY	State: MS	Zip: 39061		
Contact: JIMMY BELL	Tel: 662-820-2124			
Certification Number: ABC-00001282	Expiration Date: 1/5/2023			
OTHER OPERATOR: ACTION PROPERTIES				
Address: 110 JERRY CLOWER BLVD., N # W				
City: YAZOO CITY	State: MS	Zip: 39194		
Contact: STEVE PHILLIPS	Tel: 601-953-3432			
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): (YES) ^{COMPLETED} YELLOW MASTIC UNDER CARPET				
WAS ASBESTOS PRESENT? (Yes/No) (YES) BROWN DOTS UNDER MIRRORS Inspection Date: 2/22/2022				
Inspector: PAUL ANDERSON	Certification Number: ABI-00001686	Expiration Date: 7/9/2022		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: REMOVED PREVIOUS ASBESTOS. REMAINING 14 MIRRORS BROWN DOTS. DECIDED NOT TO KEEP ANY MIRRORS IN DRESSING ROOMS + BATHROOMS BROWN GLUE DOTS CONTAINS ASBESTOS				
VII. QUANTITY OF RACM TO BE REMOVED: 14 MIRRORS + BROWN DOTS GLUE				
Pipes (LN FT):	Surface Area (SQ FT): 100 SF	Volume of Facility Components (CU FT):		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I: <input checked="" type="checkbox"/>	Category II:			
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 5/16/2022		Complete: 5/18/2022		
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 5/19/2022		Complete: 7/19/2022		

"Rev"

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

PLACE 6 mil POLY under mirrors, wet BETWEEN mirrors AND WALL with MASTIC REMOVAL, USE FLATBAR TO PRY APART MIRROR FROM WALL. CONTINUE TO wet with mastic REMOVAL

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

WET with MASTIC REMOVAL MAKES Brown Dots DISOLVE, SCRAP FROM WALL with plastic ~~scrap~~ SCRAPPER, PLACE INTO Double BAG. WRAP CLEAN with TOWEL, PLACE TOWEL INTO Double BAG, TAG/TAPE/Dispose AS ASBESTOS

XIII. WASTE TRANSPORTER #1

Name: BELL ENVIRONMENTAL SERVICES, LLC

Address: P.O. BOX 133

City: DELTA City

State: MS

Zip: 39061

Contact Person: Jimmy Bell

Tel: 662-820-2124

WASTE TRANSPORTER #2 N/A

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: LEFLORE County Landfill

Address: 15200 US HWY 49 E South

City: SIDON

State: MS

Zip: 38954

Contact Person: MABEL BROWN

Tel: 662-455-6477

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

N/A

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS:

N/A

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:

PLACE WORK AREA UNDER CONTAINMENT DURING REMOVAL
MIRRORS LOCATED IN Dressing Rooms AND Bathrooms

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell

Type or Print Name

Jimmy Bell
(Signature of Owner/Operator)

5/13/2022

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Jimmy Bell

Type or Print Name

Jimmy Bell
(Signature of Owner/Operator)

5/13/2022

(Date)