"Rev"

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

P1

MDEQ Use Only: ☑Email ☐Mail ☐Hand Delivery	Postmark (mail only)	Date Received 9.14.2022	AI Number

I. **Type of Notification** (O=Original R=Revised C=Canceled A= Annual): R = Revised Address / Start Date

II. **TYPE OF OPERATION** (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): E = Emer, Demo / Cleanup

III. **FACILITY DESCRIPTION** (Include building name, number and floor or room number):

Bldg. Name: Collins Corner Store

Address: 129/127 Broadway Street

City: Yazoo City	State: MS	Zip: 39194
Site Location: 129 Broadway St., Yazoo City, MS		Tel: 662 571 5898
Building Size: 4,452 Sq ft	# of Floors: 2	Age in Years: 60 +
Present Use: Vacant	Prior Use: Clothing Store	

IV. **FACILITY INFORMATION** (Identify owner, asbestos removal contractor, and other operator)

OWNER NAME: Cobie Collins

Address: 1040 Grady Ave

City: Yazoo City	State: MS	Zip: 39194
Contact: Cobie Collins		Tel: 662 571-5898

ASBESTOS REMOVAL CONTRACTOR: Bell Environmental Services, LLC.

Address: P.O. Box 133

City: Delta City	State: MS	Zip: 39061
Contact: Jimmy Bell		Tel: 662-820-2124
Certification Number: ABC-0000/282		Expiration Date: 1/5/2023

OTHER OPERATOR: City of Yazoo City Building Inspector

Address: P.O. Box 689

City: Yazoo City	State: MS	Zip: 39194
Contact: Danny Neely		Tel: 662-746-1401

V. **WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS?** (Yes/No): YES

WAS ASBESTOS PRESENT? (Yes/No): YES		Inspection Date: 8/31/2022
Inspector: Terrance Hurssey	Certification Number: ABI-00001050	Expiration Date: 9/10/2022

VI. **SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:**

Sampled: Roofing materials, wall paneling, plaster, brick, brick mortar. Procedures used to Detect presence of Asbestos. PLM Method, Analytical by Eurofins CEI 730 SE. Maynard Rd., Cary, NC 27511

VII. **QUANTITY OF RACM TO BE REMOVED:** Roofing materials / Plaster Texture

Pipes (LN FT): 0	Surface Area (SQ FT): 4,452	Volume of Facility Components (CU FT):

VIII. **QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:**

Category I: —	Category II:

IX. **SCHEDULED DATES ASBESTOS REMOVAL** (MM/DD/YY) Start: 9/14/2022 Complete: 9/17/2022

X. **SCHEDULED DATES DEMO/RENOVATION** (MM/DD/YY) Start: 9/14/2022 Complete: 9/17/2022

(P2)

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:
Wet method, Lined Dumpster, Tarp, Haul To Approved Landfill. Barricade Debris 15 ft. From Streets. Work Debris Toward Center of Building while loading

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: Set up Continue Water Sprinkle System over Debris. Remove Roof and All Materials Related To Asbestos and load onto Dumpster using Trackhoe with Thumb Attachment. On Site Air Monitor/Inspector

XIII. WASTE TRANSPORTER #1

Name: Helton Trucking Services

Address: 677 Sunflower Dr.

City: Yazoo City | State: MS | Zip: 39194

Contact Person: Kevin Helton | Tel: 662 571 5115

WASTE TRANSPORTER #2 N/A

Name:

Address:

City: | State: | Zip:

Contact Person: | Tel:

XIV. WASTE DISPOSAL SITE Asbestos

Name: Leflore County Landfill

Address: 15200 US Hwy 49 E, South

City: Sidon | State: MS | Zip: 38954

Contact Person: Mabel Brown | Tel: 662 455-6477

NOW Asbestos Disposal Site; Phone # 662.571.4604
Yazoo Rubbish Site; Contact: Mac Gaston
3342 Old Hwy 3, Yazoo City, MS 39194

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: Cobie Collins | Title: County Supervisor Yazoo City

Authority:

Date of Order (MM/DD/YY): | Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: Building Collapse into Street Causing Traffic Light Failer.

Date and Hour of Emergency (MM/DD/YY): 9/8/2022 Side of Building show signs of Caving out,

Description of the sudden unexpected event: more Bricks Falling into Streets from vibrations from Car Traffic and Trains Vibrations. unstable Building

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:
Danger To Passing Traffic / No Red Light or street Lights
Danger To People Walking on Sidewalk.

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:
Continue To Keep Wet; Double Bag Any Crumbled Debris. Continue To Inspect while Cleaning up Debris.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell — Type or Print Name | Jimmy Bell — (Signature of Owner/Operator) | 9/8/2022 — (Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Jimmy Bell — Type or Print Name | Jimmy Bell — (Signature of Owner/Operator) | 9/8/2022 — (Date)