

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

| | | | | |
|--|--|------------------------------------|--|-----------|
| MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery | | Postmark (mail only) | Date Received 10-17-2022 | AI Number |
| I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): Original | | | Revision #1 Corrected | |
| II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation | | | | |
| III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Goodhaven Apartments | | | | |
| Bldg. Name: Units A2 A4 B4 C2 C8 & E6 | | | | |
| Address: 94 Goodhaven Dr | | | | |
| City: Goodman | | State: MS | Zip: 39079 | |
| Site Location: Interior | | Tel: 901-383-9077 | | |
| Building Size: unknown | | # of Floors: unknown | Age in Years: 50 +/- | |
| Present Use: Vacant Apts | | Prior Use: Apt Building | | |
| IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator) | | | | |
| OWNER NAME: Blue Sky Restoration Contractors LLC | | | | |
| Address: 7480 Bartlett Corporate Cove West | | | | |
| City: Bartlett | | State: TN | Zip: 38133 | |
| Contact: Mike Scott | | Tel: 901-383-9077 | | |
| ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc. | | | | |
| Address: P.O. Box 343012 | | | | |
| City: Memphis | | State: TN | Zip: 38184-3012 | |
| Contact: William Stamps | | Tel: 901-507-1203 | | |
| Certification Number: ABC00001660 | | | Expiration Date: 10/20/2022 | |
| OTHER OPERATOR: n/a | | | | |
| Address: | | | | |
| City: | | State: | Zip: | |
| Contact: | | Tel: | | |
| V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes | | | | |
| WAS ASBESTOS PRESENT? (Yes/No): Yes | | | Inspection Date: 04/21/2022 | |
| Inspector: Marvinetta Cooper | | Certification Number: ABI-00010385 | Expiration Date: 03/15/2023 | |
| VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: | | | | |
| Flooring Renovation project only - materials sampled were floor tile and mastic | | | | |
| Bulk sampling using plm methods | | | | |
| VII. QUANTITY OF RACM TO BE REMOVED: 2556 sf VAT/2556 sf Mastic | | | | |
| Pipes (LN FT): n/a | | Surface Area (SQ FT): 2556/2556 | Volume of Facility Components (CU FT): n/a | |
| VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: n/a | | | | |
| Category I: n/a | | Category II: n/a | | |
| IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 10/14/2022 | | Complete: 10/17/2022 | | |
| X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 10/14/2022 | | Complete: 10/17/2022 | | |

R1

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Removal of ACM using hand tools and wet methods

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Splashguard containment, negative pressure, hand tools, chemical stripper, double bag waste

XIII. WASTE TRANSPORTER #1 SASI

Name: SASI Memphis

Address: 4009 Broadway Rd

City: Bartlett

State: TN

Zip: 38135

Contact Person: Dwight Grayson

Tel: 901-507-1203

WASTE TRANSPORTER #2 Waste Management Memphis

Name: Waste Management Memphis

Address: 3750 Hatcher Circle

City: Memphis

State: TN

Zip: 38118

Contact Person: Carlton Gibson

Tel: 901-331-7187

XIV. WASTE DISPOSAL SITE WM The Tunica Landfill

Name: WM The Tunica Landfill

Address: 6035 Bowdre Rd

City: Robinsonville

State: MS

Zip:

Contact Person: Carlton Gibson

Tel: 901-331-7187

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: n/a

Title:

Authority: n/a

Date of Order (MM/DD/YY): n/a

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: n/a

Date and Hour of Emergency (MM/DD/YY): n/a

Description of the sudden unexpected event:

n/a

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

n/a

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

All work will cease, workers will be removed from site, MDEQ will be called for an inspection

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

William Stamps

Type or Print Name

(Signature of Owner/Operator)

09/28/2022

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Amy Adams

Type or Print Name

(Signature of Owner/Operator)

09/28/2022

(Date)

Unit A2- 679 SF floor tile and mastic

Unit A4- 506 SF floor tile and mastic

Unit B4- 171 SF floor tile and mastic

Unit C2- 458 SF floor tile and mastic

Unit C8- 458 SF floor tile and mastic

Unit E6- 284 SF floor tile and mastic

Unit A- 379 2F floor life and message
Unit A- 306 2F floor life and message
Unit B- 171 2F floor life and message
Unit C- 428 2F floor life and message
Unit D- 158 2F floor life and message
Unit E- 184 2F floor life and message