## MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

Mail notification to. Mil	EQ Asbestos i	ina Bena Branen	, oro E.	rimite street, suc	10011, 1110 07 101			
MDEQ Use Only: □Email \$\infty\text{Mail} □Hand Delivery	Postmark (mail only) Date		Date R	Received Al Number				
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):								
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R								
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Main Bldg Roof & Cafeteria Roof								
Bldg. Name: Gentry High School								
Address: 801 BB King Rd								
<sub>City:</sub> Indianola		State: MS		Zip: 38751				
Site Location: 801 BB King Rd, Indianola, MS 38751				Tel: 662-884-1240				
Building Size: 70,000 sf +/-	# of Floors: 1		Age in Years: 70 +/-					
Present Use: School		Prior Use: School						
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)								
OWNER NAME: Sunflower Co Consolidated School District								
Address: 196 Martin Luther King Dr								
<sub>City:</sub> Indianola	State: MS		<sub>Zip:</sub> 39074					
Contact: Marvin Hawkins			<sub>Tel:</sub> 662-887-4919					
ASBESTOS REMOVAL CONTRACTOR: Jeff Evans, Inc d/b/a Eagle Construction								
Address: 1450 Old Brandon Rd								
<sub>City:</sub> Flowood	City: Flowood		State: MS		<sub>Zip:</sub> 39232			
Contact: Chuck Womack			Tel: 601-940-5411					
Certification Number: ABC-1799	Expiration		ion Date: 3/4/2023					
OTHER OPERATOR: Upchurch Plumbing, Inc								
Address: P. O. Box 8106								
<sub>City:</sub> Greenwood		State: MS		<sub>Zip:</sub> 38935-8106				
Contact: Scott Upchurch			Tel: 662-453-6860					
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes								
WAS ASBESTOS PRESENT? (Yes/No): Yes Inspection Date: 12/3/2021								
Inspector: Willie Nester Certification Number: ABI-2244 Expiration Date: 2/4/2022					Date: 2/4/2022			
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:								
Flashing, window caulk, plaster ceiling, ceiling tile PLM								
VII. QUANTITY OF RACM TO BE REMOVED: 500 sf flashing								
Pipes (LN FT):	Surface Area (SQ FT): 500 sf			Volume of Facility Components (CU FT):				
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: N/A								
Category I: Category II:								
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 11/1/2022 Complete: 5/30/2023								
x. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 11/1/2022 Complete: 11/30/2023								
KECEIVED								

OCT 24 2022

Removal of asbestos containing materials			(S) TO BE USED:					
			TO DDEVENT EMICS	IONS OF ASSESTOS AT THE				
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING DEMOLITION OR RENOVATION SITE:	NG CONTROL	S TO BE USED	) TO PREVENT EMISS	IONS OF ASBESTOS AT THE				
Stop work and notify competent person, keep asbestos wet, seal all critical barriers & put under negative pressure								
XIII. WASTE TRANSPORTER #1								
Name: ADS, Inc								
Address: P. O. Box 1296								
City: Clinton	State: MS		<sub>Zip.</sub> 39060-1296					
Contact Person: Mark Parkman			Tel: 601-925-0507					
WASTE TRANSPORTER #2		50.00 ±0000 Maree 04.00 10.00						
Name: Eagle Construction								
Address: 1450 Old Brandon Rd								
City: Flowood	State: MS		zip: 39232					
Contact Person: Chuck Womack			Tel: 601-940-5411					
XIV. WASTE DISPOSAL SITE								
Name: Little Dixie Landfill								
Address: 1716 North County Line Rd								
<sub>City:</sub> Ridgeland	State: MS		<sub>Zip:</sub> 39157					
Contact Person: Mike Raley			<sub>Tel:</sub> 601-982-9488					
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENC	CY, PLEASE I	DENTIFY THE A	AGENCY BELOW:					
Name:		Title:						
Authority:								
Date of Order (MM/DD/YY):	Order (MM/DD/YY): Date Ordered			o Begin (MM/DD/YY):				
XVI. FOR EMERGENCY RENOVATIONS:								
Date and Hour of Emergency (MM/DD/YY):								
Description of the sudden unexpected event:								
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:								
		eneman Chamban West L						
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED I NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLE				FOUND OR PREVIOUSLY				
Stop work & notify owner, keep wet and do	uble bag	immediatel	у					
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PRONSITE DURING THE DEMOLITION OR RENOVATION, AND THIS PERSON WILL BE AVAILABLE FOR INSPECTION DUR	EVIDENCE T	HAT THE REQU	JIRED TRAINING HAS					
Chuck Womack	V.	$\sim$	and	10/24/2022				
Type or Print Name	(Signature of O	wner/Operator)		(Date)				
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECTED CONTROL OF THE CONTROL OF T	ct. ,	1 ~		10/24/2022				
Type or Print Name	(Signature of O	wner/Operator)		(Date)				