(Side 1)

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: ☑Email ☐Mail ☐Hand Delivery	Postmark (mail only)	Date Received 11.21.2022	AI Number

I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): O = Original

II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D = Demo

III. FACILITY DESCRIPTION (Include building name, number and floor or room number):

Bldg. Name: Mitch Lundy Law Office

Address: 64 1st Street

City: Grenada | State: MS | Zip: 38901

Site Location: 64 1st Street, Grenada, MS | Tel: 662-809-8724

Building Size: 4,020 S.F. | # of Floors: 1 | Age in Years: 60 + —

Present Use: Vacant | Prior Use: Office Space

IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)

OWNER NAME: Grenada County Board of Supervisors

Address: P.O. Box 1208 | State: MS | Zip: 38901

City: Grenada | Tel: 662-417-5350

Contact: Billy Cummins

ASBESTOS REMOVAL CONTRACTOR: Bell Environmental Services, LLC

Address: P.O. Box 133 | State: MS | Zip: 39041

City: Delta City | Tel: 662-820-2124

Contact: Jimmy Bell | Expiration Date: 1/5/2023

Certification Number: ABC-0000282

OTHER OPERATOR: Grenada County Board of Supervisors

Address: P.O. Box 1208 | State: MS | Zip: 38901

City: Grenada | Tel: 662-417-5350

Contact: Billy Cummins

V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES | Inspection Date: 5/18/2017

WAS ASBESTOS PRESENT? (Yes/No): YES | Certification Number: ABI-0000 2023 | Expiration Date: 1/6/23

Inspector: Chris C. PEARSON

VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:
Walls, Roof, Floors, Ceiling, Window Chalking. All were Sampled and Sended to EMLab p+K, Phoenix, AZ 85027 using the PLM Method

Roof material and Roof Flashing and Bathroom Linoleum Contains Asbestos only

VII. QUANTITY OF RACM TO BE REMOVED: Roofing Materials, Bathroom Linoleum 4,020 S.F.

Pipes (LN FT): 0 | Surface Area (SQ FT): 4020 S.F. | Volume of Facility Components (CU FT):

VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 0

Category I: | Category II:

IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 11/26/22 | Complete: 11/28/22

X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 11/28/22 | Complete: 12/28/22