

**MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM**

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 1/5/23	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): Original				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Emergency				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Refinery				
Bldg. Name: Chevron Pascagoula Refinery				
Address: 250 Industrial Rd				
City: Pascagoula		State: MS	Zip: 39581-3201	
Site Location: 11 Plant - C-1101			Tel:	
Building Size:		# of Floors:	Age in Years: 55	
Present Use:		Prior Use:		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Chevron Products Company				
Address: 250 Industrial Road				
City: Pascagoula		State: MS	Zip: 39581-3201	
Contact: Benjamin Moore			Tel: 228-934-7553	
ASBESTOS REMOVAL CONTRACTOR: Brock Services, LLC #ABC00009559				
Address: 10343 Sam Houston Park Dr. Suite 200				
City: Houston		State: TX	Zip: 77064	
Contact: Ken Sherman			Tel: 228-990-3739	
Certification Number: ABC00009559			Expiration Date: 3/28/2023	
OTHER OPERATOR:				
Address:				
City:		State:	Zip:	
Contact:			Tel:	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): No - Assumed to be asbestos				
WAS ASBESTOS PRESENT? (Yes/No):			Inspection Date:	
Inspector:		Certification Number:	Expiration Date:	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Assumed materials are the only materials to be removed. Materials include C-1101 Column (Industrial Vessel) insulation				
VII. QUANTITY OF RACM TO BE REMOVED:				
Pipes (LN FT):		Surface Area (SQ FT): 1400	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:			Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 1/9/2023			Complete: 1/18/2023	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 1/9/2023			Complete: 1/18/2023	

**XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:**

Removal of Asbestos from C-1101 to perform CUI Inspection. Inspection is critical to process safety and must be performed in the time window specified by this notification.

**XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:**

Strip & Removal, Containment, Wet Method, Double Bagging, Glove Bag, Remove Intact, Negative Air.

**XIII. WASTE TRANSPORTER #1**

Name: Waste Management of Mississippi - Gulf Coast

Address: Pecan Grove RDF, 9685 Firetower Rd

City: Pass Christian

State: MS

Zip: 39571

Contact Person: Rick Prickett

Tel: 228-832-3144

**WASTE TRANSPORTER #2**

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

**XIV. WASTE DISPOSAL SITE**

Name: Waste Management of Mississippi - Gulf Coast

Address: Pecan Grove RDF, 9685 Firetower Rd

City: Pass Christian

State: MS

Zip: 39571

Contact Person:

Tel: 228-255-5553

**XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:**

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

**XVI. FOR EMERGENCY RENOVATIONS:**

Date and Hour of Emergency (MM/DD/YY): 01/09/2023 - 06:00

Description of the sudden unexpected event:

Unplanned CUI inspection to ensure vessel integrity (process safety)

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

The CUI inspection referenced above is critical to process safety of the vessel and must be performed in the specified time window outlined by this notification due to the timeline of the maintenance outage.

**XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:**

Work will stop. Notifications will be completed as necessary. Proper controls will be instituted.

**XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.**

Benjamin Moore

Type or Print Name



(Signature of Owner/Operator)

Digitally signed by Benjamin Moore

Date: 2022.10.11 09:13:45 -0500

1/5/2023

(Date)

**XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:**

Benjamin Moore

Type or Print Name



(Signature of Owner/Operator)

Digitally signed by Benjamin Moore

Date: 2022.10.11 09:13:53 -0500

1/5/2023

(Date)