

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

| Mail notification to: MDEQ Asbestos | and Lead Branch. | 515 E. Amite Street, Jac | kson, MS 39201 | | | | |
|--|------------------|--------------------------|--|--|--|--|--|
| MDEQ Use Only: Postmark (ma □Email □Mail □Hand Delivery | | Date Received | Al Number | | | | |
| I. Type of Notification (O-Grigina) R=Revised C=Canceled A= Annual): | | | | | | | |
| II. TYPE OF OPERATION (D-Dem) O= Ordered Demo R=Renovation E=Emer. Renovation): | | | | | | | |
| III. FACILITY DESCRIPTION (Include building name, number and floor or room number): | | | | | | | |
| Bldg. Name: Rawls Spring Baptist Church | | | | | | | |
| Address: 55 to RAWIS Spring Loop Kd | | | | | | | |
| City: Hatticsburg | State: MS | Zip: 39404~ | zip: 39464 - 39402 | | | | |
| Site Location: | | Tel: | Tel: | | | | |
| Building Size: 2400 | # of Floors: | Age in Years: / | 979 | | | | |
| Present Use: | Prior Use: | | en Styroven, e ven i i | | | | |
| IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator) | | | | | | | |
| OWNER NAME: a dam wade | | | | | | | |
| Address: Kawls Spring | | | | | | | |
| city: Hattiesbarg | State: in 5 | ZIp: 39402 | | | | | |
| Contact: | | | Tel: 601-596-6047 | | | | |
| ASBESTOS REMOVAL CONTRACTOR: | | 1.5 001 371 | ,, | | | | |
| Address: 201 hakeward Loop | | V-1111 | | | | | |
| city: Mattieslang | State: mS | zip: 3940 | 2 | | | | |
| Contact: Frederick Smith | | | Tel: 601-918-2568 | | | | |
| Certification Number: 0000 8819 Expiration Date: oct -7-2023 | | | | | | | |
| OTHER OPERATOR: | | | | | | | |
| Address: | | | 100000 | | | | |
| City: | State: | Zip: | | | | | |
| Contact: | | Tel: | The second secon | | | | |
| V, WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): | | | | | | | |
| WAS ASBESTOS PRESENT? (Yes/No): Inspection Date: | | | | | | | |
| Inspector: TUNY BIYANT Certification Number: 0000 1613 Expiration Date: May - 24 - 2023 VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: | | | | | | | |
| Transite Siding and Linolan Flooring was positive for a shestas | | | | | | | |
| Bulk sampling methods (Plm Analysis) | | | | | | | |
| | | | | | | | |
| VII. QUANTITY OF RACM TO BE REMOVED: | | | | | | | |
| Pipes (LN FT): N/FT Surface Area (SQ FT): 2 40 0 Volume of Facility Components (CU FT): | | | | | | | |
| VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: | | | | | | | |
| Category I: Category II: | | | | | | | |
| IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 2-/7-2023 Complete: 2-/9-2023 | | | | | | | |
| X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 2-20-2023 Complete: 2-23-2023 | | | | | | | |

| XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED: | | | | | | | | |
|--|---|----------------|---|-----------------------|---|--|--|--|
| USC wet methods and decon contaminants. | | | | | | | | |
| XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING DEMOLITION OR RENOVATION SITE: | NG CONTROL | S TO BE USED | TO PREVENT EMISSIO | NS OF ASBESTOS AT THE | | | | |
| Remove aspestos meterials using wet method, hand tools, pean containments & my | | | | | | | | |
| | | | | | | | | |
| Name: Frederick Environmental) | -1-6 | | 21.000000000000000000000000000000000000 | | | | | |
| Address: 201 Halkewood loop | | , | 20 (10) | | | | | |
| Contact Person: Frederick Smith | State: m | | zip: 39402 Tel: 601-918-2 | 25/8 | | | | |
| | | | Tel: 001 1 18 a | 730g | | | | |
| WASTE TRANSPORTER #2 | | | | | , | | | |
| Name: | | | | - | | | | |
| Address: | | | | | | | | |
| City: | State: | | Zip: | | | | | |
| Contact Person: Tel: | | | | | | | | |
| XIV. WASTE DISPOSAL SITE | | | | | | | | |
| Name: Pinc Belt Regional Landfill | | | | | | | | |
| Address: P. O. Ro K 384 | | | 20.006 | | | | | |
| city: Petal | State: M. | | Zip: 39 465 | 1-71 | | | | |
| Contact Person: Sams Harrison | | | Tel: 601-545-6 | 6 16 | | | | |
| XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENC | CY, PLEASE IC | DENTIFY THE A | AGENCY BELOW: | | | | | |
| Name: | | Title: | | | | | | |
| Authority: | | | | | | | | |
| ate of Order (MM/DD/YY): Date Ordered to Begin (MM/DD/YY): | | | | | | | | |
| XVI. FOR EMERGENCY RENOVATIONS: | | | | | | | | |
| Date and Hour of Emergency (MM/DD/YY): Description of the sudden unexpected event: | | | | | | | | |
| Description of the statuen anaxyothea event. | | | | | | | | |
| Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: | | | | | | | | |
| Explanation of now the event caused disable continuous of would | occuso equipin | icin damago or | all diffeasoriance in allaci | Jaidon. | | | | |
| XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED II NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLE | | | | OUND OR PREVIOUSLY | | | | |
| Stop work and call MDEQ | | | | | | | | |
| XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS. | | | | | | | | |
| Type or Print Name | (Signature of Owner/Operator) 2-7-2023 (Date) | | | | | | | |
| XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT: 4 reduction South Treduct Smith 2-7-2023 | | | | | | | | |
| Type or Print Name | (Signature of Owner/Operator) | | | (Date) | | | | |