## **MAP**

## MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: XIEmail ⊟Mail ⊟Hand Delivery	Postmark (mail only)		Date Received 07/03/2023		Al Number 38029				
I. Type of Notification (O=Original R=Revised	I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): Original								
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation									
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):									
Bidg. Name: Building 4331, Allee Hall									
Address: Corner of H Street and Fischer Street									
City: Keesler Air Force Base State: MS				Zip: 39534					
Site Location: Poplarville High School			Tel: (228)481-4874						
Building Size: approximately 50,0000		# of Floors: 2		Age in Years: 40+					
Present Use: Educational Building	Prior Use: Educational Building Prior Use:		ational	al Building					
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)									
OWNER NAME: Keesler Air F0rce Base									
Address: 508 L Street									
City: Keesler AFB		State: MS		zip: 39534					
Contact: Robin Sykes		:		Tel: (228)481-4874					
ASBESTOS REMOVAL CONTRACTOR: Global Contracting, LLC									
Address: 226 Harry Sones Road									
<sub>City:</sub> Carriere	State: MS			Zip: 39426					
Contact: Eddie Blossman				<sub>Tel:</sub> (601)795-3401					
			Expiration	piration Date: January 9, 2024					
OTHER OPERATOR: Gulf Pacific Contracting									
Address: 750 Sand Path Road ;									
<sub>City:</sub> Bonifay		<sub>State:</sub> Florida		zip: 32425-7426					
Contact:				Tel:					
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No):									
WAS ASBESTOS PRESENT? (Yes/No): Yes Inspection Date: 01/04/22									
Inspector: Charles D. Bingham Certification Number: ABI-00001348 Expiration Date: 02/12/2024									
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: HVAC Duct insulation and Mastic									
Ceiling Tiles Pipe Insulation									
Samples were analyzed by PLM with dispersion staining according to EPA Method 600/R-93/116									
VII. QUANTITY OF RACM TO BE REMOVED:									
Pipes (LN FT): 700	Surface Area (St	Q FT):		Volume of Facility Con	nponents (CU FT):				
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:									
Category I: Category II:									
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 07/17/2023 Complete: 09/30/2023									
x. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 07/17/2023 Complete: 09/30/2023									

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVA Removal of approximately 700 In ft of Ther	mal Sys	₹K, Al stem	ND METHOD( 18 Insulati	s) to be used: on (TSI) Chilled	water Piping.				
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING DEMOLITION OR RENOVATION SITE:  Wet glove bag removal,, area and clearance				TO PREVENT EMISSIO	ONS OF ASBESTOS AT THE				
XIII. WASTE TRANSPORTER #1									
Name: Global Contracting, LLC									
Address: 226 Harry Sones Road									
City: Carriere	State: MS		<sub>Zip:</sub> 39426						
Contact Person: Eddie Blossman			Tel: (601)795-3401						
WASTE TRANSPORTER #2									
Name:									
Address:									
City:	State:			Zip:					
Contact Person:				Tel:					
XIV. WASTE DISPOSAL SITE									
Name: Waste Management-Pecan Grove Landfill									
Address: 9685 Firetower Road									
<sub>City:</sub> Pass Christian	State: MS			<sub>Zip:</sub> 39571					
Contact Person: Michael Eidt			Tel:(228)255-5553		53				
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:									
Name: ;			Title:						
Authority:									
Date of Order (MM/DD/YY):		Date Ordered to Begin (MM/DD/YY):							
XVI. FOR EMERGENCY RENOVATIONS:									
Date and Hour of Emergency (MM/DD/YY):									
Description of the sudden unexpected event:									
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:									
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:									
Stop work immediately, contact regulatory authorities wait for approval of resume work.									
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.									
EDDIE BLOSSMAN (Lellist 7/03/2023									
Type or Print Name (Signature of Owner/Operator) (Date)									
EDDIE BLOSSMAN THE ABOVE INFORMATION IS CORRECT!									
Type or Print Name	(Signature of Owner/Operator) (Date)								