MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: Postmark (XEmail □Mail □Hand Delivery	(mail only)	Date Re	eceived 17-19-2023	Al Number				
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):								
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D								
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):								
Bldg. Name: City of Rolling Fork Parkway Community Center								
Address: 227 Parkway Community Center								
City: Rolling Fork,	State: MS	State: MS		Zip: 39159				
Site Location: 227 Parkway Community Center			Tel: Out of order					
Building Size: 3,500 sq. ft.	# of Floors: 1		Age in Years: Unknown					
Present Use: Vacant	Prior Use: Comm	Prior Use: Community Center						
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)								
OWNER NAME: City of Rolling Fork								
Address: P. O. Box 310								
City: Rolling Fork State: MS			Zip: 39159					
Contact: Mayor Eldridge J. Walker			Tel: 662/873-2814					
ASBESTOS REMOVAL CONTRACTOR: Advanced Environmental Consultgants, Inc.								
Address: 775 N. President Street								
City: Jackson State: MS			Zip: 39202					
Contact: Dr. DeJonnette Grantham King			Tel: 601/362-1788					
Certification Number: ABC-00002431		Expiration Date: 1/3/2024						
OTHER OPERATOR: Dynamic Group								
Address: 3045 West Fork Drive	100000							
City: Baton Rouge	State: LA	State: LA		Zip: 70816				
Contact: Mr. Chris Whiottington			Tel: 601/498-1866					
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No):								
			ction Date: 7/6/2023					
Inspector: Kristian King Certification Number: ABI-00003739 Expiration Date: 7/26/2023				Dato.				
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: PLM Testing- floor tile and mastic.								
FLINI Testing- nool tile and mastic.								
VII. QUANTITY OF RACM TO BE REMOVED:								
Binas (LN ET): Surface Are	ea (SQ FT): 2,489		Volume of Facility Co	mnonents (CILET):				
Pipes (LN FT): Surface Area (SQ FT): 2,489 Volume of Facility Components (CU FT): VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:								
Category I: 2,489 Category II:								
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 8/2/2023 Complete: 8/10/2023								
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 8/7/2023 Complete: 8/18/2023								

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED: Abatement: On completion of asbestos abatement-, floor tile, mastic, and caulking will be removed using the wet method and HEPA filter equipped vacuum. Demolition-track will be used to demoliksh builidng.							
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:							
Track hoe will be used to demolish building and transport to landfill.							
XIII. WASTE TRANSPORTER #1							
Name: Advanced Environmental Consultants, Inc.							
Address: 775 N. President Street							
City: Jackson	State: MS		Zip: 39203				
Contact Person: Dr. DeJonnette Grantham King			Tel: 601/362-1788				
WASTE TRANSPORTER #2							
Name: Dynamic Group							
Address:3045 West Fork Drive							
City: Baton Rouge	State: LA		Zip: 70816				
Contact Person: Mr. Chris Whittington			Tel: 601/498-1866				
XIV. WASTE DISPOSAL SITE							
Name: BFI Little Dixie Landfill							
Address: 1716 N. County Line Road							
City: Ridgeland	State: MS		tip: 39157				
Contact Person: -			Tel: 800/967-2488				
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: NA							
Name:	e: Title:						
Authority:							
Date of Order (MM/DD/YY): Date Ordered to Begin (MM/DD/YY):							
XVI. FOR EMERGENCY RENOVATIONS: NA							
Date and Hour of Emergency (MM/DD/YY):							
Description of the sudden unexpected event:							
ALMARIANTE INSTRUCTION OF THE SECOND							
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:							
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:							
PREVENTIVE MEASURES WILL BE IMPLEMENTED, WORK CEASE, OWNER, AND MDEQ NOTIFIED							
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.							
DeJonnette Grantham King	De Jonnette GK		ng	7/19/23			
Type or Print Name	(Signature of Owner/	Operator)	U	(Date)			
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:							
De Jonnette Grantham King Type or Print Name	(Signature of Owner/Operator)		J	7/19/23 (Date)			
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	(2.5. Liuis di Ownen	- 1-0.0101)					