MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only:  □Email □Mail □Hand Delivery	Postmark (mail only)		Date Received 2023 Al Number 374		Al Number 37466			
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):								
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R								
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Rice Hall								
Bldg. Name: MSU - Rice Hall								
Address: McKay St - MSU Campus								
<sub>City:</sub> Mississippi State		State: MS		<sub>Zip:</sub> 39762				
Site Location: MSU Campus				Tel: 662-325-2553				
Building Size: 50,000 +/-		# of Floors: 4		Age in Years: 80 +/-				
resent Use: Dorm		Prior Use: Dorm						
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)								
OWNER NAME: MSU Office of Procurement & Contracts								
Address: 610 McArthur Hall Ave								
<sub>City:</sub> Mississippi State		State: MS		zip: 39762				
Contact: Ches Fedric				Tel: 662-325-2553				
ASBESTOS REMOVAL CONTRACTOR: Jeff Evans, Inc d/b/a Eagle Construction								
Address: 1450 Old Brandon Rd								
City: Flowood		State: MS		<sub>Zip:</sub> 39232				
Contact: Chuck Womack			Tel: 601-940-5411					
Certification Number: ABC-1799	Expiration		on Date: 3/4/2023					
OTHER OPERATOR: Codaray Construction								
Address: P O Box 16628								
<sub>City:</sub> Hattiesburg		State: MS		Zip: 39404				
Contact: Phillip Davis				Tel: 601-909-9260				
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes								
WAS ASBESTOS PRESENT? (Yes/No): Yes Inspection Date: 12/16/2022								
Inspector: Kirk Giessinger Certification Number: ABI-2367 Expiration Date: 2/15/2023								
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  FT/M. Pipe Elbows, Wall Plaster, Cove Base  PLM								
FT/M, Pipe Elbows, Wall Plaster, Cove Base PLM								
VII. QUANTITY OF RACM TO BE REMOVED: 40,000 CET/A CO								
VII. QUANTITY OF RACM TO BE REMOVED: 40,000sf FT/M - 20 pipe elbows - 100 sf transite								
Pipes (LN FT):	Surface Area (SQ FT):			Volume of Facility Components (CU FT):				
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: N/A								
Category I: Category II:								
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 8/10/2023 Complete: 9/10/2023								
x. scheduled dates demo/renovation (MM/DD/YY) Start: 8/10/2023  Complete: 2/10/2024  DEPT. OF ENVIRONMENTAL OUR LINE OF THE PROVIDENT OF THE P								
DEPT. OF ENVIRONMENT OF THE PROPERTY OF THE PR								

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:								
Removal of asbestos containing materials with hand tools								
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:								
Stop work and notify competent person, keep wet, seal all critical barriers & put under negative pressure								
XIII. WASTE TRANSPORTER #1								
<sub>Name:</sub> Burns Waste								
Address: 57 Burns Dr								
<sub>City:</sub> Columbus	State: MS		<sub>Zip:</sub> 39702					
Contact Person: Nic Parrish			Tel: 662-549-6070					
WASTE TRANSPORTER #2								
Name: Eagle Construction								
Address: 1450 Old Brandon Rd								
City: Flowood	State: MS		Zip: 39232					
Contact Person: Chuck Womack			Tel: 601-940-5411					
XIV. WASTE DISPOSAL SITE								
Name: Prairie Bluff Landfill								
Address: 1649 Hwy 15 North								
<sub>City:</sub> Houston	State: MS		<sub>Zip:</sub> 38851					
Contact Person:	Tel:			<sub>Fel:</sub> 662-456-9560				
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:								
lame: Title:								
Authority:								
Date of Order (MM/DD/YY):	Date Ordered to	Date Ordered to Begin (MM/DD/YY):						
XVI. FOR EMERGENCY RENOVATIONS:								
Date and Hour of Emergency (MM/DD/YY):								
Description of the sudden unexpected event:								
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:								
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:								
Stop work & notify owner, keep wet and double bag immediately								
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING MORMAL BUSINESS HOURS.								
Chuck Womack	<u> </u>		mp	7/26/2023				
Type or Print Name	(Signature of O	wner/Operator)		(Date)				
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECTION OF THE CHURCH WOMACK	ick: 9	t.		7/26/2023				
Type or Print Name	(Signature of Owner/Operator)			(Date)				