

**MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM**

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 08-01-2023	AI Number 70371
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):		O = ORIGINAL		
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):		R = RENOVATIONS		
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: South CANAL subdivision				
Address: 701 CANAL STREET				
City: TUPELO		State: MS	Zip: 38801	
Site Location: 406 BURRESS #2 STREET, TUPELO, MS			Tel: 662-416-3418	
Building Size: 925 sq. ft.		# of Floors: 2	Age in Years: 40+	
Present Use: VACANT FOR REPAIRS		Prior Use: SINGLE FAM. 2 story unit		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Tupelo Housing Authority				
Address: 701 South CANAL STREET				
City: TUPELO		State: MS	Zip: 38801	
Contact: TABITHA SMITH		Tel: 662-842-5122 ext. 2002		
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC.				
Address: P.O. BOX 133				
City: DELTA City		State: MS	Zip: 39061	
Contact: JIMMY BELL		Tel: 662-820-2124		
Certification Number: ABC-00001282		Expiration Date: 1/5/2024		
OTHER OPERATOR: PACE & SONS CONSTRUCTION, INC.				
Address: 374 CR-7000				
City: BOONEVILLE		State: MS	Zip: 38829	
Contact: CLAYTON PACE		Tel: 662-416-3418		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES				
WAS ASBESTOS PRESENT? (Yes/No): YES			Inspection Date: Aug. 19, 2011 - Aug. 30, 2011	
Inspector: WILLIAM J. YOUNG		Certification Number: ABI-00001688		Expiration Date: 9/24/2011
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: SAMPLES TAKEN FROM: WALLS, CEILING, ROOFING MATERIALS, FLOORS, WINDOWS, INSULATION AND FORWARDED TO CALABS., INC. BATON ROUGE, LA FOR TESTING USING THE PLM METHOD.				
VII. QUANTITY OF RACM TO BE REMOVED: (ONLY FLOOR TILE/MASTIC CONTAINS ASBESTOS) APPROXIMATELY 900 sq. FLOOR TILE/MASTIC				
Pipes (LN FT): 0		Surface Area (SQ FT): 900	Volume of Facility Components (CU FT): 0	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 0				
Category I: <input checked="" type="checkbox"/>			Category II: <input type="checkbox"/>	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 8/14/23			Complete: 8/16/23	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 8/17/23			Complete: 10/17/23	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

WET METHOD, CONTAINMENT, NEG-AIR, D-CON UNIT, INDEPENDENT AIR MONITORING/AIR - CLEARANCE, DOUBLE BAG.

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

PREP SITE, SIGNS, 6 MIL POLY OVER WINDOWS AND DOORS, AIR VENTS. WET REMOVE DOUBLE BAG, DROP TA9, TAPE CLOSE. REMOVE MASTIC, SOLIDIZE, DOUBLE BAG. PLACE ALL BAGS INTO LINED TRAILER DUMP WITH TARP. NEPA-VAC, CLEAN, AWAIT AIR CLEARANCE.

XIII. WASTE TRANSPORTER #1

Name: BELL ENVIRONMENTAL SERVICES, LLC

Address: P.O. BOX 133

City: DELTA CITY

State: MS

Zip: 39061

Contact Person: JIMMY BELL

Tel: 662-820-2124

WASTE TRANSPORTER #2 N/A

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: THREE RIVER LANDFILL

Address: 1904 PONTOTOC PARKWAY WEST

City: PONTOTOC

State: MS

Zip: 38863

Contact Person: 662 488 - 0444

Tel: 662 488 - 0444

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: N/A

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

STOP WORK, CONTINUE NEG-AIR, CONTAINMENT, CONTACT OWNER/MDEQ OF CHANGE, SEND MDEQ REVISED NOTIFICATION.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell

Type or Print Name

Jimmy Bell

(Signature of Owner/Operator)

8/1/23

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Jimmy Bell

Type or Print Name

Jimmy Bell

(Signature of Owner/Operator)

8/1/23

(Date)