

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MAP

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 08-29-2023	AI Number 70371
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):			R= REVISED DATE - Holiday	
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):			R= RENOVATIONS	
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: South CANAL STREET Subdivision				
Address: 701 South CANAL STREET				
City: Tupelo	State: MS	Zip: 38801		
Site Location: 1614 GREEN STREET Unit # 2 2 nd Floor			Tel: 662-416-3418	
Building Size: 900 sq. ft.	# of Floors: 2	Age in Years: 40+		
Present Use: VACANT FOR REPAIRS		Prior Use: Single Family 2 bedroom unit		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Tupelo Housing Authority				
Address: 701 South CANAL STREET				
City: Tupelo	State: MS	Zip: 38801		
Contact: TABITHA SMITH		Tel: 662-842-5122-ext. 2002		
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC.				
Address: P.O. BOX 133				
City: DELTA City	State: MS	Zip: 39061		
Contact: Jimmy Bell		Tel: 662-820-2124		
Certification Number: ABC-00001282		Expiration Date: 1/5/2024		
OTHER OPERATOR: PACE & SONS CONSTRUCTION, INC.				
Address: 374 CR-7000				
City: BUONEVILLE	State: MS	Zip: 38829		
Contact: CLAYTON PACE		Tel: 662-416-3418		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES				
WAS ASBESTOS PRESENT? (Yes/No): YES		Inspection Date: Aug., 19, 2011		
Inspector: WILLIAM J. YOUNG	Certification Number: ABT-00001688	Expiration Date: 9/24/2011		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:				
SAMPLES TAKEN FROM: WALLS, CEILING, ATTIC INSULATION, ROOF MATERIALS, WINDOWS AND FLOOR TILE/MASTIC. ALL MATERIALS WERE SHIPPED TO LA LABS., INC., BATON ROUGE - LA AND TESTED USING THE PLM METHOD				
THE FLOOR TILE CONTAINS ASBESTOS (UPSTAIRS ONLY)				
VII. QUANTITY OF RACM TO BE REMOVED:				
400 sq. ft. Floor Tile Located in upstairs Bedrooms and Bathroom.				
Pipes (LN FT): 0	Surface Area (SQ FT): 400 sq. ft.	Volume of Facility Components (CU FT): 0		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 0				
Category I: ✓		Category II:		
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 9/13/23		Complete: 9/14/23		
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 9/16/23		Complete: 12/16/23		

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Wet Method, Containment, Neg-Air, Independent Air Monitoring/Air Clearance
Double Bag, Tape, DYOP Tags.

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

PLACE SIGNS, REMOVE KICK BOARDS, WET, REMOVE, INSTANT,
DOUBLE BAG, CLEAN UP, HEPA-VAC, FOR FIBER-LOC, AWAIT AIR CLEARANCE.
PLACE BAGS INTO LINED TRAILER DUMP, TARP, HAUL TO STATE APPROVED LANDFILL.

XIII. WASTE TRANSPORTER #1

Name: BELL ENVIRONMENTAL SERVICES, LLC.Address: P.O. BOX 133City: DELTA CityState: MSZip: 39061Contact Person: Jimmy BellTel: 662-820-2124WASTE TRANSPORTER #2 N/A

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: LEFLORE County LandfillAddress: 15200 US Hwy, 49th SouthCity: SidonState: MSZip: 38954Contact Person: MABEL BROWNTel: 662-455-6477XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: N/A

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

WET EVERYTHING DOWN, CONTINUE CONTAINMENT, NEG-AIR. STOP WORK, CONTACT OWNER/
MDEQ OF CHARG, AWAIT MDEQ DIRECTIONS. SEND MDEQ REVISED 15 DAY NOTIFICATION.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell

Type or Print Name

Jimmy Bell

(Signature of Owner/Operator)

8/30/2023

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Jimmy Bell

Type or Print Name

Jimmy Bell

(Signature of Owner/Operator)

8/30/2023

(Date)