

REV

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

| | | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|------------------------------------|----------------------------------------|--------------------|
| MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery | | Postmark (mail only) | Date Received 8.28.2023 | AI Number 82424 |
| I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): R | | | | |
| II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D | | | | |
| III. FACILITY DESCRIPTION (Include building name, number and floor or room number): VACANT | | | | |
| Bldg. Name: VACANT HOUSE | | | | |
| Address: 201 PINE STREET | | | | |
| City: MCCOMB | | State: MS | Zip: 39648 | |
| Site Location: SAME | | | Tel: | |
| Building Size: 1400 SQUARE FEET | | # of Floors: 1 | Age in Years: OVER 20 | |
| Present Use: VACANT | | Prior Use: RESIDENCE | | |
| IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator) | | | | |
| OWNER NAME: CITY OF MCCOMB | | | | |
| Address: P O BOX 667 | | | | |
| City: MCCOMB | | State: MS | Zip: 39648 | |
| Contact: HENRY GREEN | | | Tel: (601) 249-9628 | |
| ASBESTOS REMOVAL CONTRACTOR: ABATEMENT PROS LLC | | | | |
| Address: 217 RALSTON ROAD | | | | |
| City: HATTIESBURG | | State: MS | Zip: 39601 | |
| Contact: LEE ROBERTS | | | Tel: (601) 408-5558 | |
| Certification Number: ABC-00011371 | | | Expiration Date: 01/03/2024 | |
| OTHER OPERATOR: TOM ELLIS DOZER SERVICE | | | | |
| Address: 2110 VAN NORMAN CURVE | | | | |
| City: MCCOMB | | State: MS | Zip: 39648 | |
| Contact: TOM ELLIS | | | Tel: (601) 600-1617 | |
| V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES | | | | |
| WAS ASBESTOS PRESENT? (Yes/No): YES | | | Inspection Date: 05/04/2023 | |
| Inspector: HENRY GREEN | | Certification Number: ABI-00009946 | Expiration Date: 01/05/2024 | |
| VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: EXTERIOR SIDING TRANSITE (PLM) ASBESTOS ANALYSIS WAS PREFORMED. | | | | |
| VII. QUANTITY OF RACM TO BE REMOVED: 1,400 SQ FT EXTERIOR TRANSITE SIDING | | | | |
| Pipes (LN FT): | | Surface Area (SQ FT): | Volume of Facility Components (CU FT): | |
| VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: | | | | |
| Category I: | | | Category II: | |
| IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 09/11/2023 | | | Complete: 09/11/2023 | |
| X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 09/12/2023 | | | Complete: 09/30/2023 | |

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:
STRUCTURES ARE TO BE ABATED OF ASBESTOS AND DEMOLISHED

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE
DEMOLITION OR RENOVATION SITE:
PROPER PPC, SPRAYING WATER FROM WATER HOSE, WET METHOD AND USING HAND TOOLS.

XIII. WASTE TRANSPORTER #1

Name: ABATEMENT PROS LLC

Address: 217 RALSTON ROAD

City: HATTIESBURG

State: MS

Zip: 39401

Contact Person: LEE ROBERTS

Tel: (601) 408-5558

WASTE TRANSPORTER #2

Name: TOM ELLIS DOZER SERVICE

Address: 2110 VAN NORMAN CURVE

City: MCCOMB

State: MS

Zip: 39648

Contact Person: TOM ELLIS

Tel: (601) 684-4522

XIV. WASTE DISPOSAL SITE

Name: MAGNOLIA LANDFILL

Address: 2103 MS 48 E

City: MAGNOLIA

State: MS

Zip: 39652

Contact Person: RED

Tel: (601) 600-1617

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: CITY OF MCCOMB

Title:

Authority: MAYOR AND BOARD OF SELECTMEN

Date of Order (MM/DD/YY): 08/15/2023

Date Ordered to Begin (MM/DD/YY): 09/11/2023

XVI. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY): N/A

Description of the sudden unexpected event:

N/A

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:
PROPERTY WAS ABANDONED AND HAS BECOME A NUISANCE TO THE COMMUNITY.

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY
NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

STOP WORK AND CALL MDEQ

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE
ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY
THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

LEE M ROBERTS

Type or Print Name

Lee Roberts

(Signature of Owner/Operator)

08/09/2023

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

HENRY GREEN

Type or Print Name

Henry Green

(Signature of Owner/Operator)

08/09/2023

(Date)