

## MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only:  Email	Postmark (mail only)		Date Received 8.28.2023		Al Number 82424		
I. Type of Notification (O=Original R=Revised	iginal R=Revised C=Canceled A= Annual): R						
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):							
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): VACANT							
Bldg. Name: VACANT HOUSE							
Address: 509 ELMWOOD STREET							
City: MCCOMB		State: MS		Zip: 39648			
Site Location: SAME				Tel:			
Building Size: 1400 SQUARE FEET		# of Floors: 1		Age in Years: OVER 20			
Present Use: VACANT		Prior Use: RESIDENCE					
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)							
OWNER NAME: CITY OF MCCOMB							
Address: P O BOX 667							
City: MCCOMB		State: MS		Zip: 39648			
Contact: HENRY GREEN				Tel: (601) 249-9628			
ASBESTOS REMOVAL CONTRACTOR: ABATEMENT PROS LLC							
Address: 217 RALSTON ROAD							
City: HATTIESBURG		State: MS		Zip: 39601			
Contact: LEE ROBERTS		Tel: (601		.) 408-5558			
Certification Number: ABC-00011371	Expiration		on Date: 01/03/2024				
OTHER OPERATOR: TOM ELLIS DOZER SERVICE							
Address: 2110 VAN NORMAN CURVE							
City: MCCOMB		State: MS		<sub>Zip:</sub> 39648			
Contact: TOM ELLIS				Tel: (601) 600-1617			
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES							
WAS ASBESTOS PRESENT? (Yes/No): YES			Inspection Date: 05/04/2023				
Inspector: HENRY GREEN Certification Number: ABI-00009946 Expiration Date: 01/05/2024							
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  EXTERIOR SIDING TRANSITE (PLM) ASBESTOS ANALYSIS WAS PREFORMED.							
TATELLIS TO THE CONTROL OF THE CONTR							
VII. QUANTITY OF RACM TO BE REMOVED: 1,400 SQ FT EXTERIOR TRANSITE SIDING							
1,400 SQ FT EXTERIOR TRANSITE SIDING							
Pipes (LN FT): Surface Area (SQ FT): Volume of Facility Components (CU FT):				mponents (CU FT):			
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:							
Category I: Category II: 09/01/2022							
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 09/01/2023 Complete: 09/01/2023							
x. scheduled dates demo/renovation (MM/DD/YY) Start: 09/12/2023 Complete: 09/30/2023							

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED: STRUCTURES ARE TO BE ABATED OF ASBESTOS AND DEMOLISHED						
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: PROPER PPC, SPRAYING WATER FROM WATER HOSE, WET METHOD AND USING HAND TOOLS.						
XIII. WASTE TRANSPORTER #1						
Name: ABATEMENT PROS LLC						
Address: 217 RALSTON ROAD						
<sub>City:</sub> HATTIESBURG	State: MS	Zip: 39401				
Contact Person: LEE ROBERTS		Tel: (601) 408-5558				
WASTE TRANSPORTER #2						
Name: TOM ELLIS DOZER SERVICE						
Address: 2110 VAN NORMAN CURVE						
City: MCCOMB	State: MS	Zip: 39648				
Contact Person: TOM ELLIS		Tel: (601) 684-4522				
XIV. WASTE DISPOSAL SITE						
Name: MAGNOLIA LANDFILL						
Address: 2103 MS 48 E						
<sub>City:</sub> MAGNOLIA	<sub>State:</sub> MS	Zip: 39652				
Contact Person: RED		Tel: (601) 600-1617				
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:						
Name: CITY OF MCCOMB Title:						
Authority: MAYOR AND BOARD OF SELECTMEN						
Date of Order (MM/DD/YY): 08/15/2023	Date Ordered to Begin (MM/DD/YY): 09/11/2023					
XVI. FOR EMERGENCY RENOVATIONS:						
Date and Hour of Emergency (MM/DD/YY): N/A						
Description of the sudden unexpected event:						
N/A						
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: PROPERTY WAS ABANDONED AND HAS BECOME A NUISANCE TO THE COMMUNITY.						
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:  STOP WORK AND CALL MDEQ						
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS						
LEE M ROBERTS	Lee Robent	08/09/2023				
	(Signature of Owner/Operator)	(Date)				
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT: HENRY GREEN 08/09/2023						
Type or Print Name	(Signature of Owner/Operator)	(Date)				