



# MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

MAP

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received <b>08-30-2023</b>	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): <b>Original</b>				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): <b>Demo</b>				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: <b>Nordan Smith Bldg</b>				
Address: <b>317 West Rankin St</b>				
City: <b>Jackson</b>		State: <b>MS</b>	Zip: <b>39201</b>	
Site Location:			Tel:	
Building Size: <b>20,000 sf</b>		# of Floors: <b>1</b>	Age in Years: <b>50</b>	
Present Use: <b>abandoned</b>		Prior Use: <b>office/warehouse</b>		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: <b>Airgas USA LLC</b>				
Address: <b>P.O. Box 3246</b>				
City: <b>Tulsa</b>		State: <b>OK</b>	Zip: <b>74101-3246</b>	
Contact: <b>Joe Pilleteri</b>			Tel: <b>205-650-9955</b>	
ASBESTOS REMOVAL CONTRACTOR: <b>Jeff Evans Inc d/b/a Eagle Construction</b>				
Address: <b>1450 Old Brandon Rd</b>				
City: <b>Flowood</b>		State: <b>MS</b>	Zip: <b>39232</b>	
Contact: <b>Chuck Womack</b>			Tel: <b>601-940-5411</b>	
Certification Number: <b>ABC-1799</b>			Expiration Date: <b>3/4/23</b>	
OTHER OPERATOR: <b>Faircloth Demolition</b>				
Address: <b>P.O. Box 1296</b>				
City: <b>Clinton</b>		State: <b>MS</b>	Zip: <b>39060</b>	
Contact: <b>Mark Parkman</b>			Tel: <b>601-573-3762</b>	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): <b>Yes</b>				
WAS ASBESTOS PRESENT? (Yes/No): <b>Yes</b>			Inspection Date: <b>6/21/23</b>	
Inspector: <b>Zander Cordan</b>		Certification Number: <b>ABI-00008038</b>	Expiration Date: <b>5/5/24</b>	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: <b>window caulking, floor tile, floor tile mastic, duct insulation, sheet flooring, drywall, brick, mortar, wall insulation, wall covering, ceiling tile, carpet, laminate flooring, cove base, mastic, sheet rock and joint compound</b> <b>PLM</b>				
VII. QUANTITY OF RAQM TO BE REMOVED: <b>350 Lf. Window Caulk   2485 SF Floor Tile + Mastic   15 Lf. Duct Insulation   815 SF sheetrock</b>				
Pipes (LN FT):		Surface Area (SQ FT):	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:			Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: <b>9/12/23</b>			Complete: <b>9/22/23</b>	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: <b>9/12/23</b>			Complete: <b>9/22/23</b>	

<b>XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:</b> remove all asbestos containing materials by hand demo with trackhoe		
<b>XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:</b> wet demo		
<b>XIII. WASTE TRANSPORTER #1</b>		
Name: American Disposal Service		
Address: P.O. Box 1296		
City: Clinton	State: MS	Zip: 39060
Contact Person: Mark Parkman		Tel: 601-573-3762
<b>WASTE TRANSPORTER #2</b>		
Name: American Disposal Service		
Address: P.O. Box 1296		
City: Clinton	State: MS	Zip: 39060
Contact Person: Mark Parkman		Tel: 601-573-3762
<b>XIV. WASTE DISPOSAL SITE</b>		
Name: Little Dixie Landfill 1716 North County Line Rd. Ridgeland, MS 39157		
Address: Faircloth Rubbish Landfill 1312 Spingridge Rd Clinton, MS 39060		
City:	State:	Zip:
Contact Person: Mark Parkman		Tel: 601-573-3762
<b>XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:</b>		
Name:		Title:
Authority:		
Date of Order (MM/DD/YY):		Date Ordered to Begin (MM/DD/YY):
<b>XVI. FOR EMERGENCY RENOVATIONS:</b>		
Date and Hour of Emergency (MM/DD/YY):		
Description of the sudden unexpected event:		
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:		
<b>XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:</b> Stop and call asbestos contractor		
<b>XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.</b>		
Mark Parkman		8/29/23
Type or Print Name	(Signature of Owner/Operator)	(Date)
<b>XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:</b>		
Mark Parkman		8/27/23
Type or Print Name	(Signature of Owner/Operator)	(Date)