

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 11/12/2024	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): <input type="radio"/> O				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D-ACM ONLY				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): House floor tile in Bathroom, FT in shop				
Bldg. Name: House				
Address: 112 Rawl Springs Loop				
City: Hattiesburg		State: MS	Zip: 39401	
Site Location: Same			Tel: 601 582 4741	
Building Size: 2000 SF		# of Floors: 1	Age in Years: >30	
Present Use: Un-Occupied		Prior Use: House		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Forrest General Hospital				
Address: PO Box 16389				
City: Hattiesburg		State: MS	Zip: 39402	
Contact: Joe Venus			Tel: 601 408 1005	
ASBESTOS REMOVAL CONTRACTOR: Environmental Serviices				
Address: 253 Delk Road				
City: Hattiesburg		State: MS	Zip: 39401	
Contact: Joe Venus			Tel: 6014081005	
Certification Number: ABC00001330			Expiration Date: Jan 2 2025	
OTHER OPERATOR: n/a				
Address:				
City:		State:	Zip:	
Contact:			Tel:	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes				
WAS ASBESTOS PRESENT? (Yes/No): Yes			Inspection Date: Aug 16, 2023	
Inspector: Lee Roberts		Certification Number: ABI00009020	Expiration Date: Mar 7 2025	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Flooring and limoleum flooring materials, PLM Analysis				
VII. QUANTITY OF RACM TO BE REMOVED:				
Pipes (LN FT):		Surface Area (SQ FT):	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I: 1,120 SF			Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 11/26/24			Complete: 11/26/24	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: N/A			Complete:	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Removal of flooring using the wet method in specified rooms

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Wet materials and remove using hand tools

XIII. WASTE TRANSPORTER #1

Name: Environmental services

Address: 253 Delk road

City: Hattiesburg

State: MS

Zip: 39401

Contact Person: Joe Venus

Tel: 601 408 1005

WASTE TRANSPORTER #2

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: RoBo landfill

Address: 6447 Walalak Road

City: Scooba

State: MS

Zip: 39358

Contact Person: Roland Edwards

Tel: 662 793 4795

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: N/A

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:

Stop work call DEQ

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Joe Venus

Type or Print Name

(Signature of Owner/Operator)

11/12/24

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Joe Venus

Type or Print Name

(Signature of Owner/Operator)

11/12/24

(Date)