

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery	Postmark (mail only)	Date Received 1/13/2025	AI Number 2299
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): Annual			
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation			
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Refinery			
Bldg. Name: Chevron Pascagoula Refinery			
Address: 250 Industrial Rd			
City: Pascagoula	State: MS	Zip: 39581-3201	
Site Location:		Tel: 228-938-4731	
Building Size:	# of Floors:	Age in Years:	
Present Use:		Prior Use:	
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)			
OWNER NAME: Chevron Products Company			
Address: 250 Industrial Rd			
City: Pascagoula	State: MS	Zip: 39581-3201	
Contact: Erin Spencer		Tel: 228-938-4731	
ASBESTOS REMOVAL CONTRACTOR: Apache Industrial Services Inc. ABC#00012143, Brand Safeway ABC#00005802			
Address: 250 Assay Street Ste. 500			
City: Houston	State: TX	Zip: 77044	
Contact: Stanley Smith		Tel: 409-718-5217	
Certification Number: Apache: ABC#00012143 Brand: ABC#00005802		Expiration Date: Apache: 8/27/2025 Brand: 1/25/2025	
		2/12/2025	3/15/2025
OTHER OPERATOR: Brand Safeway			
Address: 1325 Cobb International Dr. Ste. D-1			
City: Kennesaw	State: GA	Zip: 30152	
Contact: Zachary Brought		Tel: 228-860-5849	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes, to be Determined			
WAS ASBESTOS PRESENT? (Yes/No):		Inspection Date:	
Inspector:	Certification Number:	Expiration Date:	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Various materials may be sampled as needed (pipe insulation, vessel insulation, etc.), if sampling does not occur, the materials will be assumed to be asbestos. If sampling occurs, Bulk sampling and analyses performed in accordance with methodologies as outlined in interim Methods for the Determination of Asbestos in Bulk Insulation EPA-600/R-93/116 and Standard Method of Testing for Asbestos Containing Materials by Polarized Light Microscopy ASTM D 22.05			
VII. QUANTITY OF RACM TO BE REMOVED:			
Pipes (LN FT): 4000*	Surface Area (SQ FT): 2000*	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:			
Category I:		Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 01/01/2025		Complete: 12/31/2025	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 01/01/2025		Complete: 12/31/2025	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

This notification is for renovations, both planned and emergency, which will individually generate less than 260 linear feet for piping and 160 square feet for other components; however, the additive amount will be greater than the reportable quantity.

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Strip & Removal, Containment, Wet Method, Double Bagging, Glove Bag, Remove Intact, Negative Air

XIII. WASTE TRANSPORTER #1

Name: Waste Management of Mississippi - Gulf Coast

Address: Pecan Grove RDF, 9685 Firetower Road

City: Pass Christian

State: MS

Zip: 39571

Contact Person: Mike Hall

Tel: 228-832-3144

WASTE TRANSPORTER #2

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: Waste Management of Mississippi - Gulf Coast

Address: Pecan Grove RDF, 9685 Firetower Road

City: Pass Christian

State: MS

Zip: 39571

Contact Person:

Tel:

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:


XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

Work will stop. Notifications will be completed as necessary. Proper controls will be instituted.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Erin Spencer

Type or Print Name



(Signature of Owner/Operator)


1/13/2025

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Erin Spencer

Type or Print Name



(Signature of Owner/Operator)

1/13/2025

(Date)