MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: Email DMail DHand Delivery	Postmark (ma	il only) Date Red		ceived 3/21/2025	Al Number				
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):									
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):									
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):									
Bldg. Name: South Delta High School									
Address: 303 Parkway Ave Rolling Fork, MS 39159									
City: Rolling Fork	Rolling Fork		State: MS		Zip: 39159				
Site Location: Hallway			Tel: (662) 873-		1849				
Building Size: Approx.20,000sf		# of Floors: 1	# of Floors: 1		Age in Years: 40+				
Present Use: School		Prior Use: School							
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)									
OWNER NAME: South Delta School District									
Address: 106 Athletic Drive, Rolling Fork, MS 39159									
City: Rolling Fork		State: MS		_{Zip:} 39159					
Contact: Timothy Ginn					Tel: 662-873-4849				
ASBESTOS REMOVAL CONTRACTOR: ANDERSON ENVIRONMENTAL									
Address: 783 HARRIS STREET									
City: JACKSON			ate: MS		Zip: 39202				
Contact: DARYL ANDERSON				Tel: 601-354-4400					
Certification Number: ABC-00002173		Expiration Date: 11-12-25							
OTHER OPERATOR: M&P Construction									
Address: 130 Walker Cr I Richland I MS I 39218									
City: Richland Sta		State: MS	State: MS		Zip: 39218				
Contact: Mariela Cancio				Tel: 769-243-6776					
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes									
WAS ASBESTOS PRESENT? (Yes/No): Yes	ESTOS PRESENT? (Yes/No): Yes Inspection				n Date: 4-26-2024				
Inspector: Willie Nester Certification Number: ABI-00002244 Expiration Date: 01/24/2025									
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Floors, ceilings, walls, roof, pipes, windows,									
Procedure PLM-Polarized Light Microscopy									
VILOUANTITY OF BACK TO BE DEMOVED.									
VII. QUANTITY OF RACM TO BE REMOVED: 6000sf Floor tile and mastic									
Pipes (LN FT): Surface Area (SQ FT): Volume of Facility Components (CU FT):					mponents (CU FT):				
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:									
Category I: Category II:									
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 04-5-25									
x. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 4-16-25 Complete: 7-30-25									

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVA Renovate School								
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING DEMOLITION OR RENOVATION SITE:	NG CONTROLS T	O BE USED	TO PREVENT EMISSIONS	OF ASBESTOS AT THE				
Area barricaded off with asbestos danger t	ape, under n	egative	pressure, material k	cept wet and placed				
in acm bags for disposal XIII. WASTE TRANSPORTER #1								
Name: Anderson Environmental								
Address: 783 Harris Street	140							
City: Jackson	State: MS		Zip: 39202					
Contact Person: Daryi Anderson	Contact Person: Daryl Anderson Tel: (601) 354-4400							
WASTE TRANSPORTER #2								
Name:								
Address:								
City:	State:		Zip:					
Contact Person:			Tel:					
XIV. WASTE DISPOSAL SITE Republic								
Name: Big River Landfill								
Address: 52 Landfield Rd Leland, MS 38756								
City: Leland	State: MS		Zip: 38756					
Contact Person: Mike Raley			Tel: (662) 335-1014					
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:								
lame: Title:								
Authority:								
Date of Order (MM/DD/YY):	Date of Order (MM/DD/YY): Date Ordered to Begin (MM/DD/YY):							
XVI. FOR EMERGENCY RENOVATIONS:								
Date and Hour of Emergency (MM/DD/YY):								
Description of the sudden unexpected event:								
Explanation of how the event caused unsafe conditions or would	cause equipment	damage or a	an unreasonable financial burd	den:				
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:								
Halt all work and notify the proper authority								
Walling a second								
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.								
DARYL ANDERSON								
Type or Print Name	(Signature of Owner/	Operator)		(Date)				
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT: DARYL ANDERSON 03-20-24								
Type or Print Name	(Signature of Owner/	'Operator)		(Date)				