

# MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)		Date Received: 02/29/2024	AI Number: 81492
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual) <b>O</b>					
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation) <b>D</b>					
III. FACILITY DESCRIPTION (Include building name, number and floor or room number) <b>Former Mississippi Phosphates Corporation</b>					
Bldg. Name: <b>Outdoor Piping</b>					
Address <b>601 Industrial Road</b>					
City: <b>Pascagoula</b>		State: <b>MS</b>		Zip: <b>39581</b>	County: <b>Jackson</b>
Site Location: <b>601 Industrial Road</b>				Tel: <b>2516544272</b>	
Building Size <b>N/A</b>		# of Floors: <b>0</b>		Age in Years: <b>30+</b>	
Present Use: <b>Industrial</b>		Prior Use: <b>Industrial</b>			
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)					
OWNER NAME: <b>Seven Seas Terminals, LLC.</b>					
Address: <b>601 Industrial Road</b>					
City: <b>Pascagoula</b>		State: <b>MS</b>		Zip: <b>39581</b>	
Contact: <b>Scott Cleveland</b>				Tel: <b>713-805-3281</b>	
ASBESTOS REMOVAL CONTRACTOR: <b>Nicholas Insulation Services</b>					
Address: <b>3568 Desirrah Drive</b>					
City: <b>Mobile</b>		State: <b>AL</b>		Zip: <b>36618</b>	
Contact: <b>Carson Williams</b>				Tel: <b>(251) 471-5900</b>	
Certification Number: <b>10779-SC</b>				Expiration Date: <b>01/14/25</b>	
OTHER OPERATOR: <b>Smith Tank &amp; Steel</b>					
Address: <b>42422 E Hwy 30</b>					
City: <b>Gonzales</b>		State: <b>LA</b>		Zip: <b>70737</b>	
Contact: <b>Corey Delatte</b>				Tel: <b>225-621-3772</b>	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): <b>Yes</b>					
WAS ASBESTOS PRESENT? (Yes/No): <b>Yes</b>				Inspection Date: <b>06/20/22</b>	
Inspector: <b>Richard Vick</b>		Certification Number: <b>ABI-00010700</b>		Expiration Date: <b>2/15/23</b>	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Suspect materials sampled included pipe insulation, tank insulation, pipe wrap, and sheet material. Samples were analyzed via Polarized Light Microscopy (PLM) for the presence of asbestos.					
VII. QUANTITY OF RACM TO BE REMOVED:					
Pipes (LN FT): <b>600</b>		Surface Area (SQ FT):		Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:					
Category I:				Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: <b>3/11/24</b>				Complete: <b>3/25/24</b>	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: <b>3/11/24</b>				Complete: <b>4/26/24</b>	

**XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:**

Demolition will include the use of hydraulic excavators with attachments and cutting torches.

**XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:**

Glove bagging and wet methods will be utilized as well as proper PPE including protective suits and respirators.

**XIII. WASTE TRANSPORTER #1**

Name: Waste Pro

Address: 4205 Beasley Road

City: Gautier

State: MS

Zip: 39553

Contact Person: Ryan Rubenstein

Tel: 228-818-5393

**WASTE TRANSPORTER #2**

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

**XIV. WASTE DISPOSAL SITE**

Name: Waste Management - Pecan Grove Landfill

Address: 9685 Firetower Road

City: Pass Christian

State: MS

Zip: 39571

Contact Person: Michael Eidt

Tel: 662-448-0773

**XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:**

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

**XVI. FOR EMERGENCY RENOVATIONS:**

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

**XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:**

Stop work and proceed in accordance with all local, state, and EPA regulations.

**XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.**

Scott Cleveland

Type or Print Name

(Signature of Owner/Operator)

2/29/2024

(Date)

**XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT.**

Scott Cleveland

Type or Print Name

(Signature of Owner/Operator)

2/29/2024

(Date)