

**MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM**

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 7/11/2024	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): -O-				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): -D-				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: BEAUTY SHOP				
Address: 115 7th AVE.				
City: MERIDIAN		State: MS	Zip: 39301	
Site Location: 115 7th AVE. <a href="#">See Attached Report</a>			Tel:	
Building Size: 720 SQ. FT.		# of Floors: 1	Age in Years: 75	
Present Use: VACANT		Prior Use: BEAUTY SHOP		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: VAN GAVIN				
Address:				
City: MERIDIAN		State: MS	Zip: 39301	
Contact: VAN GAVIN		Tel: 601-227-8377		
ASBESTOS REMOVAL CONTRACTOR: BILLY SHUMATE CONST.				
Address: P.O. BOX 4279				
City: MERIDIAN		State: MS	Zip: 39304	
Contact: BILLY SHUMATE		Tel: 601-934-9337		
Certification Number: ABC-00001893			Expiration Date: AUG. 15 2024	
OTHER OPERATOR: SAME				
Address:				
City:		State:	Zip:	
Contact:		Tel:		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES				
WAS ASBESTOS PRESENT? (Yes/No): YES			Inspection Date: 6-10-24	
Inspector: DON COOLEY		Certification Number: ABI-00001363	Expiration Date: 6-5-24 1/05/2025	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: FLOOR TILE AND MASTIC , ROOFING MATERIAL , CEILING TILE , SHEETROCK-JOINT COMPOUND , TRANSITE SIDING , WINDOW GLAZE -PLM-				
VII. QUANTITY OF RACM TO BE REMOVED: 720 S.F. FLOOR TILE & MASTIC, 300S.F. TRANSITE SIDING				
Pipes (LN FT):		Surface Area (SQ FT):	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:		Category II:		
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 7-25-24			Complete: 7-28-24	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 7-29-24			Complete: 8-3-24	

**XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:  
TOTAL DEMOLITION OF STRUCTURE - WITH EXCAVATOR**

**XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE  
DEMOLITION OR RENOVATION SITE:  
WET METHOD , DOUBLE BAGGING**

**XIII. WASTE TRANSPORTER #1**

Name: BILLY SHUMATE CONST.

Address: P.O. BOX 4279

City: MERIDIAN

State: MS

Zip: 39304

Contact Person: BILLY SHUMATE

Tel: 601-934-9337

**WASTE TRANSPORTER #2**

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

**XIV. WASTE DISPOSAL SITE**

Name: KEMPER COUNTY LANDFILL - WASTE PRO

Address: 21211 HWY 16 E.

City: DEKALB

State: MS

Zip: 39328

Contact Person:

Tel: 601-743-4210

**XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:**

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

**XVI. FOR EMERGENCY RENOVATIONS:**

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

**XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY  
NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:  
AS PER MDEQ REQUIREMENTS**

**XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE  
ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY  
THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.**

BILLY SHUMATE CONST.

Type or Print Name

*Billy Shumate*  
(Signature of Owner/Operator)

7-11-24  
(Date)

**XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:**

BILLY SHUMATE CONST.

Type or Print Name

*Billy Shumate*  
(Signature of Owner/Operator)

7-11-24  
(Date)

**DRC Environmental Consulting, LLC**  
**96 Cooley Park Road**  
**Soso, MS 39480**  
**(601) 954-3268**

June 20, 2024

Mr. Billy Shumate  
Shumate Construction and Demo  
Post Office Box 4279  
Meridian, MS 39304

RE: Asbestos-Containing Material (ACM) Inspection  
Beauty Shop  
115 7<sup>th</sup> Avenue, Meridian, MS

Dear Mr. Shumate:

On June 10, 2024, DRC Environmental Consulting, LLC (Consultant) conducted an Asbestos-Containing Material Inspection on the commercial building of block and transite siding with a shingle roof at the location referenced above. This inspection for friable and non-friable material was performed by Don Cooley, Mississippi-certified Asbestos Inspector number ABI-00001363, exp. January 5, 2025 (copy of certificate attached).

A total of twenty-seven (27) laboratory analyses were performed on samples of suspect asbestos-containing material (ACM) taken from eighteen (18) sample sites. The samples were then submitted to Eurofins EPK Built Environment Testing LLC, a fully accredited independent environmental testing laboratory, for analysis, following the Environmental Protection Agency (EPA)-recommended Polarized Light Microscopy (PLM) method. Sample chain of custody and analytical results are attached.

The suspect materials which were identified as possible ACM and sampled homogeneously are listed below. Sample locations may be found on the attached site drawing. No thermal system insulation was seen above the ceiling.

- Floor Tile and Mastic
- Roofing Materials
- Ceiling Tile
- Sheetrock/Joint Compound (composite)
- Transite Siding
- Window Glaze

Suspect materials identified as asbestos-containing (ACM):

Non-Friable  
Floor Tile & Mastic  
Transite Siding

Mr. Billy Shumate  
June 20, 2024  
Page 2

<u>ACM</u>	<u>Condition</u>	<u>Location</u>	<u>Estimated Quantity</u>
Floor Tile & Mastic (Bottom Layer)	Non-Friable	Bottom Layer of Entire Building	720 sq. ft.
Transite Siding	Non-Friable	East and West Outside Walls	300 sq. ft.

The Consultant makes the following recommendations:

- As this survey was conducted as a snapshot in time and the Consultant's familiarity with the facility is limited, suspect materials may be found during renovation/demolition that were not sampled. If this occurs please contact the Consultant before further work is performed, or assume materials found to be ACM.
- As required by law, a notification to the Mississippi Department of Environmental Quality should be filed ten (10) working days prior to the start of the abatement / demolition.
- Mississippi-certified asbestos abatement contractor and workers are required for the asbestos removal.
- Waste must be disposed of in the appropriate landfill.
- The asbestos abatement contractor should verify quantities, as the inspector quantities listed in this report are estimates only.

DRC Environmental Consulting, LLC appreciates the opportunity to provide professional environmental consulting services to you. Please contact us at (601) 954-3268, or by e-mail at donrcooley@gmail.com, with any questions you may have regarding this information.

Sincerely,



Don Cooley  
Principal

Report Attachments:

Site Drawing (1)  
Laboratory Results from iATL (3)  
Chain of Custody Forms (3)  
MS Certificate of Licensure—Asbestos Inspector (1)

DC:cc