

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: ★Email □Mail □Hand Delivery	Postmark (mail only	/)	Date Rec	reived 7/12/2024	Al Number	37466			
	I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): R								
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation); R									
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Mississippi State University									
Bldg Name Research & Curriculum Unit									
Address: 103 Russell Street									
_{City} . Starkville	State: MS			_{7ip:} 39759					
Site Location: Research & Curriculum Unit			Tel: 662-325-2510						
Building Size: Unknown		# of Floors:		Age in Years: Unknown					
Present Use: Educational learning	Pri	_{or Use:} Unknov	vn						
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)									
OWNER NAME: Mississippi State University									
Address: PO Box 5307									
City: Mississippi State State: MS		ES.	_{Zin} : 39762						
Contact: Unknown				Tel: 662-325-2323					
ASBESTOS REMOVAL CONTRACTOR: Snyder Environmental & Construction, LLC									
Address: 7705 Northshore Place									
City: North Little Rock State: AR				Zip: 72118					
Contact: Justin Dixon/Andrew Ables				Tel: 501-801-2776/601-559-2185					
			Expiratio	ration Date: 9/30/2023					
OTHER OPERATOR: N/A									
Address: N/A									
City: N/A	Sta	State: N/A		_{Zip:} N/A					
Contact: N/A			Tel: N/A						
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes									
WAS ASBESTOS PRESENT? (Yes/No): Yes Inspecti				on Date: 5/4/2023					
Inspector: Joe Venus Certification Number: ABI-00001353 Expiration Date: 2/9/2024									
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:									
PLM Bulk Samples Approx 200 SE of 12x12 Floor Tile/Mastic									
Approx. 900 SF of 12x12 Floor Tile/Mastic.									
VII. QUANTITY OF RACM TO BE REMOVED: N/A									
N/A						N/A			
Pipes (LN FT): N/A Surface Area (SQ FT): N/A Volume of Facility Components (CU FT): N/A									
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 900 SF									
Category I: Category II: Floor Tile/Mastic IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 7/1/2024 Complete: 7/10/2024									
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: N/A Complete: N/A									

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:								
Materials listed to be removed by hand so facility can be renovated.								
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:								
Materials will be wetted, during and after abatement, properly packaged, labeled and transported to a class 1 landfill for disposal.								
XIII. WASTE TRANSPORTER #1								
Name: Snyder Environmental & Construction, LLC	>							
Address: 7705 Northshore Place								
City: North Little Rock	State: AR		Zip: 72118					
Contact Person: Andrew Abels			Tel: 601-559-2185					
WASTE TRANSPORTER #2 N/A								
Name: N/A								
Address: N/A								
City: N/A	State: N/A		z _{ip:} N/A					
Contact Person: N/A			Tel: N/A					
XIV. WASTE DISPOSAL SITE								
Name: Alternative Waste Landfill								
Address: 43 White City Road								
City: Mayflower	State: AR		Zip: 72106					
Contact Person: N/A	***************************************		Tel: 501-851-1171					
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:								
Name: N/A Title: N/A								
Authority: N/A								
Date of Order (MM/DD/YY): N/A Date Ordered to Begin (MM/DD/YY): N/A								
XVI. FOR EMERGENCY RENOVATIONS:								
Date and Hour of Emergency (MM/DD/YY): N/A								
Description of the sudden unexpected event:								
N/A								
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:								
N/A								
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:								
Wet the unexpected, make area safe and notify DEQ								
, , , , , , , , , , , , , , , , , , ,								
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.								
Barbara McElroy	Barbara McClroy 7/12/2024							
Type or Print Name	(Signature of Owner/Ope	erator)	8	(Date)				
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT: Barbara McElroy Barbara McElroy 7/1220244								
Type or Print Name	(Signature of Owner/Op	-	rog					
				(Date)				