



MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 02-14-2024	AI Number 2221
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): R= Revised				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: #2 Mill Building				
Address: 850 N Broadway				
City: Greenville		State: MS	Zip: 38701	
Site Location: Lower Roof of #2 Mil			Tel:	
Building Size: 100,000		# of Floors: 1	Age in Years: 90	
Present Use: Industrial Production		Prior Use: Industrial Production		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: USG Interiors				
Address: 850 N Broadway				
City: Greenville		State: MS	Zip: 38701	
Contact: Drew Moran			Tel: (662) 347-4059	
ASBESTOS REMOVAL CONTRACTOR: Northstar Contracting Group, Inc				
Address: 76 East 9 Mile Rd				
City: Pensacola		State: FL	Zip: 32534	
Contact: Jerzy Sobski			Tel: (850) 777-0365	
Certification Number: ABC-00010281			Expiration Date: 02-15-2024	
OTHER OPERATOR: Industrial Roofing				
Address: 1128 Hwy 2				
City: Sterlington		State: LA	Zip: 71280	
Contact: Brandon Courson			Tel: (318) 665-0483	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes				
WAS ASBESTOS PRESENT? (Yes/No): Yes			Inspection Date: 04-29-2013	
Inspector: Daniel Hayes		Certification Number: ABI-00005808	Expiration Date: 08-08-213	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Core Roof samples taken, and underlying insulation. PLM used to determine Presence				
VII. QUANTITY OF RACM TO BE REMOVED: In SF below				
Pipes (LN FT): NA	Surface Area (SQ FT): 36,600		Volume of Facility Components (CU FT): NA	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I: NA		Category II: NA		
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 02-20-2024			Complete: 04-31-2024	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 02-20-2024			Complete: 04-31-2024	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:		
Builtup Roofing including insulation to be removed in section . During removal material will be kept wet to prevent emmisions		
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:		
Wetting, strip removal in larger sections,		
XIII. WASTE TRANSPORTER #1		
Name: Republic Services of Leland		
Address: 52 Landfill Rd		
City: Leland	State: MS	Zip: 38756
Contact Person: Mike Raley	Tel: (601) 613-8671	
WASTE TRANSPORTER #2		
Name: NA		
Address: NA		
City: NA	State: NA	Zip: NA
Contact Person: NA	Tel: NA	
XIV. WASTE DISPOSAL SITE		
Name: Big River Landfill		
Address: 52 Landfill Rd		
City: Leland	State: MS	Zip: (662) 332-7927
Contact Person: Mike Raley	Tel: (601) 613-8671	
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:		
Name: NA	Title: NA	
Authority: NA		
Date of Order (MM/DD/YY): NA	Date Ordered to Begin (MM/DD/YY): NA	
XVI. FOR EMERGENCY RENOVATIONS: NA		
Date and Hour of Emergency (MM/DD/YY): NA		
Description of the sudden unexpected event:		
NA		
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:		
NA		
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:		
Stop Work, Segregate affected area, wet material, HEPA vacuum and clean area, Notify Owner and MDEQ		
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.		
Jerzy Sobski		02-14-2024
Type or Print Name	(Signature of Owner/Operator)	(Date)
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:		
Jerzy Sobski		02-14-2024
Type or Print Name	(Signature of Owner/Operator)	(Date)