

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 02-26-202024	AI Number 79718
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual) O				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation) R				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number)				
Bldg. Name: Robertson Place (18 units) 201 Katie Ave.				
Address Units: A2, A5,B11,F36,G38,H46,I50,I51,J59,L67,M74,M76,O90,Q99,R105,R107,T116,T117				
City: MS Hattiesburg	State: MS	Zip: 39401	County: Forrest	
Site Location: 201 Katie Ave		Tel: 601-583-2762		
Building Size 18 units approx 13,185 sq ft.	# of Floors:	Age in Years:		
Present Use: vacant	Prior Use: public housing complex			
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Hattiesburg Housing Authority				
Address: 201 Katie Ave				
City: Hattiesburg	State: MS	Zip: 39401		
Contact: Rusty Walker	Tel: 228-860-9000			
ASBESTOS REMOVAL CONTRACTOR: Southeast Environmental Group, Inc.				
Address: P.O. Box 433/ 296B 2nd Ave.				
City: York	State: AL	Zip: 36925		
Contact: Johnny Rodgers	Tel: 205-392-9308			
Certification Number: ABC00001906	Expiration Date: 06/02/2024			
OTHER OPERATOR:				
Address:				
City:	State:	Zip:		
Contact:	Tel:			
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): yes. years ago				
WAS ASBESTOS PRESENT? (Yes/No): yes		Inspection Date: unknown		
Inspector: unknown	Certification Number: unknown	Expiration Date: unknow		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Some units were tested years ago. The black mastic was confirmed to contain amc. Since the units are vacant, they will all be done as one job. All of the flooring will be handled as ACM. It is approx 13,185 sq ft of floor tile and mastic. All the mastic and tile is presumed to contain Asbestos				
VII. QUANTITY OF RACM TO BE REMOVED:				
Pipes (LN FT):	Surface Area (SQ FT): approx 13,185 sq ft	Volume of Facility Components (CU FT):		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:	Category II:			
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 3/08/2024		Complete: 5/08/2024		
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: n/a		Complete: n/a		

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:
Removal of presumed ACM will be performed by trained and certified personnel. The ACM will be kept wet throughout the process. The work area will be protected and sealed by using the capsule concept to assure the least to no particles escape.

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:
the non-friable ACM will be removed by competent personnel that is trained and knowledgeable in the removal, handling, and disposal of ACM. All work will be done to comply with Federal, State, and local regulations. The work will be protected and sealed by using the capsule concept to assure the least to no particle escape. The concept of "keep it wet" will be used throughout the asbestos removal process.

XIII. WASTE TRANSPORTER #1

Name: Johnny Rodgers

Address: 296B 2nd Ave

City: York

State: AL

Zip: 36925

Contact Person: Bertha Rodgers

Tel: 205-392-9308

WASTE TRANSPORTER #2

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: Kemper County Landfill

Address: 21211 Hwy 16 East

City: Dekalb

State: MS

Zip: 39328

Contact Person: Jimmy Thomas

Tel: 601-743-4310

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:
MDEQ will be immediately notified. The unexpected asbestos will be properly handled in the same way as the original.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Bertha Rodgers
Type or Print Name

Bertha Rodgers
(Signature of Owner/Operator)

2/26/2024
(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Bertha Rodgers
Type or Print Name

Bertha Rodgers
(Signature of Owner/Operator)

2/26/2024
(Date)