

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 10/23/2024	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): R				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: MS Regional 5 Housing Authority				
Address: Medgers Evers Drive (See attached) 109 Medgar Evers Dr				
City: Decatur Decatur		State: MS	Zip: 39327	
Site Location: Unit 109 see attachment			Tel: 601-63-3371	
Building Size: Unknown		# of Floors: Unknown	Age in Years: Unknown	
Present Use: Housing		Prior Use: Unknown		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: MS Regional housing Authority V				
Address: 298 Northside Drive				
City: Newton		State: MS	Zip: 39345	
Contact: Nick Kaminer (General Contractor-601-573-6985)			Tel: 601-683-3371	
ASBESTOS REMOVAL CONTRACTOR: Snyder Environmental & Construction, LLC				
Address: 7705 Northshore Place				
City: North Little Rock		State: AR	Zip: 72118	
Contact: Justin Dixon/Andrew Ables			Tel: 501-801-2776/601-559-2185	
Certification Number: ABC-00009502			Expiration Date: 07/12/2024 05/15/2025	
OTHER OPERATOR: N/A				
Address: N/A				
City: N/A		State: N/A	Zip: N/A	
Contact: N/A			Tel: N/A	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No):				
WAS ASBESTOS PRESENT? (Yes/No): Yes			Inspection Date: 11/20/2023	
Inspector: Lamar Gilliland		Certification Number: ABI-00001036	Expiration Date: 2/7/2025	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:				
PLM Bulk Samples				
VII. QUANTITY OF RACM TO BE REMOVED: 1,024 SF FT/Mastic, 2,080 SF Drywall JC, 162 LF WD Caulk,				
Pipes (LN FT):		Surface Area (SQ FT):	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:				
Category I:			Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 10/21/2024			Complete: 10/24/2024	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: N/A			Complete: N/A	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Materials listed to be removed by hand so facility can be renovated.

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:

Materials will be wetted, during and after abatement, properly packaged, labeled and transported to a class 1 landfill for disposal.

XIII. WASTE TRANSPORTER #1

Name: Complete Environmental & Remediation

Address: 37 David Swan Lane

City: Pervis

State: MS

Zip: 397475

Contact Person: Kevin Ivy

Tel: 601-951-8136

WASTE TRANSPORTER #2

Name: N/A

Address: N/A

City: N/A

State: N/A

Zip: N/A

Contact Person: N/A

Tel: N/A

XIV. WASTE DISPOSAL SITE

Name: Clearview Landfill

Address: 2253 Mudline Road

City: Lake

State: MS

Zip: 39092

Contact Person: N/A

Tel: 866-909-4458

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:

Name: N/A

Title: N/A

Authority: N/A

Date of Order (MM/DD/YY): N/A

Date Ordered to Begin (MM/DD/YY): N/A

XVI. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY): N/A

Description of the sudden unexpected event:

N/A

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

N/A

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

Wet the unexpected, make area safe and notify DEQ..

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Barbara McElroy

Type or Print Name

Barbara McElroy

(Signature of Owner/Operator)

10/23/2024

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Barbara McElroy

Type or Print Name

Barbara McElroy

(Signature of Owner/Operator)

10/23/2024

(Date)

Information for MS Region 5 Housing Authority Abatement NOI

Decatur – we will begin this work on 9/25, and conclude on 9/27

- Medgar Evers Drive, Unit 109
 - 162 LF of exterior perimeter window caulk
 - 370 SF of exterior transite
 - 1,024 SF of 12x12 FT/mastic
 - 2,080 SF of drywall / jc (JC is hot)