

REV

(PT)

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 12/16/2024	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): R= REVISED Building STATUS + DATES				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R= RENOVATION				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: DELTA RESEARCH + EXTENSION CENTER				
Address: 82 Stoneville Rd.				
City: Stoneville		State: MS		Zip: 38776
Site Location: RESEARCH units # 1574 + 1575			Tel: 662-686-3214	
Building Size: 19,332 SF		# of Floors: 3		Age in Years: 40+-
Present Use: VACANT		Prior Use: SOYBEAN RESEARCH LABS		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: MISSISSIPPI STATE UNIVERSITY / DELTA RESEARCH + EXTENSION CENTER				
Address: P.O. BOX 197 / 82 Stoneville Road				
City: STONEVILLE		State: MS		Zip: 38776
Contact: KENNEY PATTON			Tel: 662-686-3214	
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC.				
Address: P.O. BOX 133				
City: DELTA CITY		State: MS		Zip: 39061
Contact: JIMMY BELL			Tel: 662-820-2124	
Certification Number: ABC-00001282			Expiration Date: 12/6/25	
OTHER OPERATOR: MISSISSIPPI STATE UNIVERSITY / DELTA RESEARCH + EXTENSION CENTER				
Address: 82 Stoneville Road				
City: Stoneville		State: MS		Zip: 38776
Contact: KENNEY PATTON			Tel: 662-686-3214	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes				
WAS ASBESTOS PRESENT? (Yes/No): Yes			Inspection Date: 5/29/24	
Inspector: PAUL ANDERSON		Certification Number: ABE00061686		Expiration Date: 5/31/25
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: SAMPLES WERE TAKEN FROM: windows, walls, ceiling, pipe insulation, floor tile/mastic, door puddy. ALL SAMPLES WERE SHIPPED TO EUROFIN, CEI LABS, 730 SE MAYNARD RD., CARY, NC. 27511 SAMPLES WERE ANALYZED USING THE PLM METHOD. THE FLOOR TILE/MASTIC ON 1ST AND 2ND FLOOR CAME BACK POSITIVE FOR ASBESTOS ONLY.				
VII. QUANTITY OF RACM TO BE REMOVED: 17,400 SF NONFRIABLE FLOOR TILE/MASTIC TO BE REMOVED ONLY.				
Pipes (LN FT): 0		Surface Area (SQ FT): 17,400 SF		Volume of Facility Components (CU FT): 0
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 0				
Category I: ✓			Category II:	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 11/2/25			Complete: 1/19/25	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 3/20/25			Complete: 9/20/25	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:
PREP Windows/DOORS/VENTS with 6 mil poly, PLACE SIGNS, NEG-AIR UNITS, D-CON UNIT AT ENTRANCE OF EACH UNIT, USING THE WET METHOD

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: WET REMOVE BAG UNDER NEG-AIR PRESURE TAG BAGS AND LOAD INTO A LINED DUMPSTER.

XIII. WASTE TRANSPORTER #1

Name: W H + D, INC.

Address: P.O. BOX 870

City: LELAND

State: MS

Zip: 38756

Contact Person: Tommy Hendrix

Tel: 662-347-0052

WASTE TRANSPORTER #2 N/A

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: Big RIVER LANDFILL (REPUBLIC SERVICES)

Address: 52 LANDFILL ROAD

City: LELAND

State: MS

Zip: 38756

Contact Person: ALEISHA JOHNSON (SPECIAL WASTE)

Tel: 662-332-7927/601-420-9248

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: N/A

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

Stop work, wet material; continue with NEG-AIR/CONTAINMENT
Contact owner and MDEQ of change. Await MDEQ directions.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell

Type or Print Name

Jimmy Bell
(Signature of Owner/Operator)

12/16/24

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Jimmy Bell

Type or Print Name

Jimmy Bell
(Signature of Owner/Operator)

12/16/24

(Date)