

# MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery	Postmark (mail only)	Date Received: 1/31/2025	File Number: 70731
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):    O = ORIGINAL			
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):    R = RENOVATIONS			
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):			
Bldg. Name: Tupelo Housing Authority    PARK HILL VILLAGE EAST SUBDIVISION			
Address: 701 South CANAL STREET			
City: Tupelo	State: MS	Zip: 38801	
Site Location: 1630 Lockridge Street Unit #1 First Floor only		Tel: 662-842-5122 EXT. 2002	
Building Size: 995 SQ. UNIT	# of Floors: 2	Age in Years: 50 + -	
Present Use: VACANT FOR REPAIRS	Prior Use: SINGLE FAMILY UNITS		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)			
OWNER NAME: Tupelo Housing Authority			
Address: 701 South CANAL STREET			
City: TUPELO	State: MS	Zip: 38801	
Contact: TABITHA SMITH		Tel: 662-842-5122 EXT. 2002	
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC.			
Address: P.O. BOX 133			
City: DELTA CITY	State: MS	Zip: 39061	
Contact: JIMMY BELL		Tel: 662-820-2124	
Certification Number: ABC-00001282	Expiration Date: 12/6/2025		
OTHER OPERATOR: PAGE & SONS CONTRACTORS, INC.			
Address: 374 CR-7000			
City: BOONEVILLE	State: MS	Zip: 38829	
Contact: CLAYTON PAGE		Tel: 662-416-3418	
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES			
WAS ASBESTOS PRESENT? (Yes/No): YES		Inspection Date: AUG. 19 - 26 / 2011	
Inspector: WILLIAM J. YOUNG	Certification Number: ABT-00001688	Expiration Date: 9/24/2011	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: SAMPLES WERE TAKEN FROM: WALLS, CEILING, ROOFING MATERIALS, WINDOWS, DOORS, ATTIC PIPES, INSULATION, FLOOR TILE/MASTIC, PREP AND SHIPPED TO CA LABS, INC. BATON ROUGE, LA. ALL SAMPLES WERE TESTED USING THE PLM METHOD  ( FLOOR TILE ON 2ND FLOOR THRU OUT CONTAIN ASBESTOS. BEDROOMS/BATHROOM.)			
VII. QUANTITY OF RACM TO BE REMOVED: FOUR HUNDRED SF; UPSTAIRS THRU OUT FLOOR TILE			
Pipes (LN FT): 0	Surface Area (SQ FT): 400 SF	Volume of Facility Components (CU FT): 0	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 0			
Category I: <input checked="" type="checkbox"/>		Category II: <input type="checkbox"/>	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 2/13/2025		Complete: 2/14/2025	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 2/16/2025		Complete: 4/15/2025	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:  
Wet Method, Containment, NEG-Air, D-CON units, Independent Air monitoring/Air Clean

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: prep site, signs, limit poly over windows, doors, Air vents, Wet and remove floor tile, Bag, Drop tag, TAPE CLOSE. Remove mastic, solidize mastic, Double Bag, Cleanup, HEPA-VAC corners, PLACE ALL BAGS INTO A Lined Dumpster, Awaiting Air Clean

XIII. WASTE TRANSPORTER #1

Name: Bell Environmental Services, LLC.  
Address: P.O. Box 133  
City: Delta City State: MS Zip: 39061  
Contact Person: Jimmy Bell Tel: 662-920-2124

WASTE TRANSPORTER #2 N/A

Name:  
Address:  
City: State: Zip:  
Contact Person: Tel:

XIV. WASTE DISPOSAL SITE

Name: Three River Landfill  
Address: 1904 Pontotoc Parkway West  
City: Pontotoc State: MS Zip: 38963  
Contact Person: 662-488-0444 Tel: 662-488-0444

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: N/A

Name: Title:  
Authority:  
Date of Order (MM/DD/YY): Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):  
Description of the sudden unexpected event:  
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLER, PULVERIZED, OR REDUCED TO POWDER:  
stop work continue to use NEG-Air and containment. Contact MDEQ/owner of change REVISE NOTIFICATIONS.

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell  
Type or Print Name  
Jimmy Bell  
(Signature of Owner/Operator)  
1/31/2025  
(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT.  
Jimmy Bell  
Type or Print Name  
Jimmy Bell  
(Signature of Owner/Operator)  
1/31/2025  
(Date)