## MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

Mail notification to: MDI					I Al Number II	
MDEQ Use Only: Demail □Mail □Hand Delivery	Postmark (mail only)  Date Re 05/0		05/05	eived / <u>2025</u>	Al Number 37170	
I. Type of Notification (O=Original R=Revised	C=Canceled A=	Annual): O				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): R  III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Bldg 268 floor tile in 2nd floor hallways						
III. FACILITY DESCRIPTION (Include building	name, number ai	nd floor or room numl	<sub>per):</sub> Bld	g 268 floor til	e in 2nd 1100r Hallways	
Bldg Name: Offices						
Address: 108 Simler Blvd, Columbus Air Force		e Base		20710		
City: Columbus		State: MS		Zip: 39710		
Site Location: Bldg 268 Simler Blvd				Tel:		
Building Size: 76,000 sf		# of Floors: 2		Age in Years: >30		
Present Use: Offices and classrooms		Prior Use: Same				
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)						
OWNER NAME: United States Air Fo	orce	<u>-</u>				
Address: 108 Simler Blvd				00740		
<sub>City:</sub> Columbus		State: MS		Zip: 39710		
Contact: Jason Alford				Tel: 601 481 4874		
ASBESTOS REMOVAL CONTRACTOR: En	vironmenta	al Services				
Address: 253 Delk Road				20.404		
City: Hattiesburg		State: MS		Zip: 39401		
Contact: Joe Venus				Tel: 601 408 1005		
Certification Number: ABC-0000133	Expiration Date: 01/06/2025		0/2025			
OTHER OPERATOR: N/A						
Address:		<del></del>				
City:		State:		Zip:		
Contact:			Tel:			
v. was site inspected to determine presence of asbestos? (Yes/No): Yes (Assumed)					0005	
WAS ASBESTOS PRESENT? (Yes/No):		Inspection Date.		2025		
I as Roberts	Log Roberts   Contiguation Number: ABI 0009020   Expiration Date: 001192020					
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:  Flooring materials contains asbestos (Assumed) original inspection was done April 5 2005 with no						
records.						
VII. QUANTITY OF RACM TO BE REMOVE	D:					
Surface Area (SO FT):				Volume of Facility Components (CU FT):		
Pipes (LN F1):						
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REIMOYES.						
Category I: Category II.  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: May 16, 2025  Complete: June 13, 2025						
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: N/A Complete:						
X. SCHEDULED DATES DEMO/RENOVATI	ON (IVIIVIIVII)	, clart.		33.00		

XI. DESCRIPTION OF PLANNED DEMOLITION OR REN	OVATION WORK, AND ME	THOD(S) TO BE USED:				
Removal of floring materials using the v	vet method					
XII DESCRIPTION OF WORK PRACTICES AND ENGINE	ERING CONTROLS TO BE	USED TO PREVENT EMISSIONS OF ASBESTOS AT THE				
DEMOLITION OR RENOVATION SITE:						
Wet materials and remove using hand	10015					
XIII. WASTE TRANSPORTER #1						
Name: Environmental Services						
Address: 253 Delk Road						
<sub>City:</sub> Hattiewsburg	State: MS	Zip: 39401				
Contact Person: Joe Venus  Tel: 601 408 1005						
WASTE TRANSPORTER #2 N/A						
Name:						
Address:						
City:	State:	Zip:				
Contact Person:		Tel:				
XIV. WASTE DISPOSAL SITE						
Name: Robo Landfill						
Address: 6447 Walalak Rd						
City: Scooba	State: MS	z <sub>ip:</sub> 39358				
Contact Person: Mr Roland Tel: 662 793 4795						
XV. IF DEMOLITION ORDERED BY A GOVERNMENT	AGENCY, PLEASE IDENTIF	Y THE AGENCY BELOW:				
Name: N/A		Title:				
Date of Order (MM/DD/YY):	Authority:  Date Ordered to Begin (MM/DD/YY):					
XVI. FOR EMERGENCY RENOVATIONS: N/A						
Date and Hour of Emergency (MM/DD/YY):						
Date and Hour of Emergency (MM/DD/11).  Description of the sudden unexpected event:						
Explanation of how the event caused unsafe conditions	or would cause equipment da	mage or an unreasonable financial burden:				
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLO NONFRIABLE ASTESTOS MATERIAL BECOMES CR	OWED IN THE EVENT THAT	UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY R REDUCED TO POWDER:				
NONFRIABLE ASTESTOS MATERIAL BECOMES CR Stop work call DEQ	UMBLED, FULVERIZED, O	····				
·						
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN	THE PROVISIONS OF THIS	REGULATION (40 CFR PART 61, SUBPART M) WILL BE				
ONSITE DURING THE DEMOLITION OR RENOVATION THIS PERSON WILL BE AVAILABLE FOR INSPECTION						
Joe Venus		5/5/25				
Type or Print Name	(Signature of Owner/O	Operator) (Date)				
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS	CORRECT:	- 5/5/25				
Joe Venus						
Type or Print Name	(Signature of Owner/0	oppiaioi) (2012)				