

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 5/19/2025	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): O = original				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D = Demo				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):				
Bldg. Name: SWEET HOME MB Church				
Address: 480 SWEET HOME ROAD 33.08117278777712, -90.79494244364406				
City: DELTA City	State: MS	Zip: 39061		
Site Location: 480 SWEET HOME Rd., DELTA City, MS		Tel:		
Building Size: 1600 SF	# of Floors: 1	Age in Years: 80 +		
Present Use: VACANT	Prior Use: PLACE OF worship			
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: SWEET HOME Church MEMBERSHIP BOARD				
Address: 480 SWEET HOME Rd.				
City: DELTA City	State: MS	Zip: 39061		
Contact: VERA BROWN, ANITA G. BELL		Tel: 662-873-1885		
ASBESTOS REMOVAL CONTRACTOR: BELL ENVIRONMENTAL SERVICES, LLC.				
Address: P.O. BOX 133				
City: DELTA City	State: MS	Zip: 39061		
Contact: Jimmy Bell		Tel: 662-820-2124		
Certification Number: ABC-00001282	Expiration Date: 12/15/25			
OTHER OPERATOR: H. B. Trucking services				
Address: P.O. BOX 205				
City: DELTA City	State: MS	Zip: 39061		
Contact: Herbert Bell JR.		Tel: 662-873-3606		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): YES Complete Inspection				
WAS ASBESTOS PRESENT? (Yes/No): YES		Inspection Date: 5/6/25		
Inspector: PAUL ANDERSON	Certification Number: ABI-00001686	Expiration Date: 5/31/25		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: SAMPLES WERE TAKEN FROM: ROOF/FLASHING/INSULATION/DRY WALL/CEILING/windows CAULKING siding EXTERIOR/siding UNDERNATH outter siding. THE SAMPLES WERE COLLECTED AND PROCESS SHIPPED TO EUROFIN'S BUILT ENVIRONMENT TESTING EAST, LLC., CARY NORTH CAROLINA TESTED FOR ASBESTOS USING THE PLM METHOD THE INNER WALL siding CONTAINED TRANSITE siding (900 SF)				
VII. QUANTITY OF RACM TO BE REMOVED: 2ND INNER WALL siding TRANSITE siding 900 SF				
Pipes (LN FT): 0	Surface Area (SQ FT): 900 SF	Volume of Facility Components (CU FT): 0		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 0				
Category I: ✓	Category II:			
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 6/3/25		Complete: 6/5/25		
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 6/8/25		Complete: 7/8/25		

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:
Wet Method, Trackhoe 6 mil poly 6 mil Bags.

XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: CLEAN UP AROUND Building - over grown weeds. Wet And Remove Siding ONTO 6 mil poly USING TRACKHOE TO REMOVE WALLS TO GROUND intact. Wet And Remove Siding ON THE GROUND. PLACE BAGS INTO A Lined Dumpster

XIII. WASTE TRANSPORTER #1

Name: BELL ENVIRONMENTAL SERVICES, LLC.

Address: P.O. BOX 133

City: Delta City

State: MS

Zip: 39061

Contact Person: Jimmy Bell

Tel: 662-820-2124

WASTE TRANSPORTER #2 N/A

Name:

Address:

City:

State:

Zip:

Contact Person:

Tel:

XIV. WASTE DISPOSAL SITE

Name: Big RIVER LANDFILL (REPUBLIC SERVICES)

Address: 52 LANDFILL RD.

City: LELAND

State: MS

Zip: 38756

Contact Person: Willie Christen

Tel: 662-332-7927

XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW: N/A

Name:

Title:

Authority:

Date of Order (MM/DD/YY):

Date Ordered to Begin (MM/DD/YY):

XVI. FOR EMERGENCY RENOVATIONS: N/A

Date and Hour of Emergency (MM/DD/YY):

Description of the sudden unexpected event:

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:

stop all work, Contact church members/ MDEQ of charge, Follow MDEQ Directions

XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.

Jimmy Bell

Type or Print Name

(Signature of Owner/Operator)

5/20/25

(Date)

XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Jimmy Bell

Type or Print Name

(Signature of Owner/Operator)

5/20/25

(Date)



4.1A

480 SWEET HOME ROAD - Delta City, MS

480 SWEET HOME ROAD
SWEET HOME MB Church

