## MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: ☑Email □Mail □Hand Delivery	Postmark (ma	il only)	Date Received 5/21/2025		Al Number		
I. Type of Notification (O=Original R=Revised	C=Canceled A=	- Annual): Original					
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): Renovation							
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): South Side Elementary School							
Bidg. Name: Classroom s-12							
Address: 237 Louis Odneal Rd							
City: West Point		State: MS		Zip: 39773			
Site Location: Interior Classroom S-12				Tel: (662) 495-6216			
Building Size: unknown		# of Floors: 1		Age in Years: 50 +/-			
Present Use: Classroom	Present Use: Classroom		Prior Use: Classroom				
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)							
OWNER NAME: West Point Consolidated School District							
Address: 359 Commerce St							
City: West Point		State: MS		z <sub>ip:</sub> 39773			
Contact: Ricky Melton				Tel: 662-494-4242			
ASBESTOS REMOVAL CONTRACTOR: Specialty Abatement Services, Inc.							
Address: P.O. Box 343012							
City: Memphis	is State:		State: TN z		Zip: 38184-3012		
Contact: William Stamps			Tel: 901-507-1203				
Certification Number: ABC00001660		Expiratio		on Date: 02/27/2026 02/07/2026			
OTHER OPERATOR: n/a							
Address:							
City:	-	State:		Zīp:			
Contact:				Tel:			
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes							
WAS ASBESTOS PRESENT? (Yes/No): Yes		Inspection Date: 05/05/2025			25		
Inspector: Willie Nester	Certification Number: ABI-00002244		02244	Expiration	Date: 01/09/2026		
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Floor Tile & Mastic, Bulk sampling using PLM methods							
Thou The & Mastie, built sampling using FEW Methods							
VII. QUANTITY OF RACM TO BE REMOVED: 680 sqft VAT, 680 sqft Mastic							
I		face Area (SQ FT): 680sf/680sf Volume of Facility Components (CU FT): n/a					
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: n/a							
Category I: n/a  Category II: n/a							
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 06/04/2025 Complete: 06/06/2025							
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 06/04/2025 Complete: 06/06/2025							

Removal of ACM using hand tools and we		)(S) TO BE USED:				
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERI DEMOLITION OR RENOVATION SITE: Containment as required, negative pressur						
XIII. WASTE TRANSPORTER #1 SASI			bio bag wac.c			
Name: SASI Memphis	destination and the second and the s	•				
Address: 4009 Broadway Rd	**************************************	***************************************				
<sub>City:</sub> Bartlett	State: TN	Zip: 38135	**************************************			
Contact Person: Dwight Grayson	<b>*</b>	Tel: 901-507-1203				
WASTE TRANSPORTER #2 L&T Services LLC						
Name: L&T Services LLC .						
Address: 2170 Highway 51						
<sub>City:</sub> Hernando	State: MS	Zip: 38632				
Contact Person: Carlton Gibson		Tel: 662-429-7335				
XIV. WASTE DISPOSAL SITE WM The Tunica Landfill						
Name: WM The Tunica Landfill						
Address: 6035 Bowdre Rd		1.00-101-00-00-00-00-00-00-00-00-00-00-00-				
City: Robinsonville	State: MS	Zip:				
Contact Person: Carlton Gibson	<u> </u>	Tel: 901-331-7187				
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:						
Name: n/a	Title:		8			
Authority: n/a						
Date of Order (MM/DD/YY): n/a	Date Ordered t	o Begin (MM/DD/YY):				
XVI. FOR EMERGENCY RENOVATIONS: <sup>11/a</sup>						
Date and Hour of Emergency (MM/DD/YY): n/a						
Description of the sudden unexpected event:  n/a						
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: n/a						
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER: All work will cease, workers will be removed from site, MDEQ will be called for an inspection						
All Work will cease, workers will be remove	d from site, widey v	VIII de called for a	in inspection			
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.						
William Stamps	Ittshop		05/21/2025			
Type or Print Name	(Signature of Owned Operator)	1	(Date)			
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:  Dwight Grayson  05/21/2025						
Type or Print Name	(Signature of Owner/Operator)		(Date)			