

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only:	Postmark (mail only)	Date Rec	ceived Al Number				
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual):							
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): D							
III. FACILITY DESCRIPTION (Include building name, number and floor or room number):							
Bldg. Name: Warehouse							
Address: 237 Hwy 72							
_{City:} Burnsville	State: MS		_{Zip:} 38833				
Site Location: 4 Spaces in Warehouse - 237 Hwy 72, Burnsville, MS		S	Tel: 256-734-2114				
Building Size: Appx 30,000 sq ft	# of Floors: 2		Age in Years: 50+				
Present Use: Vacant	Prior Use: Storag	je Facilit	ty				
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)							
OWNER NAME: Dale Bright							
Address: 508 1st Ave SE	S		ensid rod that a spice and				
City: Cullman	State: AL		Zip: 35055				
Contact: Chad Rankin			Tel: 662-871-0082				
ASBESTOS REMOVAL CONTRACTOR: EAC E	nvironmental		Under Section 1997 House				
Address: 4546 Cal Steens Road	Riving Revo	-	20,022,00				
_{City:} Caledonia	City: Caledonia State: MS		_{Zip:} 39740				
Contact: Ed Clay			Tel: 662-386-6386				
Certification Number: ABC 00005192 Expirat			_{n Date:} 11-05-23				
OTHER OPERATOR: Hodges Construction							
Address: 1281 CR 811							
City: Saltillo	State: MS		Zip: 38866				
Contact: Chad Rankin			Tel: 662-871-0082				
V. WAS SITE INSPECTED TO DETERMINE PRE	SENCE OF ASBESTOS? (Yes/No		trigito Psustramenti recinste a rita initigaciando				
WAS ASBESTOS PRESENT? (Yes/No): Yes	SBESTOS PRESENT? (Yes/No): Yes Inspecti		on Date: 09-12-22				
Inspector: Taliesen M Partridge	Certification Number: ABI-0001	11381	Expiration Date: 01-21-23				
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Roofing, Drywall, Cove Base, Floor Tile, and Mastic Analyzed by PLM							
VII. QUANTITY OF RACM TO BE REMOVED:		a sall all	IT MERONIAS . NEI CANDONIAS TAMP VII 1805 I 1805				
Pipes (LN FT): Su	urface Area (SQ FT): 2,900 Vinyl, M	lastic V	olume of Facility Components (CU FT):				
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:							
Category I: Category II:							
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 03-10-23 Complete: 03-11-23							
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 03-13-23 Complete: 03-27-23							

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:						
Post ACM Removal, Demolition will be performed using heavy equipment						
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:						
Contain Work Area, Air Scrubbers, Airless Sprayer w/ Surfactant, Wet Removal, Double Bag in 6mil poly						
· · · · · · · · · · · · · · · · · · ·		,				
XIII. WASTE TRANSPORTER #1						
Name: EAC Environmental						
Address: 4546 Cal Steens Road						
City: Caledonia	State: MS		Zip: 39740			
Contact Person: Ed Clay			Tel: 662-386-6386			
WASTE TRANSPORTER#2						
Name: Waste Pro						
Address: 1600 12th Avenue South						
City: Columbus	State: MS		Zip: 39701			
Contact Person: RuthAnn Faris			Tel: 662-328-5528			
XIV. WASTE DISPOSAL SITE						
Name: RoBo Landfill						
Address: 6447 Wahalak Road						
City: Scooba	State: MS		Zip: 39358			
Contact Person: Roland Edmonds			Tel: 662-793-4795			
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:						
Name:		Title:				
Authority:						
Date of Order (MM/DD/YY):		ate Ordered to	Begin (MM/DD/YY):			
XVI. FOR EMERGENCY RENOVATIONS:						
Date and Hour of Emergency (MM/DD/YY):						
Description of the sudden unexpected event:						
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:						
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER:						
Contain material, notify owner and MDEQ						
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.						
Edward A. Clay	_ Edward A. Clay		02-27-23			
Type or Print Name	(Signature of Ow	rner/Operator)	(Date)			
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECTED BY THE CONTROL OF THE CONT	CT: Edwne	L A. Clay	02-27-23			
Type or Print Name	(Signature of Ov	vner/Operator)	(Date)			