## MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only:	☐Hand Delivery	Postmark (mai	l only)	Date Received 3-24-23		Al Number		
I. Type of Notification (O	Type of Notification (O=Original R=Revised C=Canceled A= Annual):							
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation):								
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): Medical Facility								
Bldg. Name: Tutwiler Clinic								
Address: 205 Alma Street								
City: Tutwiler		State: MS		zip: 38963				
Site Location: 1st Floor from Hall 4 to Hall 5					Tel: 662-345-3152			
Building Size: Unknown		# of Floors: 1		Age in Years: Unknown				
Present Use: Medical	Present Use: Medical Facility		Prior Use:					
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)								
OWNER NAME: Tallahatchie General Hospital								
Address: 141 Dr. T.T. Lewis Circle								
City: Charleston			State: MS		<sub>Zip:</sub> 38921			
Contact: Bryan Douglas					Tel: 662-647-4866			
ASBESTOS REMOVAL CONTRACTOR: Snyder Environmental								
Address: 7705 Northshore Place								
City: North Little Rock		State: AR		<sub>Zip:</sub> 72118				
Contact: Andrew Ables					<sub>Tel:</sub> 601-559-2185			
Certification Number: ABC00009502			Expiration		n Date: 9/30/2023			
OTHER OPERATOR: N/A								
Address:								
City:		State:		Zip:				
Contact:					Tel:			
v. was site inspected to determine presence of asbestos? (Yes/No): Yes								
WAS ASBESTOS PRESENT? (Yes/No): Yes				Inspection Date: 3/22/2023				
Inspector: Andrew Ables   Certification Number: ABI00010682   Expiration Date: 10/25/2023								
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Assumed Inspection by Andrew Ables								
9x9 floor tile and mastic - 1st Floor								
VII. QUANTITY OF RACM TO BE REMOVED: 1,400 SF of 9x9 floor tile and mastic								
Pipes (LN FT): Surface Area (SQ FT): Volume of Facility Components (CU FT):						mponents (CU F1):		
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED:								
Category I: Category II:  IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 3/27/2023 Complete: 3/29/2023								
x. scheduled dates demo/renovation (MM/DD/YY) Start: N/A  Complete: N/A								
A. SCHEDULED DATES DEMOVEROVATION (MM/DD/TT) Start: Complete: "" Complete: ""								

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:  Materials listed above will be removed by hand so facility can be restorated and renovated.								
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:  Materials will be adequately wetted before/during/after abatement, properly packaged, labeled, and transported to a certified landfill								
XIII. WASTE TRANSPORTER #1								
Name: Henderson Waste & Recycling Co								
Address: 71001 US 82 West								
City: Greenwood	State: MS		Zip: 38930					
Contact Person: Bobby Henderson			Tel: 662-299-8069					
WASTE TRANSPORTER #2 N/A								
Name:								
Address:								
City:	State:		Zip:					
ntact Person:			Tel:					
XIV. WASTE DISPOSAL SITE								
Name: Leflore County Sanitary Landfill								
Address: 15200 US Hwy 49 East								
City: Sidon	State: MS		<sub>Zip:</sub> 38935					
Contact Person: Troy Thompson			Tel: 662-385-5483					
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:								
Name: N/A Title:								
Authority:								
Date of Order (MM/DD/YY):  Date Ordered to Begin (MM/DD/YY):								
XVI. FOR EMERGENCY RENOVATIONS:								
Date and Hour of Emergency (MM/DD/YY): Unknown - Restoration company reached out on 3/22								
Description of the sudden unexpected event:  The medical facility recently had some pipes freeze then burst into this portion of the medical clinic. Over half the facility is shut down due to this event.								
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:  Over half the facility is shut down due to the flooding and damage.								
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER: Halt work, wet the unexpected, make safe the area, treat everything as ACM, and notify MDEQ.								
i lait work, wet the unexpected, make sale the alea, treat everything as ACIVI, and noting MDEQ.								
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.								
		rew Ables		3/24/2023				
Type or Print Name	(Signature of O	wner/Operator)		(Date)				
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:  Andrew Ables  3/24/2023								
Type or Print Name (Signature of Owner.			- · · · · · · ·	(Date)				