



MAP

MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail <input type="checkbox"/> Hand Delivery		Postmark (mail only)	Date Received 5-1-23	AI Number
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): <input type="radio"/>				
II. TYPE OF OPERATION (D=Demo O= Ordered Demo R=Renovation E=Emer. Renovation): <input type="radio"/> D				
III. FACILITY DESCRIPTION (Include building name, number and floor or room number): GYM DEMOLITION				
Bldg. Name: McCarthy GYMNASIUM				
Address: 216 MCCARTHY GYM				
City: MS STATE		State: MS	Zip: 39762	
Site Location: Mississippi State University			Tel: 662-325-2323	
Building Size: 35000 SF		# of Floors: 2	Age in Years: 50+ yrs	
Present Use: Educational Facility		Prior Use: Educational Facility		
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)				
OWNER NAME: Mississippi State University				
Address: 75 B. S. Hood Rd				
City: Mississippi State		State: MS	Zip: 39762	
Contact: CHRIS PULLIAM		Tel: 662-312-7764		
ASBESTOS REMOVAL CONTRACTOR: MAK ENVIRONMENTAL LLC				
Address: 17115 FINNELL RD				
City: NORTHPORT		State: AL	Zip: 35175	
Contact: PATRICK HENDON		Tel: 205-410-1995		
Certification Number: ABC-00007308			Expiration Date: 1/13/2024	
OTHER OPERATOR: NA				
Address:				
City:		State:	Zip:	
Contact:		Tel:		
V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): Yes				
WAS ASBESTOS PRESENT? (Yes/No): Yes			Inspection Date: 1/11/2023	
Inspector: EDWARD CLAY		Certification Number: ABI-00006706	Expiration Date: 6/23/2023	
VI. SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Samples were analyzed using PLM. SAMPLES INCLUDED TSI (525LF) ROOF SEALANT(10LF) ACM COATING ON METAL SIDING (6000SF), VAT/MASTIC 1500SF) SAFE DOOR IS ASSUMED ACM				
VII. QUANTITY OF RACM TO BE REMOVED: 525LF TSI PIPE INSULATION				
Pipes (LN FT): 525		Surface Area (SQ FT):	Volume of Facility Components (CU FT):	
VIII. QUANTITY OF NONFRIABLE ASBESTOS NOT REMOVED: 7500				
Category I: None			Category II: None	
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 5/17/2023			Complete: 6/17/2023	
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 5/26/2023			Complete: 6/30/2023	

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED: <small>NON-FRIABLE SIDING, FLOOR TILE AND MASTIC WILL BE REMOVED MECHANICALLY AND WET METHOD FRIABLE TSI WILL BE REMOVED BY GLOVE BAG AND WET METHOD - DEMO CONTRACTOR IS GOING TO MAKE US AN OPENING SO WE CAN GET A BOOM LIFT IN THE GYM TO WORK FROM.</small>		
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: Work will be performed within a negative pressure HEPA filtered containment. Material will be kept wet constantly with amended water and airless sprayer. Material will be double bagged with 6 mil bags.		
XIII. WASTE TRANSPORTER #1		
Name: LIBERTY WASTE		
Address: 50 SEARS DR.		
City: STARKVILLE	State: AL	Zip: 39759
Contact Person: CHRIS THOMAS	Tel: 662-312-4224	
WASTE TRANSPORTER #2		
Name:		
Address:		
City:	State:	Zip:
Contact Person:	Tel:	
XIV. WASTE DISPOSAL SITE		
Name: ROBO ASBESTOS LANDFILL		
Address: 6447 WAHALAK RD		
City: SCOوبا	State: MS	Zip: 39358
Contact Person: ROLAND EDMONDS	Tel: 800-248-2990	
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY THE AGENCY BELOW:		
Name:		Title:
Authority:		
Date of Order (MM/DD/YY):		Date Ordered to Begin (MM/DD/YY):
XVI. FOR EMERGENCY RENOVATIONS:		
Date and Hour of Emergency (MM/DD/YY):		
Description of the sudden unexpected event:		
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:		
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER: <small>STOP WORK AND NOTIFY OWNER FOR NEWLY DISCOVERED ACM MATERIAL WILL BE KEPT WET WHILE CONTAINMENT IS EXPANDED. MATERIAL WILL BE TESTED AND IF ADDITIONAL ACM IS PRESENT, THE NOTIFICATION WILL BE REVISED TO INCLUDE THE NEW MATERIAL. ALL WORK WILL BE PERFORMED WITHIN A NEGATIVE PRESSURE HEPA FILTERED CONTAINMENT.</small>		
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ONSITE DURING THE DEMOLITION OR RENOVATION, AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS.		
PATRICK HENDON <small>Type or Print Name</small>	 <small>(Signature of Owner/Operator)</small>	4/28/2023 <small>(Date)</small>
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:		
PATRICK HENDON <small>Type or Print Name</small>	 <small>(Signature of Owner/Operator)</small>	4/28/2023 <small>(Date)</small>