MISSISSIPPI ASBESTOS DEMOLITION/RENOVATION NOTIFICATION FORM MAP

Mail notification to: MDEQ Asbestos and Lead Branch, 515 E. Amite Street, Jackson, MS 39201

MDEQ Use Only: XEmail □Mail □Hand Delivery	Postmark (mail only)	Date Received 09-11-2023	Al Number 70371			
I. Type of Notification (O=Original R=Revised C=Canceled A= Annual): O = Oyig inac						
II. TYPE OF OPERATION (D=Demo O= Ordered	d Demo R=Renovation E=Emer. Re		ouoitavou			
III. FACILITY DESCRIPTION (Include building na	ame, number and floor or room num	nber):				
Bldg. Name: South CANAL Street S	ubdivision					
Address: 901 South CANAL Str	eet					
City: Tupelo	State: MS	Zip: 38801				
Site Location: 1620 Forbes Street, Fupelo, ms		Tel: 663 4	Tel: 663 446 - 3418			
Building Size: 900 St.	# of Floors: 2	# of Floors: 2 Age in Years: 40 t -				
Present Use: VACANT FUY REPAIRS	Prior Use: Sing	Prior Use: Single family 2 bedroom unit				
IV. FACILITY INFORMATION (Identify owner, asbestos removal contractor, and other operator)						
OWNER NAME: Tupels Housing A	uthoch					
OWNER NAME: Tupelo Housing Authority Address: 701 South CANA(Street						
City: Tupolo	State: M5	Zip: 3880	Zip: 38801			
Contact: Tabitha Smith			Tel: 662-842-5122 EXT. 2002			
ASBESTOS REMOVAL CONTRACTOR: BELL ENUIVON MENTAL SETVICES, LLC						
Address: RO	. Box 133					
City: DELLA CITY	State: M5	Zip: 3 906	Zip: 3 9061			
Contact: Jimmy Bell		Tel: 662-	Tel: 662-820-2124			
Certification Number: ABC-00001	2,82	Expiration Date: 1/5/	2024			
OTHER OPERATOR: PACE & SONS CONSTRUCTION, INC.						
Address: 374 CR - 7000						
City: BOONEVILLE	State: MS	Zip: 38829	Zip: 38829			
Contact: CLAY+OH PACE Tel: 462-416-3418		16-3418				
V. WAS SITE INSPECTED TO DETERMINE PRE	V. WAS SITE INSPECTED TO DETERMINE PRESENCE OF ASBESTOS? (Yes/No): yes					
WAS ASBESTOS PRESENT? (Yes/No): yes Inspection Date: Aug., 19, 2011						
Inspector: William J. Young Certification Number: ABI-00001688 Expiration Date: 9/24/2011 VI SUSPECT MATERIALS SAMPLED AND PROCEDURES USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:						
Samples collected from! Walls, Ceiling, Attil Tusulation, Rood Materials, Floor Tile/Mastic, Windows, All Samples Shipped To The LA Labs, Inc., Baton Rouge, LA where Tested using _ The Plm method. The Floor Tile/Mastic Samples Contain Asbestus.						
VII. QUANTITY OF RACM TO BE REMOVED:		loor Tile Importic				
Pipes (LN FT): & Si	urface Area (SQ FT): 400		Components (CU FT):			
VIII. QUANTITY OF NONFRIABLE ASBESTOS	^	, same of a solid v				
Category I: Category II:						
IX. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY) Start: 9/25/23 Complete: 9/27/23						
X. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY) Start: 9/28/3	2.3 Complete	e: 12/16/23			

XI. DESCRIPTION OF PLANNED DEMOLITION OR RENO WET METHOD, CONTAINMET, NEG-AIC, INDE	VATION WORK, AND	METHOD(S) TO BE USED:	.b/# 2 -	
1000	peantar in Thom	TWINIT CLEATHING, WO	3A91 TA98.	
XII. DESCRIPTION OF WORK PRACTICES AND ENGINEED DEMOLITION OR RENOVATION SITE: PLACE SIGNED TILE JUST PLACE TIE INTO DOUBLE BATE FOR USING FIDER FLOC, AWAIT AIR CLEAR	14 ENTERNOES 15 REMOVE M	, REMOVE KICK BOArds Astic, Double BAq, Cli	, Wet And Remove Enwup, Hepavac.	
XIII. WASTE TRANSPORTER #1	PLA	ce Bags into lined	Trailer Dump, Trang.	
Name: BELL EDUITOUMENTAL SERVICE	£ 110			
Address: P.D. 130x 133	3, 220,	and the same of th		
City: Delta Lity	State: MS	7: 700//		
Contact Person. Timmy Bell	State. 773	Zip: 39064 Tel: 662-826	21911	
WASTE TRANSPORTER #2 &/M	**************************************	1ei. 800 - 800) - 21 24	
Name:				
Address:	1			
City:	State:	Zip:	1, - × ×	
Contact Person:		Tel:		
XIV. WASTE DISPOSAL SITE				
Name: Letlore County Landfill	una de la composición dela composición de la composición dela composición de la composición de la composición de la comp	The second secon		
Address: 15200 US May 49 5 South		: :		
City: 5.dow	State: M5	Zip: 38954		
Contact Person: MABEL Brown		Tel: 662-45	5-6477	
XV. IF DEMOLITION ORDERED BY A GOVERNMENT AGE	NCY, PLEASE IDENTI		N/A	
Name: Title:				
Authority:				
Date of Order (MM/DD/YY): Date Ordered to Begin (MM/DD/YY):				
XVI. FOR EMERGENCY RENOVATIONS: N/A				
Date and Hour of Emergency (MM/DD/YY):				
Description of the sudden unexpected event:				
Explanation of how the event caused unsafe conditions or wou	ıld cause equipment da	mage or an unreasonable financi	al burden:	
XVII. DESCRIPTION OF PROCEDURES TO BE FOLLOWED NONFRIABLE ASTESTOS MATERIAL BECOMES CRUMBL CONTINUE CO	ED, PULVERIZED, OF	REDUCED TO POWDER.		
MDEQ Directions. Resend Revised No	otification.	,		
XVIII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE P ONSITE DURING THE DEMOLITION OR RENOVATION, AN THIS PERSON WILL BE AVAILABLE FOR INSPECTION DU	D EVIDENCE THAT TH	IE REQUIRED TRAINING HAS I	I, SUBPART M) WILL BE BEEN ACCOMPLISHED BY	
Jimmy Bell		Bu	9/11/23	
Type or Print Name	(Signature of Owner/Op	erator)	(Date)	
XIX. I CERTIFY THAT THE ABOVE INFORMATION IS CORR	RECT:	JOA A o	9/11/23	
Type or Print Name	(Signature of Owner/Operator)		(Date)	
			170 (5)	